Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resource	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		WELL API NO. 30-025-30288
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE ☑ FEE □
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No. 034417
87505 SUNDRY NOT	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	DSALS TO DRILL OR TO DEEPEN P P ARK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	WEST DOLLARHIDE QUEEN SAND
1. Type of Well: Oil Well		8. Well Number 126
2. Name of Operator RAM ENERGY LLC	RECEIVE	9. OGRID Number 309777
3. Address of Operator		10. Pool name or Wildcat
2100 S. UTICA AVE., SUITE	175, TULSA, OK 74114	DOLLARHIDE QUEEN (018810)
4. Well Location		
Unit LetterN8	70feet from theSOUTH line and	1980feet from theWEST_line
Section 32		88E NMPM LEA County
	11. Elevation (Show whether DR, RKB, RT, GR	, etc.)
	3155' GR	
12 Charle	Appropriate Box to Indicate Nature of No	ing Papart or Other Data
12. Cleck	Appropriate Box to indicate Nature of No.	ice, Report of Other Data
NOTICE OF I		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	<u> </u>
TEMPORARILY ABANDON DULL OR ALTER CASING	·	E DRILLING OPNS. P AND A
DOWNHOLE COMMINGLE		MENI JOB []
OTHER:	OTHER:	
	pleted operations. (Clearly state all pertinent detail ork). SEE RULE 19.15.7.14 NMAC. For Multiple	s, and give pertinent dates, including estimated date
proposed completion or re		e Completions. Attach wendore diagram of
1. NOTIFY NMOCD 24 HR	S. BEFORE MIRU.	
2. MIRU. ND WH, NU BOP		
2 TAC CIDD@25001 CDCT		See Attached
	20SX OF CLASS "C" CEMENT FROM 3500'-3	See Attached
4. CIRCULATE 9.5 PPG MI	LF AND TEST CASING.	Conditions of Approval
 CIRCULATE 9.5 PPG MI SPOT 35SX OF CLASS " 		Conditions of Approval
 4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY (Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE).
 CIRCULATE 9.5 PPG MI SPOT 35SX OF CLASS " SPOT 25SX OF CLASS " SPOT 55SX OF CLASS " CUTOFF WELLHEAD, A 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE).
 4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY (Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE).
 CIRCULATE 9.5 PPG MI SPOT 35SX OF CLASS " SPOT 25SX OF CLASS " SPOT 55SX OF CLASS " CUTOFF WELLHEAD, A RECLAMATION. 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY (Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR
 CIRCULATE 9.5 PPG MI SPOT 35SX OF CLASS " SPOT 25SX OF CLASS " SPOT 55SX OF CLASS " CUTOFF WELLHEAD, A RECLAMATION. 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C ANCHORS 3' BELOW SURFACE AND INSTAL	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR
 4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINS 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C NCHORS 3' BELOW SURFACE AND INSTAL	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR
 CIRCULATE 9.5 PPG MI SPOT 35SX OF CLASS " SPOT 25SX OF CLASS " SPOT 55SX OF CLASS " CUTOFF WELLHEAD, A RECLAMATION. 	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C ANCHORS 3' BELOW SURFACE AND INSTAL	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAIN	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C NCHORS 3' BELOW SURFACE AND INSTAL	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINS Spud Date:	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C NCHORS 3' BELOW SURFACE AND INSTAL	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR SS.
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINANCE Spud Date:	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY C ANCHORS 3' BELOW SURFACE AND INSTAL INMENT SYSTEM WILL BE USED FOR FLUID Rig Release Date:	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR SS.
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINANCE Spud Date:	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY CANCHORS 3' BELOW SURFACE AND INSTAL INMENT SYSTEM WILL BE USED FOR FLUID Rig Release Date:	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR PS.
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINANCE Spud Date:	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY CANCHORS 3' BELOW SURFACE AND INSTAL INMENT SYSTEM WILL BE USED FOR FLUID Rig Release Date:	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR OS.
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINANCE Spud Date: I hereby certify that the information	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY CANCHORS 3' BELOW SURFACE AND INSTAL INMENT SYSTEM WILL BE USED FOR FLUID Rig Release Date:	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR SS. Vledge and belief. MANAGERDATE11/25/19
4. CIRCULATE 9.5 PPG MI 5. SPOT 35SX OF CLASS " 6. SPOT 25SX OF CLASS " 7. SPOT 55SX OF CLASS " 8. CUTOFF WELLHEAD, A RECLAMATION. CLOSED LOOP CONTAINA Spud Date: I hereby certify that the information SIGNATURE Type or print name MATTHEW PA	LF AND TEST CASING. C" CEMENT FROM 2725'-2405'. WOC&TAG. (C" CEMENT FROM 1250'-1100'. WOC&TAG. (C" CEMENT FROM 466'-SURFACE. VERIFY CANCHORS 3' BELOW SURFACE AND INSTAL INMENT SYSTEM WILL BE USED FOR FLUID Rig Release Date: Above is true and complete to the best of my known	Conditions of Approval YATES/B.SALT) T.SALT) EMENT TO SURFACE. (FW/SHOE/SURFACE). L DRYHOLE MARKER. TURN OVER FOR SS. Vledge and belief. MANAGERDATE11/25/19

خر

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #126

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	Q	By: LEE R. By: IDE QUEEN SAND UNIT BUEEN B	Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions:	126 30-025-30288 N Sec. 24S-T38E OGRID:	32
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 416' 250 YES SURFACE 12-1/4"				
FORMATION T.Salt B. Salt	1200' EST. 2505' EST.				
Intermediate Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	e Casing 5-1/2" 15.5# 3900' 850 YES SURFACE 7-7/8"			P@3500' een: 3590'-3740'(OA)	

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #126

Created:	11/25/19	By: LEE R.	_	Well #:	126			
Updated:		Ву:	_	API		30-025-30288		
Lease:		DE QUEEN SAND UNIT	_	Unit Ltr.:	N	Sec.	32	
Field:	QI	UEEN		TSHP/Rng:	:	24S-T38E		
Surf. Loc.:	870' FSL	& 1980' FWL	_ _	Pool Code:		OGRID:	309777	
Bot. Loc.:			-					
County:	LEA	St.: NM	-	Directions:				
Status:			_					
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 416' 250 YES SURFACE 12-1/4"		MLF			F CMT FROM 4 SHOE/SURFAC	166'-SURFACE. CE)	
FORMATION T.Salt B. Salt Intermediate Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC:	1200' EST. 2505' EST.		MLF	S W T. F. C	POT 35SX OVOC&TAG. IAG CIBP@3500'-	(T.SALT) OF CMT FROM (YATES/B.SA 3500' . SPOT 3250'.	20SX OF CMT	
Hole Size:	7-7/8"	_						
_								

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.