## State of New Mexico **Energy Minerals and Natural Resources**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No.

|                     | \PPLICATION FOR EXCEPTION  | N TO NO EL ADE D   | (For Division Use Only                       |
|---------------------|--|--|--|
| <i>F</i>            |  |  | HOBBS OCD                                    |
| Α.                  | ApplicantSteward Energy II, LLC,   |  | DEC <b>31</b> 2019                           |
|                     | whose address is2600 N. Dallas Pkwy, Suite 400   Frisco, TX 75034,   |  | RECEIVED                                     |
|                     | hereby requests an exception to Rule 19.15.18.12 for   |  |  |
|                     | March 31, Yr 2020, for the following described tank battery (or LACT):   |  |  |
|                     | Name of Lease  | Name of Pool   | Bronco San Andres South                      |
|                     | Location of Battery: Unit Letter  DOGBAR IN FEE  Number of wells producing into battery  | Section 11 Township # /# 30-025-42873; AP# 30-025-42875; AP# 30-025-4285** | 14S Range 38E  H 025-42121; AP# 30-025-42622 |
| В.                  | Based upon oil production of   |  |  |
|                     | of gas to be flared is377 average  | MCF; Value \$700   | per day.                                     |
| C.                  | Name and location of nearest gas gathering facility:  Immediate Area   |  |  |
| D.                  | Distance NA Estimated of   | cost of connection   | IA .   |
| E.                  | This exception is requested for the following reasons:   |  |  |
|                     | Steward Energy II, LLC (SE II) hereby request an exception to Rule 19.15.18.12 because Targa's Versado System,   |  |  |
|                     | due to pressure and gas quality constraints, cannot take all of SE II's contractual gas on their system 100 % of the time.                                   |  |  |
|                     | Interruptions can occur and it will be necessary for SE II to flare during these times.  |  |  |
|                     |  | <del></del>  |  |
| ivision have t      | that the rules and regulations of the Oil Conservation been complied with and that the information given above plete to the best of my knowledge and belief. | OIL CONSERVATION I Approved Until  | DIVISION .                                   |
| ignature <u>10</u>  | EN Price for   | By All   | and .  |
| rinted Nam<br>Title | WPrice-Price LLC mgm consultant for SEII   | Title  | Petroleum Engin                              |
| -mail Addr          | esswayneprice@q.com  | Date   | 20   |
| Date DEC 2          | 27, 2019 Telephone No. 505-715-2809  |  |  |

<sup>\*</sup> Gas-Oil ratio test may be required to verify estimated gas volume.