Submit 1 Copy To Appropriate District State of New Mexico	Form C-103	
Office	Revised July 18, 2013	
Submit 1 Copy To Appropriate District State of New Mexico Office District I ~ (575) 393-6161 1625 N. French Dr., Hobbs OFFS OCHORY, Minerals and Natural Resources District II ~ (575) 748-12 N 811 S. First St., Artesia, NM 88210	WELL API NO.	
District II $-$ (575) 748-12 Bit S. First St. Artesia, NM 88210 District III $-$ (505) 334-6178 EFB 2 0 2020 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-025-45440	
District III - (505) 334-6178 FEB 2 02020 1000 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease STATE FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa RECEIVED 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)	BRAD LUMMIS COM	
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Number 112H	
2. Name of Operator MATADOR PRODUCTION COMPANY	9. OGRID Number 228937	
3. Address of Operator	10. Pool name or Wildcat	
5400 LBJ FREEWAY, STE 1500, DALLAS, TX 75240	RED HILLS; BONE SPRING, NORTH	
4. Well Location Unit Letter C : 319 feet from the N line and 2215 feet from the W line		
Section 23 Township 24S Range 34E		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3477' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORI		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI		
	ЈОВ 🗌	
OTHER: OTHER: Perfora	ate, fracture treat, produce 🛛 🕅	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
12/29/19 Open well to test csg for 30 min to 5015 psi; dropped 49 psi.	Good test. WSI.	
01/13/20 Frac done. RDMO HES. WSI until drillout.		
	s) w/12,019,000 lbs Saliu. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops.	s) w/12,019,000 lbs saild. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.	s) w/12,019,000 lbs saild. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops.	s) w/12,019,000 lbs sand. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.	s) w/12,019,000 lbs sand. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.	5) W/ 12,0 19,000 IDS Sand. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.	s) w/12,019,000 ibs saild. 10,570 - 15,160	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.		
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback.	11/29/19	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce.	· · · · · · · · · · · · · · · · · · ·	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce.	11/29/19	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief.	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief.	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief.	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief. St	
01/16 - 17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief. st DATE 02/19/20 prresources.com PHONE: 972-371-5218	
01/16 -17 Mill plugs.WSI until flowback ops. 01/19/20 Open well to flowback. 01/20/20 Well begins to produce. Spud Date: 11/10/19 Rig Release Date:	11/29/19 e and belief. St	