Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

-	
•	Lease Serial No.
J.	Lease Seliai 110.
	NMLC069276
	INIVII CAUDSIZZO

SUNDRY Do not use the abandoned we	5. Lease Serial No. NMLC0692766. If Indian, Allottee or Tribe Name								
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.								
	2 22 22				_				
1. Type of Well ☐ Gas Well ☐ Otl	8. Well Name and No. HUDSON FEDERAL 03								
2. Name of Operator CIMAREX ENERGY COMPA	9. API Well No. 30-025-30551-00-S2								
3a. Address 600 N MARIENFELD STREE MIDLAND, TX 79701	b. Phone No. Ph: 432-68	(include area code) 7-3033	10. Field and Pool or Exploratory Area S CASS						
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)				11. Cou	ınty or Parish, S	State		
Sec 19 T18S R33E SWSE 66			LEA COUNTY, NM						
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	O INDICA?	TE NATURE OF	F NOTICE,	REPOR	T, OR OTH	ER DATA		_
TYPE OF SUBMISSION	-		TYPE OF	ACTION	-				
□ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Producti	on (Star	t/Resume)	☐ Water Shut	-Off	_
	☐ Alter Casing	☐ Hydi	aulic Fracturing	☐ Reclama	tion		☐ Well Integr	ity	
Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recomp	lete		Other		
☐ Final Abandonment Notice	☐ Change Plans	🛛 Plug	and Abandon	☐ Tempor	arily Ab	andon			
	☐ Convert to Injection	Plug	Back	□ Water Disposal					
13. Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f 02/02/20: SET 7" CIBP @ 8.5 SXS CMT @ 7 135'-6.965'. 02/03/20: PERE X SQZ 55.S 02/04/20: PUMP 55 SXS CMT 02/06/20: CUT 7" CSG @ 2.5 02/07/20: TAG CMT @ 2.834' (02/08/20) PERE X SQZ 45.S ALL ANNULL, 25 SXS CMT @ 02/09/20: DIG OUT X CUT OF PLATE TO CSGS. X INSTALI WELL PLUGGED AND ABAN	ally or recomplete horizontally, given will be performed or provide the loperations. If the operation result bandonment Notices must be filed final inspection. 100'; CIRC, WELL W/ M.L.F.; W.S.CMT. @ 5,538'; W.O.C. F. @ 5,388', P.F.R. R.N.; W.O.C. F. W.C. W.C	es subsurface le Bond No. on its in a multiple only after all repumble 1. PUMP 40. DID NOT TO CX TAG CIZ 50 SXS. T. @ 1,34! AG CMT. (CERIEY CM.)	ocations and measur file with BLM/BIA. completion or recover completion of the co	red and true versions and ing reclamation in a reclamation 500'-8320'; 'D. BY BLM') WOC. @ 1.190'.	ntical dep sequent r ew interv n, have be	ths of all pertime eports must be al, a Form 3164 en completed a RECL 40 RE	ent markers and ze filled within 30 day 0-4 must be filled on the operator has AMATION PROATTACHED CCLAMA JE 3-8-	nces. ICEDUF	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #502 For CIMAREX ENER nitted to AFMSS for processir	RGY COMPA	NY OF CO, sent	to the Hobbs	3				
Name (Printed/Typed) DAVID A	Title AGENT		And	EDTEN	END DEM	nar	_		
Signature (Electronic S	Submission)		Date 02/10/20)20	AUL	CFICU	FOR RECO	ן טאנ ו	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	THIS SPACE FOR	FEDERA			¥	FEB	3 2 020		=
			- Marian di						=
Approved By	Title				ND MANAGEME		_		
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	Office			CARLSBAD	FIELD OFFICE				
							_		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm

TA E RIDE

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing pienty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure) Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD. Form 3160-3). Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4 Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Hom Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612