

UNITED STATES...  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 20185. Lease Serial No.  
NMNM0634C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
FEDERAL 129. API Well No.  
30-025-07991-00-D110. Field and Pool or Exploratory Area  
D-K11. County or Parish, State  
LEA COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2****HOBBS OCD**  
JUL 30 2020  
**RECEIVED**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

LEGACY RESERVES OPERATING LRE-Mail: mreyes@legacyreserves.com

Contact: MELANIE REYES

3a. Address

303 W WALL SUITE 1600  
MIDLAND, TX 79702

3b. Phone No. (include area code)

Ph: 432-221-6358

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 30 T20S R39E SWNW 1980FNL 660FWL

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

## TYPE OF SUBMISSION

## TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

We are requesting the subject well be placed in TA status for four years due to the current situation the oil industry is in.

POH with production equipment. RIH with CIBP. Set CIBP at 4,510' and cap with 35' of cement. Tag cement top. Circulate well and load casing with inert fluid. Notify BLM for MIT and perform MIT on well. Wellbore diagram attached.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #521182 verified by the BLM Well Information System  
For LEGACY RESERVES OPERATING LP, sent to the Hobbs  
Committed to AFMSS for processing by PRISCILLA PEREZ on 07/08/2020 (20PP2967SE)

Name (Printed/Typed) STEPHEN OWEN

Title SR ENGINEERING ADVISOR

Signature (Electronic Submission)

Date 07/07/2020

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By JONATHON SHEPARD

Title PETROELUM ENGINEER

Date 07/22/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*****Accepted for Record Only**

KZ

NM OCD

7-31-20

## Revisions to Operator-Submitted EC Data for Sundry Notice #521182

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	TA NOI	TA NOI
Lease:	NMNM0634C	NMNM0634C
Agreement:		
Operator:	LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701 Ph: 432-689-5200	LEGACY RESERVES OPERATING LP 303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686. 8318
Admin Contact:	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com  Ph: 432-221-6358	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com  Ph: 432-221-6358
Tech Contact:	STEPHEN OWEN SR ENGINEERING ADVISOR E-Mail: sowen@legacyreserves.com  Ph: 432-689-5200	STEPHEN OWEN SR ENGINEERING ADVISOR E-Mail: sowen@legacyreserves.com  Ph: 432-689-5200
Location:		
State:	NM	NM
County:	LEA COUNTY	LEA
Field/Pool:	D-K;DRINKARD/D-K;ABO	D-K
Well/Facility:	FEDERAL 12 Sec 30 T20S R39E SWNW 1980FNL 660FWL	FEDERAL 12 Sec 30 T20S R39E SWNW 1980FNL 660FWL

## **BUREAU OF LAND MANAGEMENT**

**Carlsbad Field Office  
620 East Greene Street  
Carlsbad, New Mexico 88220  
575-234-5972**

### **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.

# Current Wellbore Schematic

FEDERAL 12

Field: D-K  
County: LEA  
State: NEW MEXICO  
Elevation: GL 3,569.00 KB 3,579.00  
KB Height: 10.00

Spud Date: 4/27/1954  
Initial Compl. Date:  
API #: 3002507991  
CHK Property #: 891232  
1st Prod Date:  
PBSD: Original Hole - 7187.0  
TD: 9,680.0

Location: 1,980.0 ft FNL & 660.0 ft FWL - Section 30 - 020S - 039E

