

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-34569</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. <b>-</b>
7. Lease Name or Unit Agreement Name <b>Mooney</b>
8. Well Number <b>1</b>
9. OGRID Number <b>17213</b>
10. Pool name or Wildcat <b>House; Drinkard</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator **Penroc Oil Corporation**

3. Address of Operator **P.O. Box 2769, Hobbs, NM 88241-2769**

4. Well Location  
Unit Letter **I** : **1980** feet from the **South** line and **330** feet from the **East** line  
Section **13** Township **20 S** Range **38 E** NMPM County **lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3554' GR**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**8.20.20 - 8.23.20**

ME WSLU & P&A Equipment. RU. Pulled @ LD rods/pump. Used TAC. NU BOP.  
TDH w/ Htg. RU WL. TTH w/ CDBP. Set same @ 6700'. TDH w/ Htg. Tagged CDBP.  
Circ. 10" Gelled brine. Spotted 35' class C Cement on CDBP. WOC 4 hrs. TTH w/  
Htg. Tag TDC @ 6665'. Perd 4 holes @ 2000'. Spotted w/ 35SX. 750' WOC 4 hrs. Tagged TDC 2145'.  
Perd 4 holes @ 1630'. Spotted w/ 35 SX. WOC 4 hrs. Tagged @ 1480'. TDH (Perd 4 holes @ 150'  
Circ. to surface. RD. Emptied 1/2 pit. Cleaned loc. Will install DTM. clean final in 40 days.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 8/23/20  
Type or print name M. J. Merchant E-mail address: ajj@penrocoil.com PHONE: (575) 492-1236  
For State Use Only  
APPROVED BY: [Signature] TITLE CO DATE 8-25-20  
Conditions of Approval (if any):