New Mexico Oil Conservation Division, District I 1625 N. French Drive

Hobbs, NM 88240

UNITED STATES DEPARTMENT OF THE INTERIOR FORM APPROVED

OMB No. 1004-0137 Expires: July 31, 2010

(August 2007)

Form 3160-5

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM0155494A 6. If Indian, Allottee or Tribe Name											
									SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
									1. Type of Well					Cato San Andres Unit		
Oil Well Gas Well Other					8. Well Name and No. Cato San Andres Unit #174											
2. Name of Operator Cano Peto of New Mexico, Inc.					9. API Well No. 30-005-20188.											
3a. Address 801 Cherry Street Suite 3200 Unit 25 Fort Wor	. (include area		10. Field and Pool or Exploratory Area													
4. Location of Well (Footage, Sec., T., G-32-08S-30E 1980 FNL 1980 FEL	817-698-090	Cato; San Andres 11. Country or Parish, State														
G-32-08S-30E 1980 FNL 1980 FEL	,			Chaves Co, NM												
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INI	DICATE NATU	RE OF NOTICI	E, REPORT OR (OTHER DATA										
TYPE OF SUBMISSION TYPE OF ACT																
✓ Notice of Intent	Acidize De		epen Prod		ction (Start/Resum	e) Water Shut-Off	Water Shut-Off									
	Alter Casing	Frac	ture Treat	Reclan		Well Integrity										
Subsequent Report	Casing Repair	☐ New	Construction	Recom	plete	✓ Other tag botto	m									
	Change Plans Plug a		and Abandon Temp		porarily Abandon											
Final Abandonment Notice	Convert to Injection	Plug	Back	Water	Disposal											
BLM ORDER NO. 24-003-10W MIRU pulling unit. RIH w/ sinker bar on the end of sand production. RD and move to next well	l line to check depth. Res	sults of data ob	otained from thi	is procedure w	vill determine wi	nether this well can be retu	rned to									
		RECEIVED														
					JUL 28 2010											
			HOBBSOCD													
14 There is a second of																
14. I hereby certify that the foregoing is tru	ne and correct. Name (Printed	d/Typed)														
Collin Strawn			Title Engineer													
Signature Cohi Som			Date 06/14/2010													
	THIS SPACE I	FOR FEDEI	RAL OR ST	ATE OFFIC	CE USE											
Denied /S/ DAVID	D CLASS		ho handa	ÒLEI MÆN	GINEED	7111 2 1 004										
Conditions of approval, if any, are attached.	R. GLASS)	Fitle Title	OLEUM EN	GINEER	JUL 2 1 201	U									
that the applicant holds legal or equitable titl entitle the applicant to conduct operations th	rtify Office	Office ROSWELL FIELD OFFICE														
Title 18 U.S.C. Section 1001 and Title 43 U fictitious or fraudulent statements or represe	S.C. Section 1212, make it a centations as to any matter with	crime for any per	son knowingly a	nd willfully to m	ake to any departr	ment or agency of the United Sta	ates any false,									

fictitious or fraudulent statements or representations as to any matter within its jurisdiction: (Instructions on page 2)



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Pecos District Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201-2019 www.nm.blm.gov



In Reply Refer To: NM-82050X 3160 (P0130)

CERTIFIED-RETURN RECEIPT REQUESTED 7000 0520 0023 4992 4731

Cano Petroleum of New Mexico, Inc. 801 Cherry Street, Suite 3200 Fort Worth, TX 76102

JUL 22 2010

RECEIVED

JUL 2 8 2010 HOBBSOCD

Gentlemen:

The Bureau of Land Management (BLM) received Sundry Notices of Intent Form 3160-5 on June 18, 2010 for Cato Unit Wells Numbers 12, 15, 34, 62, 66, 117, 132, 134, 138, 140, 151, 152, 153, 160, 161, 164, 165, 166, 171, 172, 174, 175, 177, 178, 179, 181, and 184 in response to Written Order Number 24-002-10W (enclosed). The subject Sundry Notices state Cano's plans to run in hole with sinker bar on the end of sand line to check depth to determine which well(s) can returned to production is not considered a sufficient plan in response to Written Order Number 24-002-10W. The subject Sundry Notices are being returned to you Denied. These Sundry Notices also refer to an incorrect Written Order Number 24-003-10W. BLM is requiring Cano provide a more detailed plan to return the subject well(s) to continuous production or plug the well(s) with a plugging program approved by this BLM office within 60 days from receipt of this letter.

If you need additional information and/or have any questions regarding this letter, please contact David Glass, Petroleum Engineer at the above address or at (575) 627-0275.

Sincerely,

15/ Angel Mayes

Angel Mayes Assistant Field Manager, Lands and Minerals

cc: NM (P0130, File Room) Well Files