

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Gribble	
9. Well No. 1	
10. Field and Pool, or Wildcat Allison? Wildcat?	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- _____
2. Name of Operator Gordon M. Cone
3. Address of Operator Box 1148, Lovington, New Mexico 88260
4. Location of Well: UNIT LETTER L 1980 FEET FROM THE S LINE AND 660 FEET FROM THE W LINE, SECTION 6 TOWNSHIP 98 RANGE 37E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 4032.5' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
---	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Cement plugs set as follows:

- 25 sacks over perfs @ 9700'**
- 25 sacks over 5-1/2" casing stub, at 5270'**
- 25 sacks at base of 8-5/8 @ 4150' (None of this 4150' pulled)**
- 10 sacks plug in top of 8-5/8" with dry hole marker set in same.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Gordon M. Cone* TITLE **Operator** DATE **February 19, 1961**

APPROVED BY *John W. Runyan* TITLE _____ DATE _____

CONDITION OF APPROVAL, IF ANY: