

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

Orig³cc: OCC, Hobbs
cc: State Land Office
cc: Southern Region (West Texas)
cc: Southland Royalty Co.
cc: file

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
E-4025

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Plug and Abandon	7. Unit Agreement Name
2. Name of Operator SINCLAIR OIL CORPORATION	8. Farm or Lease Name Lea 514 State Com.
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>9S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Sawyer San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3940' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Presently completed in San Andres perms. 4916-38'.
7-5/8"OD 20# J-55 casing set @ 330' and cemented w/225 sks. Circ. to surf.
2-7/8"OD EUE 6.5# N-80 Tbg F/casing set @ 5000' and cemented w/125 sks., top of cement outside 2-7/8"OD tbg F/csg. @ 4425'. Later after completion, hole came in 2-7/8"OD Tbg F/Csg. @ 836-1100', defective tubing was replaced and cemented Tbg F/csg. from 4425' to surface w/1650 sacks.

PROPOSE TO: Plug and Abandon as follows:
Cement squeeze 2-7/8"OD Tubing F/casing w/approx. 300 sks. (approx. 150 sks. to squeeze perms. 4916-38' and approx. 150 sks. to fill tubing F/casing to surface. Erect regulation dry hole marker, clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Superintendent DATE 1-14-69

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: