

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
**K-2790**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Major, Giebel &amp; Forster</b>	8. Farm or Lease Name <b>Sinclair-Southland State</b>
3. Address of Operator <b>1126 Vaughn Building, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>L</b> , <b>510</b> FEET FROM THE <b>West</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>31</b> TOWNSHIP <b>10-S</b> RANGE <b>34-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Vada Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>Furnish later</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2/26/69 Spud well at 12:45 A.M. Drilled 17 1/2" hole to 385 feet. Cemented 12 3/4" 42# casing at 385 feet w/350 sx. Cement circulated. Plug down at 2:45 P.M. WOC 9 hours.
- 2/27/69 WOC 10 hours. Tested casing w/500 psi. Held OK. Started drilling 11" hole.
- 3/4/69 Drilled 11" hole to 4045 feet. Cemented 8 5/8" 32 & 24# casing at 4050 feet w/400 sx. Plug down at 9:00 A.M. WOC 14 hours.
- 3/5/69 WOC 9 hours. Tested casing w/1000 psi. Held OK. Started drilling 7 7/8" hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *William S. Kene* TITLE Engineer DATE 3/7/69

APPROVED BY *[Signature]* TITLE SECRETARY DATE MAR 10 1969

CONDITIONS OF APPROVAL, IF ANY: