

Submit 3 Copies
to Appropriate
District Office

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2008

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-041-20868

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
V. Weir

8. Well No.
1

9. Pool Name or Wildcat
Justis Blbry-Tubb-Dkrd

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL GAS WELL other Dry Hole

2. Name of Operator
ARCO OIL and GAS COMPANY

3. Address of Operator
P.O. Box 1610, Midland, Texas 79702

4. Well Location
Unit Letter L : 1980 Feet From The South Line and 660 Feet from The West Line
Section 20 Township 5S Range 36E NMPM Roosevelt County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4104.9 GR

11. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
(Other)

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
(Other)

12. Describe Proposed or completed Operation (Clearly state all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD'd 11" hole at 3420. Ran 8-5/8 24/32# csg to 3420. Cmt'd w/950 sx 50/50 MBF "C" + 3% salt + 0.2 gal disp + 1/4# FC + 0.03 gal defoam (yld 2.03) followed by 400 sx "C" + 1% CC. Circ 41 sx to surf. WOC 12 hrs. Press test 8-5/8 csg to 1000# for 30 min. DA w/7-7/8 bit.

TD'd 7-7/8 hole at 7750, 5-7-93. Ran OH logs. P&A as follows:

Plug	Interval	Cmt	Remarks
1	7239-7639	125 sx H	Wolfcamp - three Brothers
2	6434-6634	75 sx H	Abo
3	4453-4653	110 sx H	Glorieta
4	3290-3490	70 sx H	8-5/8 shoe
5	322-472	45 sx H	13-3/8 shoe
6	0-30	10 sx H	Surface

Cut of wellhead & installed dry hole marker. P&A'd 5-11-93. P&A procedure approved by Paul Kautz 5-6-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Ken W. Gosnell TITLE Regulatory Coordinator DATE 5-13-93

TYPE OR PRINT NAME Ken W. Gosnell TELEPHONE (915) 688-5672

(This space for State Use)

OIL & GAS INSPECTOR

SEP 20 1993

APPROVED BY Harry W. [Signature] TITLE _____ DATE _____

CONDITIONS FOR APPROVAL, IF ANY:

131

8