

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-00523
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. B 871
Lease Name or Unit Agreement Name NEW MEXICO "O" STATE
Well No. 21
Pool name or Wildcat MALJAMAR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)


Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
Name of Operator SOUTHWEST ROYALTIE, INC.
Address of Operator P. O. BOX 11390; MIDLAND, TX 79702
Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line 12 Section <u>17S</u> Township <u>32E</u> Range <u>NMPM</u> <u>LEA</u> County
Elevation (Show whether DF, RKB, RT, GR, etc.) 4238 GL

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PLUGGING CONTRACTOR.
- TIH W/ CIBP & SET @ ^{4100'} 4780' +/- CAP W. 35' OF CMT (TAG). LOAD CSG W/ MUD.
- SPOT 10 SX PLUG FROM 3400' - 3550'. **ALL PLUGS 25SX OR 100' WHICHEVER IS GREATER -**
- PERF CSG @ 2500' & SQZ W/ 50 SX. LEAVING 10 SX INSIDE CSG - TAG.
- SPOT 35 SX PLUG FROM 1150' - 1400'. **- TAG**
- SPOT 25X CMT PLUG FROM 3' - 103'.
- CUT OFF WELLHEAD, INSTALL P&A MARKER. RESTORE LOCATION.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE AGENT DATE 11-28-01

TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915 686-9927

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

J
L

SOUTHWEST ROYALTIES


PROJECT State of NM "D" NCT-3
Well No 21

PAGE 1 OF 1
 BY cmB DATE 11/12/01

Elev. 4233' GL

1980' FN&EL
 Ut. G Sec 12, T17S, R32E
 Lea Co, NM
 ST B 871

Spudded 3/25/60 (Tenneco)
 Drly Comp 4/4/60



4/60 Partial SA
 4146-50, 70-74, 4223-32
 4250-53, 67-72, 73-84,
 91-94, 93-4312 25PF
 AW 1500 gals 15% LST AEA
 SOEW 20,000 gals RD 7 15,000
 165 sd 20/40
 IP F 53 BOPD, 0 BW in 10 hrs
 1/24/88 SWF 4146-4312'
 w/ 30000 gals 7 30000 lbs sd
 in 3 stg's
 IP 11 BOPD, 62 BW 24 hrs.