

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-01328
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2229
7. Lease Name or Unit Agreement Name	PHILLIPS E STATE
8. Well No.	6
9. Pool name or Wildcat	MALJAMAR GB/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4294' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 OIL WELL GAS WELL OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
 Unit Letter **M** : **660** Feet From The **SOUTH** Line and **660** Feet From The **WEST** Line
 Section **9** Township **17 S** Range **33 E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4294' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/28/95 MIRU DDU & CMT EQUIPMENT, POOH LD RODS, ND WH NU BOP, RELEASE TAC POOH W/PROD. TBG.
 03/29/95 FINISH POOH W/PROD TBG. PU & RIH W/CIBP, SET CIBP @ 4247'. MIX & SPOT PLUG #1 40 SX CLASS C CMT, INTERVAL 4247'-3947'. RIH W/PKR AND SET @2480'. RIH & PERF 5-1/2" CSG @2722'.

03/30/95 NOTIFIED JERRY SEXTON W/NMOCD OF INTENT TO SPOT PLUG #2 (OK'D-25 SX PLUG @2772', NO TAG). MIX & SPOT PLUG #2 25 SX C CMT, INTERVAL 2772'-2572'. RIH & PERF 5-1/2" CSG @1475'. MIX & SQZ PLUG #3, 50 SX C CMT, INTERVAL 1475'-1320'. TAG PLUG #3 @1320'. RELEASE THE PKR, POOH W/PKR & WORKSTRING. PERF'D 5-1/2" CSG @335'. MIX & PUMP 150 SX C CMT.

03/31/95 TAG PLUG #4 @40'. ND BOP, MIX 10 SX C CMT, FILLING CSG TO SURF. RDMO DDU, CUT OFF, CAP, INSTALL MARKER & PERFORM RECLAMATION @ LATER DATE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *L. M. Sanders* TITLE SUPERVISOR, REG. AFFAIRS DATE 4/6/95
 OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

see for State Use)

BY *Larry M. Hill* TITLE OIL & GAS INSPECTOR DATE 4/26/95
 APPROVAL, IF ANY: