

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-29794 ✓

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Meyers

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
2

2. Name of Operator
Amerind Oil Company Limited Partnership

3. Address of Operator
415 W Wall Suite 500, Midland TX 79701

9. Pool name or Wildcat
Knowles Drinkard West

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 2130 Feet From The West Line
Section 33 Township 16S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3782' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/26/93 Unable to recover stuck 2-3/8" tbg from 7924'-5130'. Cmt'd in place w/1st plug.

Plug 1	200 sx H w/5 lb. gilsonite/sx	7924'-5014'	(2910')	Tagged
Plug 2	50 sx C	5000'-4840'	(160')	Tagged
Plug 3	50 sx C	4250'-4150'	(100')	Tagged
Plug 4	60 sx C	2050'-1950'	(100')	
Plug 5	15 sx C	20'-surf	(20')	

Cut off wellhead and set dry hole marker. Well P & A 3/1/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James E. Yeley TITLE Agent DATE March 2, 1993
TYPE OR PRINT NAME James E. Yeley TELEPHONE NO. 915/682-8217

(This space for State Use)

APPROVED BY [Signature] TITLE _____ DATE _____