
Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, New Mexico 87504-2088		WELL API NO. 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OL WELL ONE OAS WELL OTHER 2. Name of Operator Shell Western E&P Inc.			7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 17 8. Well No. 141	
P.O. Box 576 Houston, TX 77001-0576 Well Location Unit LetterM :660 Feet From The SOUTH Line and			9. Pool name or Wildcat HOBBS (G/SA)	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 12-07 TO 12-09-93: POH W/PROD EQMT. SET CIB: 30 MIN. (CHART ATTACHED.) WELL TA'D.	PLUG AND ABANDON CHANGE PLANS Dictions (Clearly state all pertinent details, and P @ 3990' & CAPPED W/35' CI CIRC INHIB FL. SECURED WELL OF NMOCD RULE 203, SHELL	Nature of Notice, R SUB REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CE OTHER: TA'D d give pertinent dates, inclu MT. PT CSG TO 506.	SEQUENT R OPNS. MENT JOB ding estimated date of CLN LOC.	Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT
SIGNATURE J. Marcus	20.00	belief. TECH. MANAGER	- ASSET ADMIN	
	SIGNED BY JERRY SEXTON TRICT I SUPERVISOR			теценноме но. 713/544—379

JAN 1 1 1994

CONDITIONS OF APPROVAL, P'ANY: This Approval of Temporary
Abandonment Expires



A CONTRACTOR OF THE PARTY OF TH