

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO STOPPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT ON FORM O-101 FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Form or Lease Name
SECTION 31

9. Well No.
411

10. Field and Pool, or Whichever
HOBBS (G/SA)

Name of Operator
SHELL WESTERN E&P INC.

Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

Location of Well
UNIT LETTER A 330 FEET FROM THE NORTH LINE AND 330 FEET FROM
THE EAST LINE, SECTION 31 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

11. Elevation (Show whether DF, RT, GR, etc.)
3645' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>OAP & ACD</u> ☒

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-31-85: Pulled production equipment. Tagged btm @ 4273'. Perf'd San Andres 4135' - 4141' (2 JSPF, 4 holes).

1-02-86: Acid perf's 4135' - 4252' w/5100 gals 15% HCl-NEA. Installed production equipment and returned well to production.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 13, 1986
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
DATE JAN 16 1986