

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPLEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT LIT (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL WELL OIL WELL GAS WELL OTHER

2. Name of Operator
SHELL WESTERN E&P INC.

3. Address of Operator
P. O. BOX 576, HOUSTON, TEXAS 77001

4. Location of Well
UNIT LETTER J 2310 FEET FROM THE SOUTH LINE AND 2310 FEET FROM
THE EAST LINE, SECTION 32 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Part of Lease Name
SECTION 32

9. Well No.
331

10. Field and Pool, or Wildcat
HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)
3642' GR

12. County
LEA

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPER. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | ZONE TESTS <input checked="" type="checkbox"/> |

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

- 4-10-86: Pulled production equipment. Tagged btm @ 4225'. Set RBP @ 4105'.
- 4-11-86: Pres tstd RBP & sqzd perfs 4087' - 4090' to 500#, held OK. Installed production equipment and returned well to production.
- 4-28 to 4-29-86: Pulled production equipment. Reset RBP to 4157'. Installed production equipment and returned well to production.
- 5-16-86: Pulled production equipment. Reset RBP to 4221'. Installed production equipment and returned well to production.
- 6-02-86: Pulled production equipment. POH w/RBP. Installed production equipment and returned well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JULY 8, 1986
 ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR
 APPROVED BY _____ TITLE _____ DATE JUL 11 1986