

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
Midland Corporation

3. Address of Operator
Box 633, Midland, Texas 79701

4. Location of Well
UNIT LETTER *C* *660* FEET FROM THE *North* LINE AND *2310* FEET FROM THE *West* LINE, SECTION *25* TOWNSHIP *17-N* RANGE *34-E* NMPM.

5. Elevation (Show whether DE, RT, GR, etc.)
4020 GL

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Form or Lease Name
Bridge State

9. Well No.
106

10. Field and Pool, or Wildcat
Vac. Horista

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Block Squeeze to prevent injection water from Channeling down to the Horista perforations as per attached recommendation

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Christine O. Tucker TITLE *Permitting Clerk* DATE *11-2-73*

APPROVED BY: _____ TITLE _____ DATE _____

APPROVED BY APPROVAL, IF ANY: _____

WELL WORK RECOMMENDATIONS
Proposals for Well Secondconditioning and Subsurface Maintenance
Workovers, Expense Dr's, P's, and Conversions

Lease: PLACENTA STATE Well No. 106
Field: WARRIOR (CLARITA)
County: LEWIS State: NEW MEXICO

RECOMMENDED PROCEDURES:

1. MOVE IN A PULLING UNIT AND PULL THE PRODUCING EQUIPMENT.
2. SET A PERFORATED BRIDGE PLUG AT APPROXIMATELY 5,100' AND CEMENT WITH 20' OF SLUD. PERFORATE THE 4 1/2" Casing WITH 4 SET SIZES AT APPROXIMATELY 5,055' TO 5,080'.
3. SOLIDIFY THE NEW PERFORATIONS (5,055'-5,080' - 4 1/2" CAS) WITH CLASS C LIGHT CEMENT CONTAINING 2 LBS/SK OF SALT AND 5 LBS/SK OF NO. 3 CEMENTING SLUD. APPROXIMATELY 100 SK OF NEED CEMENT WILL BE REQUIRED.
4. DRILL OUT THE CEMENT BRIDGE WOC FOR 24 HRS. CLEAR THE SLUD OUT, AND PULL THE RETRIEVBLE BRIDGE PLUG AT 5,100'.
5. RETURN THE WELL TO PRODUCTION AS A CLARITA PRODUCER.

10-10-73
19:00