

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-32471

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:
OIL WELL GAS WELL OTHER Dry

Scarborough

2. Name of Operator
Collins & Ware, Inc.

8. Well No.
1

3. Address of Operator
508 W. Wall, Suite 1200, Midland, Texas 79701

9. Pool name or Wildcat
Humble City (33490)

4. Well Location
Unit Letter K : 2100 Feet From The South Line and 1500 Feet From The West Line

Section 10 Township 17 South Range 37 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3660.2 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-07-94 Ran DST #1 from 10,738 to 10,758' (20')

5-08-94 Ran DST #2 from 10,800 to 10,872' (72')

5-12-94 Ran DST #3 from 11,400 to 11,432' (32')

5-13-94 Logged from 11,432 to 4408 w/ GR to surface

5-14-94 Began P&A Operations:

- Spot plug #1, 25 sx class "H" @ 11,440'
- Spot plug #2, 25 sx class "H" @ 9,520'
- Spot plug #3, 25 sx class "H" @ 7,520'
- Spot plug #4, 25 sx class "H" @ 5,150'

5-15-94

- Spot plug #5, 50 sx class "H" @ 4,500'
- Spot plug #6, 50 sx class "H" @ 2,300'

8-08-94

- Spot plug #7, 120 sx cement plug @ 520'. Tagged @ 345'
- Spot plug #8, 10 sx cement plug from 33' to surface.

Shot off 8 5/8" casing @ 470'. Recovered 475' 8 5/8" casing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Clerk DATE 8/15/94

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. 915-687-3435

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SAO

RECEIVED

AUG 16 1954

RECORDS
OFFICE