

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised March 25, 1999

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>WELL API NO.</b> 30-025-04698
<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>6. State Oil &amp; Gas Lease No.</b>
<b>7. Lease Name or Unit Agreement Name:</b> Eunice Monument South Unit
<b>8. Well No.</b> 379
<b>9. Pool name or Wildcat</b> Grayburg-S.A.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well:**  
 Oil Well  Gas Well  Other

**2. Name of Operator** Chevron USA, Inc.

**3. Address of Operator** 15 Smith Rd. Midland, Tx 79705

**4. Well Location**  
 Unit Letter G : 2310 feet from the north line and 2310 feet from the east line  
 Section 17 Township 21-S Range 36-E NMPM County Lea

**10. Elevation (Show whether DR, RKB, RT, GR, etc.)**

**11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Tag 5 1/2 CIBP @ 3800, spot 50sx plug fr/3800-3600(Grayburg-Queen) Tag @ 3568
- Displace hole w/MLF 9.5# Brine w/25 # Gel P/BBL.
- Spot 45sx plug fr/3020-2600(9 5/8 shoe, B-salt)WOC Tag @ 2605
- Perf 4 holes @ 1400, sqz w/100sx fr/1400-1200(T-salt)Tag @ 1120
- Perf 4 holes @ 300, circ cmt fr/300 to surf w/195sx (15 1/2 shoe) Tag @ surf
- Install dry hole marker 10-31-02

Approved as to plugging of the Well Bore.  
 Liability under bond is retained until surface restoration is completed

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 10-31-02

Type or print name Jimmy BAGLEY Telephone No 915 520-8756

(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE / STAFF MANAGER DATE FEB - 7 2003

Conditions of approval, if any GARY W. WINK

GWW

4