

7/16/97

Mark Faris

Arco

\* Wimberly #5 - C, <sup>990/1172310/W</sup> 24-25-37

White Fang #1-30-25-36

\* Cannot locate  
well File

need plugging

procedure will

be in early Thurs

---

DISTRICT I  
P.O. Box 1500, Hobbs, NM 88240

# OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
P.O. Drawer DD, Azusa, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Azusa, NM 87410

WELL API NO.	3002531514
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

7. Lease Name or Unit Agreement Name	White Fang #1
8. Well No.	South Justis
9. Pool name or Wellnet	Lea County Sec 30-255-38E
	#1
	Abo (South Justis)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	Arco Permian - P.O. Box 1610 - Midland, TX 79702
3. Address of Operator	P.O. Box 1610 - Midland, TX - 79702
4. Well Location	Unit Letter 950 Feet From The West Line and 456 Feet From The South Line

Section	30	Township	25S	Range	38E	NMGM	Lea County
10. Elevation (Show whether DP, RCB, RT, GR, etc.)	3052 Ground Level						

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work): SEE RULE 1103.

R.I. 4 1/2" tubing and tag cement on top of CIB Pat 6175'. Circulate hole with salt gel mud. Rig up Halliburton acid pump cement plug at 3400' w/ 50 feet above and below of base cement. Pulled up acid pump 100' plug at 2150'. Pulled up acid pump 10 sockets surface plug. Dig out well head flange and cut off. Installed P&R markers. Estimated to start (7-22-97)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc Farris TITLE consultant DATE 7-18-97

TYPE OR PRINT NAME Marc Farris TELEPHONE NO. 505-325-3138

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL IF ANY \_\_\_\_\_