

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-32053
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-269

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 OIL WELL GAS WELL OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South Fourth Street - Artesia, NM 88210

4. Well Location
 Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line
 Section 23 Township 26S Range 36E NMPM Lea County

7. Lease Name or Unit Agreement Name
Beartooth State Unit

8. Well No.
1

9. Pool name or Wildcat
Wildcat Bone Springs

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
2912' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7725'. Plugged and abandoned well as follows:

Plug #1: 7625-7725' with 25 sacks
 Plug #2: 5430-5530' with 25 sacks
 Plug #3: 3205-3105' with 25 sacks
 Plug #4: 1097-1197' with 25 sacks inside 8-5/8" and 50 sacks in 8-5/8" X 13-3/8" annulus. Perforated at 1197'. Set cement retainer at 1097'.
 Plug #5: Surface with 10 sacks.

Cleaned pits and nipped down. Cut off wellhead and installed regulation abandonment marker. Released rig at 9:15 AM 8-21-93. PLUGGED AND ABANDONED - FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 10-31-93
 TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Charles... TITLE _____ DATE _____