

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| ANTA FE | | |
| ILE | | |
| S.G.S. | | |
| AND OFFICE | | |
| PERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

7. Unit Agreement Name

Name of Operator

8. Farm or Lease Name
Humphreys

Maralo, Inc.
Address of Operator

9. Well No.
2

P. O. Box 832, Midland, Texas 79702 0832
Location of Well

UNIT LETTER K 1650 FEET FROM THE South 2310 FEET FROM
West 25 25-S 36-E TOWNSHIP 25-S RANGE 36-E NMPM.

10. Field and Pool, or Wellcat

15. Elevation (Show whether DF, RT, CR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK
TEMPORARILY ABANDON
REPAIR OR ALTER CASING
OTHER
PLUG AND ABANDON
CHANGE PLANS
OTHER

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING TEST AND CEMENT JOB
OTHER
ALTERING CASING
PLUG AND ABANDONMENT
OTHER

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Proposed Operation to Plug and abandon:

1. Notify NMOC
2. Set CIBP @ +/- 3200' (within 100' of OH) w/20' cement on top to 3180'.
3. Load hole w/10#/gal mud-laden fluid using 25# gal/bol.
4. Determine free-point of 5 1/2" casing. Cut and pull free casing.
5. Place 100' cement plug across casing cut.
6. Set 100' cement plug across 10 3/4" surface casing shoe from 367' to 467'.
7. Using 10 sacks cement, set surface plug.
8. Remove wellhead, cut off casing & weld plate on casing.
9. Clean up location
10. Place a metal dry hole marker at location.

100' CEMENT PLUG SET AT 3180' AT 2937
100' CEMENT PLUG SET AT 3180' AT 1010
TO COMPLETION OF THIS WELL
HEREBY REPORTING TO THE COMMISSION
THAT THE WELL IS BEING PLUGGED
AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Brenda Cuffman
915 684-7441
Agent DATE 5-19-87

Orig. Signed by
Paul Kartz
Geologist

ILLEGIBLE

DATE MAY 21 1987

RECEIVED
MAY 20 1961
U.S. AIR FORCE
HEADQUARTERS