

Submit 3 Copies To Appropriate District Office

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-23306
5. Indicate Type of Lease STATE                      FEE    X
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	7. Lease Name or Unit Agreement Name:  Langlie Mattix Queen Unit
2. Name of Operator Gruy Petroleum Management Co.	8. Well No. 3
3. Address of Operator P.O. Box 140907, Irving, TX. 75014-0907	9. Pool name or Wildcat Langlie Mattix 7RV-Qu-Grbg
4. Well Location  Unit Letter M-__ 990__ feet from the South - line and 890__ feet from the __ West__ line  Section 10 Township 25 S Range 37E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3106' GR	


11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Request for temporarily Abandon Status <input checked="" type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Pool with 1 Jt. 2 3/8" Cement Coated Tbg., 99 Jts. Of 2 7/8" on a 5 1/2" Model AD-1 Packer Set @ 3031'.  
Rih with a 4.24" CIPB set @ 3299', spot 35' of class "H" Cement on plug.  
Rih with 98 Jts. Of 2 7/8 CC Tbg., 1 Jt. Of CC 2 3/8" Tbg. Circulate 120 bbls of treated water.  
Nu wellhead, test casing to 520 Psig, pressure after 30 Minutes was 483 Psig. A drop of 7.1%  
Gruy Petroleum Mgt., respectfully request approval to temporarily Abandon this inactive well.  
See attached Chart, Conformation on procedure of this test was given by Silvia Dickey, Hobbs, NM. OGD

This Approval of Temporary Abandonment Expires 8/8/07



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Reggie Reston TITLE Production Superintendent

DATE 8/1/02

Type or print name Reggie Reston

Telephone No. 505-393-2358

APPROVED BY \_\_\_\_\_  
Conditions of approval, if any:

ORIGINAL SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
GARY W. WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

3  
C  
S