

Case No
4560

Large Exhibits





U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D.C. 20250

BLM Form 100-107 (Rev. 1-87)

Water Damaged Documents


FILE NUMBER 4560

MAP NUMBER 314

PLAT NUMBER 727

DATE 1-5-87

APPROVED BY Hernandez



12A
HTC

- Dashed Oil Well
- Abandoned Dashed Oil Well
- Proposed Gas Well
- Proposed Disposal Well

Scale 1" = 2000'

RIJAN OIL COMPANY, INC.

Proposed Water Disposal Well

Section 31-Township 30 North-Range 16 West
San Juan County, New Mexico

LESSORS:


- Rijan Oil Company, Inc.
- Amoco Production Co.
- Claude G. Kennedy
- Walter Duncan
- Wm. Lamb
- Raymond Charles
- Manley-Moore
- Texaco, Inc.
- Open



BEFORE EXAMINER NUTTER

OIL CONSERVATION COMMISSION

EXHIBIT NO. 1

CASE NO. 4560





DAKOTA STRUCTURE & ADJACENT AREAS M

NORTHEAST SLICK ROCK DAKOTA OIL POOL
T30N, R16W - SEC. 31 — SAN JUAN COUNTY, NEW MEXICO

P.O. BOX 100 — SAN JUAN COUNTY,
PRINCE GEORGE COUNTY INC.

- LEADER
- 1 - OIL WELL
2 - DRY HOLE WITH SHOW
3 - TEMPORARILY ABANDONED WELL
4 - DRY HOLE
5 - G. GALLUP SANDSTONE
6 - M. M. DAKOTA SANDSTONE
7 - M. M. DAKOTA SANDSTONE
8 - 100' INTERVAL FROM GALLUP TO DAKOTA
9 - INJECTION WELL
10 - SCALE 1" = 200'
11 - DATE 12/19/71
12 - TOP OF FIRST DAKOTA SANDSTONE
13 - TOTAL DEPTH
14 - MAGNETIC TOP
15 - MAGNETIC TOP
- V.A. REESE, CERTIFIED PROFESSIONAL GEOL.

