

NOV 14 '90 18:23

3744

PAGE.002

Page 1 of 2

REPORT OF UNDESIRABLE EVENT

NOTIFICATION OF FIRE, BREAK, BLOWOUT, ACCIDENTAL DISCHARGE, LEAK, OR OTHER

OPERATOR: CONOCO INC. ADDRESS: P.O. BOX 460, HOBBS, NEW MEXICO 88240

DIVISION
RECEIVED

90 NOV 26 AM 10 53

TYPE OF EVENT

Accidental Discharge: Break _____ Leak ☒ Blowout _____ Other _____

Other Event: Fire _____ Fatality _____ Injury _____ Property Damage _____

Gas Venting _____ Uncontrolled Flow of Wellbore Fluids _____

Other (Specify) _____

Quantity of Loss: Oil ☒ Prod. Water 20 Gas ☒ Other (Specify) _____

Did Any Fluid Reach Watercourse? _____ No _____ Quantity: _____ None _____

RECOVERED 15 BW.

LOCATION OF EVENT

Facility (Name and Type) St. H. 35 BtryFacility Location: Qtr./Qtr. Unit letter B Section 35 Township 17-S Range R. 34ECounty: Lea State: New MexicoDistance or direction from nearest town or prominent landmark: 1 mi SW. of Buckeye NM.

DESCRIPTION OF EVENT

Date of Occurrence (Estimate) NOV. 14, 1990 Time of Occurrence (Estimate) 12:00 noonDate of Discovery: NOV. 19, 1990 Time of Discovery: 2:00 pmEstimated Cost of Repair and Cleanup: \$1,000Describe Cause of Problem and Remedial Action Taken: WTR. TRANSFER LINE FROM OUR ST. H. 35 BTRY TO PHILLIPS M.E. HAIL BTRY (STATE H. 35 WF SYSTEM)due to external corrosion. 2 1/2" TPE line was buried in rockexternal wrapping was damaged by the rock.Describe Area Affected and Cleanup Action Taken: pasture area, recovered waterwith vacuum truck - 2'x50' ran into a 80'x90' area.Description of Area: Farming _____ Grazing ☒ Urban _____ Other _____Surface Conditions: Sandy _____ Sandy Loam _____ (Clay ☒ Rocky ☒ Wet _____ Dry ☒ Snow _____Describe Prevailing Conditions (Temperature, Precipitation, etc.) 65° sunny breezyWere Cattle Observed? Yes _____ No ☒Describe Action Taken or Will Be Taken To Prevent Recurrence: Ball holes will be dug and line willbe inspected. line will be left out of service until correctiveaction has been taken. AREA DUG OUT AROUND LEAK INDICATES THAT THE DITCH WASN'T BEDDEDNOTIFICATION BEFORE LINE WAS LAID. FURTHER INSPECTION SHOULD VERIFY THIS, PROPER LAYING PROCEDURESWas Immediate Notification Necessary for BLM? NO NMOC? NOWILL BE FOLLOWED ON ANY REPLACEMENT WORK.

IF IMMEDIATE NOTIFICATION WAS NECESSARY, COMPLETE THE FOLLOWING SECTION:

BUREAU OF LAND MANAGEMENT

NEW MEXICO OIL CONSERVATION DIVISION

Given To: _____

Given To: _____

BLM Office: _____

OCD Office: _____

By Whom: _____

By Whom: _____

Date: _____ Hour: _____

Date: _____ Hour: _____

Other Agency(ies) Notified: _____

Surface Ownership (Federal/Indian/Fee/State): State

Mineral Ownership (Federal/Indian/Fee/State): _____

Lease No.: B-3196 Unit/CA No.: _____

Right-of-Way No.: _____

I hereby certify that the information above is true and complete to the best of my knowledge.

Signed: Steven H. McLeisterTitle: Prod. Oper.Date: Nov 14, 1990Mike ColbornPROD. FOREMAN11-14-90

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 610356

CONDITIONS

Operator: CONOCO INC P.O. Box 2197, WI3 3046 Houston, TX 77252	OGRID: 5073
	Action Number: 610356
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
scwells	Copying initial C-141 into incident file.	7/31/2026