District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

<u>District II</u>

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Form C-140 Permit 45791 Revised June 10, 2003

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

APPLICATION FOR WELL WORKOVER PROJECT

	or and Well:						A1907A0000000000000000000000000000000000	
Operator name & address							OGRID Number	
OCCIDENTAL PERMIAN LTD							157984	
PO Box 429	94							
Houston T	K 77210						6	
Contact Party							Phone	
Karen Ellis							713-366-5161	
Property Name Well Number							API Number	
NORTH HOBBS G/SA UNIT 131							30-025-07544	
UL - Lot	Section	Township	Range	Feet From The	North/South Line	Feet From The	East/West Line	County
L	33	18S	38E	2310	S	330	W	Lea
II. Worke	over:							
Date Workover	Commenced:	Previou	s Producing P	ool(s) (Prior to We	orkover):			
6/20/2006		HOB:	BS;GRAYE	URG-SAN AN	DRES			
Date Workover	Completed:							
6/30/2006								
IV. Attach follow:	a production ding the workov	ecline curve or t er reflecting a po	able showing sitive product		nths of production pr	iar to the warkov	er and at least three	e months of production
	- 1	I THE WOLKOVEL	Procedures pe	normed to Indease	production.			
V. Signat		ation aborn is t	no and compl	lata ta tha hast of w	ry knowledge and be	line		
Signature		onically Signe	7 July 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		gulatory Team L		Date 1	29/2007
"	£ 500		50		,			
Type or pr	nnt name <u>E</u>	izabeth Bush	-lvie E	L-mail address	Elizabeth_Bush	@oxy.com_le.	lephone No. 7	13-366-5303
FOR OIL CON	CEDUATION:	ъплетом пер	ОМ У:					
VI. CERT This A shows	IFICATION O application is heap of the production of the productio	F APPROVAL ereby approved liction increase.	and the above By copy here		tifies the Secretary o			reby verifies the data sent of this Approval and
Signature I	istrict Sup	ervisor: Ch	ris Williams	3	District :	1 1	Date 2/1/200	7
_	•						300	

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: 2/1/2007

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE		TION DIVISION	WELL API NO.			
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	ICT I 1220 South St. Francis Dr.					
DISTRIC <u>T II</u>			5. Indicate Type of Lease			
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE		
DISTRICT III			6. State Oil & Gas Lease No.			
1000 Rio Brazos Rd, Aztec, NM 87410						
	ES AND REPORTS ON WEL		7. Lease Name or Unit Agreen	ient Name		
(DO NOT USE THIS FORM FOR PROPOSED DIFFERENT RESERVOIR. USE "APPLIC	North Hobbs (G/SA) Unit Section 33					
1. Type of Well:	ZATION FOR TEIGHT (TOTAL C. I.	Ty to an proposition	8. Well No. 131			
Oil Well X	Gas Well Other	•				
2. Name of Operator			9. OGRID No. 157984			
Occidental Permian Ltd. 3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)		
HCR 1 Box 90 Denver City, TX 79323						
4. Well Location						
Unit Letter E : 2310 I	Feet From The North	Feet	From The West	_ Line		
Section 33	Township 18-S	Range 38-E	NMPM	Lea County		
	11. Elevation (Show whether DF, RK 3625' GR	B, RT GR, etc.)				
Pit or Below-grade Tank Application	or Closure					
Pit Type Depth of Ground Wa		earest fresh water well	Distance from nearest st	urface water		
Pit Liner Thickness mil Be	low-Grade Tank: Volume	bbls; Construction Mat	erial			
				<u> </u>		
12. Check Ap NOTICE OF INTENT	propriate Box to Indicate Nat FION TO:	ure of Notice, Report, or C SUBS	other Data SEQUENT REPORT O	·F:		
PERFORM REMEDIAL WORK PL	LUG AND ABANDON	REMEDIAL WORK	ALTERIN	G CASING		
TEMPORARILY ABANDON CI	HANGE PLANS	COMMENCE DRILLING OP	NS. DLUG & /	ABANDONMENT		
PULL OR ALTER CASING M	ultiple Completion	CASING TEST AND CEMEN	T JOB			
OTHER:		OTHER: Pump repair/Op	en Additional perfs/ AT	Х		
12 Describe Proposed or Completed Operati	ons (Clearly state all pertinent de	tails, and give pertinent dates	, including estimated date of	starting any		
proposed work) SEE RULE 1103. For	Multiple Completions: Attach w	ellbore diagram of proposed of	completion or recompletion.			
I. RUPU & RU. Kill well. Pull out of he	ole w/tbg & ESP equipment.					
2 Tanged the @4243' (PRTD)		Alia Callervine denther AllA	16' 4124-26' 4152-54'			
 ragged tog (#3-1/8") Perforate hole w/3-1/8" cased guns @2 Perform 4 stage SPA acid job using 210 	JSPF w/180 degree phased at	the following depuis: 4114-	-10,4124-20,4132-34.			
 Perform 4 stage SPA acid job using 210 Swab 100 bbl fluid from well. 	on and the transfer in the or	, 2 DI M & 1500 1 D.				
6. Pump scale squeeze 200 gal 6490 mixe	d in 100 bbl fresh water. Flust	w/500 bbl fresh water.	•			
7. Run back in hole w/ESP equipment on	125 jts of 2-7/8" tbg. Intal	ce set @3869'.				
8. RDPU & RU. Clean Location.						
RUPU 06/20/2006						
RDPU 06/30/2006			it a sure to a later to later to a later to	han boan/will bo		
I hereby certify that the information above is true	and complete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank	nas ocen/wiii de		
constructed or closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved			
SIGNATURE		TITLE Administrative	Associate DAT	TE 07/11/2006		
	son E-mail address:	mendy johnson @oxy.co). 806-592-6280		
TYPE OR PRINT NAME Mendy A. Johns For State Use Only	1011 Li mun adaress.					
·		TITLE	DA	ATE.		
APPROVED BY	<u></u>					
CONDITIONS OF APPROVAL IF ANY:						