



District IIDistrict IIIDistrict IV

## Energy, Minerals and Natural Resources

## Oil Conservation Division

1220 S. St Francis Dr.

Santa Fe, NM 87505

## WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-025-39078	2. Pool Code 2500	3. Pool Name ARKANSAS JUNCTION-SAN ANDRES
4. Property Code 36929	5. Property Name ARKANSAS STATE	
6. Well No. 002	7. OGRID No. 13837	
8. Operator Name MACK ENERGY CORP	9. Elevation 3765	

## 10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
H	35	18S	36E		1650	N	990	E	LEA

## 11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 40.00		13. Joint or Infill		14. Consolidation Code			15. Order No.		

**NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION**

			■

## OPERATOR CERTIFICATION

*I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.*

E-Signed By: Jerry Sherrell

Title: Production Clerk

Date: 8/11/2008

## SURVEYOR CERTIFICATION

*I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.*

Surveyed By: Ronald Eidson

Date of Survey: 8/11/2008

Certificate Number: 3239

# Permit Comments

Operator: MACK ENERGY CORP , 13837

Well: ARKANSAS STATE #002

API: 30-025-39078

Created By	Comment	Comment Date
JWSHERRELL	H2S concentration of wells in this area from surface to TD are low enough that a contingency plan is not required.	8/11/2008