	7:57:2
	5/5/2021
-	Imaging:
— .	Released to

SIGNATURE TITLE Compliance Coordinator DATE Type or print name Melanie Reyes

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Rig Release Date:

E-mail address: <u>mreyes@legacyreserves.com</u> PHONE: (432) 221-6358

ONDITIONS OF APPROVAL

For State Use Only

diameter 4' tall Above Ground Market

Kerry Forther APPROVED BY: TITLE Compliance Officer A DATE 5/4/21

Conditions of Approval (if any):

Spud Date:


Received by OCD: 3/12/2021 1:47:22 PM

Name of the last o			WELLBORE SCHEMATIC AND HISTORY	
CURRENT	COMPLETION SCH	MATIC	LEASE NAME Cooper Jal Unit	WELL NO. 107
			STATUS; Active Rod Pump - Gas	API# 30-025-09558
	T T		LOCATION: 1650 FSL & 1980 FWL Sec 13, T - 245, R - 365; Lee County, New Mexico	
		1 60	SPUD DATE: TO 3611 KB 3,327 INT. COMP. DATE: 08/26/52 PBTD 3267 GL 3,316	DF
			INT. COMP. DATE: 08/26/52 PBTD 3267 GL 3,316 GEOLOGICAL DATA	
				ES, DST'S or MUD LOGS:
Surface Csq			GR-N (3-23-52 Lane Wells)	
Hole Size: 11 in 3			CBL-GR-MSG-CCL from 3400 - 1500 ft (11-2-94 Haliburton)	
Cog. Size: 8 5/8 in Set @: 252 ft			HYROCARBON SEARING ZONE DEPTH TOPS:	
Sxs Cmt: 200				
Circ: Yes			Yates @ 2970' 7-Rivers @ 3178' Queen @ 3550'	
TOG @: surf		lex .		
TGC by: circ			CASING PROFILE	
		Crnt sqz'd csg	SURF, 8 5/8" - 28#, J-55 set@ 252' Cmt'd w/200 sxs - circ cmt to surf.	
		leak @ 467*	PROD. 5 1/2"-15.5#, J-55 set@ 3426' Cmt'd w/200 sxs - TOC @ 2600' f/ surf. DV tool @1147' - pmp	
		cmt circ to surf	LINER None CURRENT PERFORATION DATA	TOC@ suf by circ
				T 0.100 0044
		ii.		E 3426 - 3611' Isolated below CIBP
· ·	* 1	(*) ***********************************	3070-3120' w/ 4 spf (200 -0.56" holes)	Isolated below CIBP
]	DV tool @ 1147	3405 - 3415' (Isolated below CIBP)	
ì	1 1			
i i	1 1			
			TUBING DETAIL 8/12/04 ROD DETAIL	8/13/04
	1 1			
	1 1		Length (ft) Detail Length (ft)	Detail
w year			2986 92 92 jts - 2 7/8" 6.5#, J-55, 8rd EUE tbg. 26 1	1 1/4" x 22' polish rod w/ 7/8" pin
	1		3 1 1-51/2"TAC 0 1	1 1/4" x 1 1/2" x 12' liner
1		TOC@ 2500	96 3 3 jts - 2 7/8" 6.5#, J-55, 8rd EUE tbg. 20 4	3 -6' & 1-2', 7/8", D78 pony rods
			1 1 1 - 2 7/8" OD - S.N. 1050 42	43 - 7/8", D78 rods
		?	4 1 2.7/8" Perf Sub 1800 72	72 - 3/4", D75 rods
			31 1 1 - 2 7/8" J-55 MA 175 7	7 - 1 1/4", sinker bars
			3123 btm 16 1	2" x 1 1/4" X 15' pmp (No RHR)
			D 1	1 1/4" x 6' gas anchor
		3	, 3087 þim	•
1		3		
		3	WELL HISTORY SUMMARY	
		<u> </u>		
3	S 1	Š.	25-Aug-52 Initial completion interval: 3426 -3611' (7 RVRS/Queen - OH). IP=0 bopd, 0 bwpd, 4.4 MMcfg	pd@AOF. ISITP=932 psi.
	(i) }	1-Jan-55 Attempted to prod, Into int. gas line. Well press too low; showing little light oil. Well flwd by hea	ads into csg head gas line.
	3 - 1		1-Jan-58 Shut-in. (Reclass, LM oil)	
		*	15-Feb-73 Converted to injector. C/O to TD @ 3611' & Perf'd 7 RVRS f/3405 -3415. Acdz'd w/1,500 gals	.
	M I	ÿ.	14-Jul-76 Sqz'd csg leak @ 446' w/ 160 sxs. Had circulation to surfac. Si braden head and sqz'd cmt to	
			Drild out & tst to 1000 psi. OK,	
3		89 80	3-Nov-94 Ran bit & scraper to 3400'. Ran CBL-GR-CCL f/3400 - 1500'. Found TOC @ 2600'. Set CIBP@	2 3302' & dmp 35' cmt op top
		** **	PBTD= 3257'. Spot 500 gals 10% acetic acid f/3120 -3070'. Perf'd using 4" csg gun f /3070-3	
8			(200 - 0.56" holes) Frac well w/ 70,000 gals & 233,280#'s 12/20 sand. PM=3740 - 2150 psi. A	
9	8 B		P15min= 250 psig. C/O sand from 2862'-3262' (PBTD). Placed well on production. Pmp; 0 box	
\$	3 8	8	12-Aug-04 POOH with rods and pump. Pumped 20 bbls of produced water with 5 gallons of de-emulsifier.	
	11	Yates (j. 2970)	Found hole 2 joints above SN. Hydrotest tubing in hole to 7,000# - test good. Set TAC with 18,0	
1		e e	well I/ 2900' to 2900', recovered 12 bbls of water with some iron sulfide, RIH pump & rods, PW	
			and 34 - 3/4" rods due to wear. Note: Found 2 joints with external erosion located across perfor	
1 3		3070'	and the state and to moon room i during a joints mail extension product across perior	ψαφ(1 .3)
3	§ :			
1		■ Jalmat		
9	√3 		CIBP set @ 3020' w/ 35' cmt	Can
		3120"	THE TO SEE THE TOTAL THE PERSON OF THE PERSO	~P
1	3 f			•
	g K	ĝ		
į į	i - 1	8		
Į Š	North teach	् Top of Fill		
į.		8		
Production Csg.		at 3196'	Anhy-113	
Hole Size: 7 7/8 in	XIXIXIX	100@ 3267	T/Salt- 1300	
k Se	lovo-	CISP@ 3302		
Csg. Size: 5 1/2 in	g 1	9	B/Salt-2800 +/-	
Set @: 3426 ft :	3 1	7-R @ 3172'		
Sxs Cmt: 550	g 1	L. M.	Yates- 2980' +/-	
Circ: No	g 1	ř.	7Rvs-3200 +/-	
TOC @: surf	g [2	<u> </u>		
TOC by: eirc	7 .	3405 -15	Queen- 3430 +/-	
1 2		Š		
		OH Interval		
		3426 - 3611'		
		Quaen @ 3550*		
			32.2146034	
			32.219001	
PGTD: 3267 ft			-103.2209549	
TD: 3611 ft			120 0009 KUA	
			- 10 < 22 O I 37 1	
	OH ID; 43/4 tn		1000000	
1	URIO; 43/4 In		700.000	



Legacy-	Proposed		
A thor:	Abby-BCM & Associates, Inc		
₩ell Name	Cooper Jal Unit	Well No.	#107
Field/Pool	Jalmat; Tan-T-7Rvs-Langlie Mattix; Q-Ggbg	API#:	30-025-09558
County	Lea	Location:	Sec 13, T245, R36E
State	New Mexico	******	1650' FSL & 1980'FWL
Spud Date	8/26/1952	GL:	3316'

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	8 5/8	J55	28#	252	11	250	Circ'd
Prod Csg	5 1/2	J55	15.5#	3,426	7 7/8	1,200	Circ'd



8 5/8 28# CSG@ 252 Hole Size: 11

Anhy-113 T/Salt- 1300 B/Salt-2800 +/-Yates- 2980' +/-7Rvs-3200 +/-Queen- 3430 +/-

3. Perf & Sqz 50 sx cmt @ 1300-1097'. WOC & Tag (DV Tool)

- 2. Spot 25 sx cmt @ 2900-2700'. WOC & Tag (Yates)
- 1. Tag existing 5 1/2" CIBP @ 3020 w/ 35' cmt cap on top. Circulate hole w/ MLF. Pressure test csg.

Perfs @ 3070-3120'

CIBP @ 3302'

5 1/2 15.5# CSG @ Hole Size: 7 7/8

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION


Received by OCD: 3/12/2021 1:47:22 PM

			W	ELLBORE SCH	MATIC AND HISTOR	!			
CURRENT COMPLETION SCHEMA	mc La	LEASE NAME		Co	per Jal Unit				WELL NO. 107
		STATUS:	Act			Rod Pump - Gas			API# 30-025-09558
	: LO	LOCATION:	169		W., Sec 13, T - 245, R	- 36E: Lee County	New Mexico	2.00~	
		SPUD DATE: INT. COMP. DA	ATE:	08/26/52 PBT	n 3	611 267	GL K9	3,327	DF
<u>Surface Csq</u> Hole Size: 11 in: Csp. Size: 8 5'B in: Set ⊚: 252 ft	GR	GR-N (3-23-52	ELECTRIC L	.ogs:	liburton)	GEOLOGICAL DA	<u>ita</u>		ES, DST'S or MUD LOGS:
Sxs Cmt: 200 Circ: Yes	Š L		Yates @ 2970	7-R	vers @ 3178	Queen @ 3550	r		
TOC by: cire						CASING PROF	LE		
					nt'd w/200 sxs - circ				
1211 1211				5 set@ 3426'	Cmt'd w/200 sxs - T	OC @ 2600' fl su	rf. DV tool @114	7' - pmp	200 sxs - Sqz csc @ 467*.
	ant circ to surf Life	LINER	None		CURR	ENT PERFORAT	ION DATA		TOC@ suf by circ
	cs	CSG. PERFS	4 -					PEN HO!	.E 3426 - 3611'
'1 1''	tool @ 1147		3070-3120' w/ 4		holes) lated below CIBP)		•		Isolated below CIBP
		TUDING OCT	7.00	0/45/04		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	DOD DETAIL		allaha
	10	TUBING DET	Length (ff)	8/12/04	Detail		ROD DETAIL		8/13/04
		2986 3	92 92	jts - 2 7/8" 6.5 5 1/2" TAC	#, J-55, 8rd EUE tbg	. ,	<u>Length (ft)</u> 26 0	1	Detail 1 1/4" x 22' polish rod w/ 7/8" pin 1 1/4" x 1 1/2" x 12' liner
3	OC@ 2500	96			J-55, 8rd EUE tbg.		20	4	3 -6' & 1-2', 7/8", D78 pony rods
		1		- 2 7/8" OD - S			1050	42	43 - 7/8", D78 rods
		4	1 27	7/8" Perf Sub			1800	72	72 - 3/4", D75 rods
		31	, 1 1-	2 7/8" J-55 M/			175	7	7 - 1 1/4", sinker bars
		3123	btn	n			16	1	2" x 1 1/4" X 15' pmp (No RHR)
							0	1	1 1/4" x 6' gas anchor
							3087 þtr	m	
	<u> </u>								***************************************
	WE	NELL HISTO	RY SUMMARY						
	15- 14- 3-h	15-Feb-73 14-Jul-78 3-Nov-94 12-Aug-04	Sqz'd csg leak @ Drid out & tst to Ran bit & scrape: PBTD= 3267'. Sp (200 - 0.56" hole P16min= 250 psi PCOH with rods Found hole 2 join well # 2900' to 25	ector. C/O to T § 446' w/ 160 s 1000 psi. OK, r to 3400'. Rai pot 500 gals 10 es) Frac well w. ig. C/O sand fn and pump. Pui nts above SN. I 900', recovered	CBL-GR-CCL #344 catic acid #3126 70,000 gals & 233, orn 2862'-3262' (PB' nped 20 bbls of pro fydrotest tubing in h	to surfac. Si brace 00 - 1500'. Found 0 -3070'. Perf'd u 280#'s 12/20 san FD). Placed well o duced water with ole to 7,000# - te th some iron sulfi	ten head and sqz TOC @ 2600'. S sing 4" csg gun d. PM=3740 - 21 on production. Pr 5 gallons of de-er st good. Set TAC de, RIH pump & r	et CIBPE f /3070-3 50 psi, / mp: 0 bo mulsifier. with 18,/	SIP=700 psi, WOC. § 3302' & dmp 35' cml on top. 120' w/ 4 spf NR=40 bpm. ISIP=900 psi, of / 65 bwpd / 357 Mcf, Tagged bottom at 319s, 3004 tension, Swabbed OP. Laid down 8 - 7/8"
	almat 120°	CIT	3P Se	+@	<i>3</i> 020'	w/ 3	35 ¹ Cr	nt	cap
Production Csq. at	15P@ 3302'					Anhy-11 T/Salt-	3		
sg. Size: 5 1/2 in	İ					3/Salt-2	800 ±/		
	R @ 3172'				-				
(C)	. M.				`	Yates- 2	:980' +/-		
Circ: No						7Rvs-32			
TOC @: surf 🕍									
TOC by: eirc 💆 🗮 34	105 -15'				(Queen-	3430 +/	-	
1 1 -	H Interval 426 - 3611'								
Table 1	ucen & 3550°								
					32	214	6034		
P6TD: 3267 ft TD: 3611 ft OHID: 43/4 ft					- 103	. 220	9549	1	
	ļ <u>.</u>					-			
		PREPAREC) 5Y:	Lam	S. Adams	····	lup	DATED:	17-Aug-04



egacy-	Proposed Abby-BCM & Associates, Inc		
Athor:	Abby-BCM & Associates, Inc		
Well Name	Cooper Jal Unit	Well No.	#107
Field/Pool	Jalmat; Tan-T-7Rvs-Langlie Mattix; Q-Ggbg	API#:	30-025-09558
County	Lea	Location:	Sec 13, T24S, R36E
State	New Mexico	*******	1650' FSL & 1980'FWL
Spud Date	8/26/1952	GL:	3316'

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	8 5/8	J55	28#	252	11	250	Circ'd
Prod Csg	5 1/2	J55	15.5#	3,426	7 7/8	1,200	Circ'd



8 5/8 28# CSG@ 252 Hole Size: 11

Anhy-113 T/Salt-B/Salt-2800 +/-Yates- 2980' +/-7Rvs-3200 +/-Queen- 3430 +/-

3. Perf & Sqz 50 sx cmt @ 1300-1097'. WOC & Tag (DV Tool)

- 2. Spot 25 sx cmt @ 2900-2700'. WOC & Tag (Yates)
- 1. Tag existing 5 1/2" CIBP @ 3020 w/ 35' cmt cap on top. Circulate hole w/ MLF. Pressure test csg.

Perfs @ 3070-3120'

CIBP @ 3302'

5 1/2 15.5# CSG @ Hole Size: 7 7/8

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 20671

COMMENTS

Operator:			OGRID:	Action Number:	Action Type:
LEGACY RESI	ERVES OPERATING, LP	15 Smith Road	240974	20671	C-103F
Suite 3000 Mid	dland, TX79705				

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	05/05/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 20671

CONDITIONS OF APPROVAL

Operator:		OGRID:	Action Number:	Action Type:
LEGACY RESERVES OPERATING, LP	15 Smith Road	240974	20671	C-103F
Suite 3000 Midland, TX79705				

OCD Reviewer	Condition
kfortner	See attached conditions of approval