District I		00010			State of N	ew Mexico			Form
1625 N. French I Phone: (575) 393 District II 811 S. First St. 4	r., Hobbs, NM -6161 Fax: (57 rtesia NM 882	88240 5) 393-0720 10		Energy	Minerals an	d Natural R	esources		Revised July 18
Phone: (575) 748 District III	1283 Fax: (575	6) 748-9720		<b>Oil Conservation Division</b>					IENDED REPO
1000 Rio Brazos Phone: (505) 334	Road, Aztec, N -6178 Fax: (505	M 87410 i) 334-6170		İ	1220 South S	t. Francis D	r.		
District IV 1220 S. St. Franc	s Dr., Santa Fe	NM 87505			Santa Fe,	NM 87505			
APPL]	CATIC	ON FOR	PERMIT 1	TO DRILL,	RE-ENTEI	R, DEEPEN	, PLUGBAC	CK, OR ADD	A ZONE
APPL	CATIC	ON FOR	PERMIT 7 <sup>1</sup> Operator Name SOLIS PARTN P.O. BOX MIDLAND 7	and Address ERS L.L.C. 5790 78 79704	RE-ENTER	R, DEEPEN	, PLUGBAC	CK, OR ADD <sup>2</sup> OGRID Number 330238	A ZONE
APPL	CATIC	ON FOR	PERMIT 7 <sup>1</sup> Operator Name SOLIS PARTN P.O. BOX MIDLAND 7	and Address ERS L.L.C. 5790 TX 79704	RE-ENTE	R, DEEPEN	, PLUGBAC	CK, OR ADD <sup>2</sup> OGRID Number 330238 <sup>3</sup> API Number 30-005-62775	A ZONE
4. Prop 32	CATIC erty Code 9356	ON FOR	PERMIT 7 <sup>1</sup> Operator Name SOLIS PARTN P.O. BOX MIDLAND 7	TO DRILL, and Address ERS L.L.C. 5790 TX 79704 PATH	Property Name	<b>R, DEEPEN</b>	, PLUGBAC	CK, OR ADD <sup>2</sup> OGRID Number 330238 <sup>3</sup> API Number 30-005-62775 <sup>6</sup> Well 7	A ZONE
APPL	CATIC erty Code 9356	ON FOR	PERMIT 7 <sup>1-</sup> Operator Name SOLIS PARTN P.O. BOX MIDLAND 7	TO DRILL, and Address ERS L.L.C. 5790 TX 79704 PATH <sup>7</sup> St	RE-ENTER <sup>5</sup> Property Name FINDER AFT STA Irface Location	R, DEEPEN	, PLUGBAC	CK, OR ADD <sup>2</sup> OGRID Number 30238 <sup>3</sup> API Number 30-005-62775 6. Well 7	A ZONE
4. Prop 32	CATIC erty Code 9356	DN FOR	PERMIT 1 Operator Name SOLIS PARTN P.O. BOX MIDLAND 1 Range	TO DRILL, and Address ERS L.L.C. 5790 TX 79704 PATH 7. St Lot Idn	Property Name FINDER AFT STA	R, DEEPEN	Feet From	CK, OR ADD <sup>2</sup> OGRID Number 330238 <sup>3</sup> API Number 30-005-62775 <sup>6</sup> Well 7 E/W Line	A ZONE

F	21	10-S	27-Е		2,310	NORTH	1,650	WEST	CHAVES
				<sup>9.</sup> Po	ol Informatio	n			9999
				Pool 1	Name				Pool Code
				DIABLO; SA	N ANDRES				17640

N/S Line

NORTH

Feet From

E/W Line

County

Feet from

2,310

<sup>11.</sup> Work Type	<sup>12</sup> Well Type	<sup>13.</sup> Cable/Rotary	<sup>14.</sup> Lease Type	<sup>15</sup> . Ground Level Elevation
P	O	R	S	3,835'
<sup>16</sup> Multiple	<sup>17.</sup> Proposed Depth 2,260'	<sup>18.</sup> Formation	<sup>19</sup> Contractor	<sup>20.</sup> Spud Date
NO		SAN ANDRES	LIBERTY PUMP	06/07/2021
n to Ground water	Distance f	rom nearest fresh water well	Distance to r	learest surface water

 $\mathbf{x}$  We will be using a closed-loop system in lieu of lined pits

UL - Lot

F

Section

21

Township

10-S

Range

27-E

Lot Idn

<sup>21.</sup> Proposed Casing and Cement Program

Туре	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC
PROD CSG	7.875"	5.5"	15.5# J-55 STC	2,670'	475 sx	SUFACE – CIRC 38 sx
(actual csg &						
cmt data)						
		<b>C</b>	10 I D	11		A

#### **Casing/Cement Program: Additional Comments**

## 22. Proposed Blowout Prevention Program

Туре	Working Pressure	Test Pressure	Manufacturer
MANUAL/ HYDRAULIC	5,000 psi	5,000 psi	CAMERON

<sup>23.</sup> I hereby certify that the information given above is true and complete to the best of my knowledge and belief.	OIL CC	INSERVATION DIVISION
I further certify that I have complied with 19.15.14.9 (A) NMAC and/or 19.15.14.9 (B) MAC , if applicable. Signature:	Approved By:	
Printed name: Debi Garza	Title:	
Title: Regulatory Coordinator	Approved Date:	Expiration Date:
E-mail Address: debi.garza@solipartnersllc.com		
Dates 05/02/2021 9: 5 Phone: 47-888-1880	Conditions of Approval Attac	thed

### PATHFINDER AFT STATE #7: RE-ENTER P&A'd WELL & RECOMPLETE IN SAN ANDRES:

Page 2 of 11

- Remove Dry Hole Marker at well, dig out well casing for tie-back.
- MIRU workover rig.
- Tie-back 8-5/8" Surface Casing with bradenhead and 5-1/2" casing hanger. Tie-back and land 5-1/2"
- Production Casing in casing hanger, pulling tension to set slips.
- Re-enter P&A'd wellbore, drilling out 15-sack cmt surface plug (0-67') and 25-sack cement plug across base of Surface Casing (512'-628').
- Clean-Out wellbore with bit and casing scraper to PBTD at +/- 2,230', top of 50-sack cement plug 2,230'-2,620', across Basal San Andres/Glorietta perfs 2488'-2626'. Circulate hole clean using reverse unit and tank.
- Pressure test 5-1/2" casing and CIBP to 500 psig for 30 minutes with chart.
- Dress-off top of cement plug from 2,230' to 2,270'.
- Run CBL log in well from 1,000' 2,270'.
- Set 5-1/2" CIBP on wireline above cement plug at 2,260' and dump bail 35' cement cap on plug. Basal SA/Glorietta perfs 2488'-2626' (63' 33 perfs). PBTD = 2,215' (TOC).
- Pressure test 5-1/2" casing and CIBP to 500 psig for 30 minutes with chart.
- Perforate San Andres: 2,020'-2,161' (97' @ 2spf 194 perfs).
- Acidize SA perfs with approx. 18,000 gal 20% NEFE HCI + additives.
- Flowback well, swab if necessary, to clean up.
- RIH with 2-3/8" 4.7# J-55 EUE tubing, rods, and pump. Hang well on for production.
- RDMO workover rig.
- Test well.

# CONDITIONS FOR PLUGGING AND ABANDONMENT

### OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E)Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - I) Glorieta
  - J) Yates.
  - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

#### DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

#### SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Phone: (505) 334-6178 Fax: (505) 334-6170

1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

District IV

Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

AMENDED REPORT

none. (565) 176 5 165 1		W	VELL LO	CATIO	ON AND ACR	EAGE DEDIC	ATION PLA	Т	
<sup>1</sup> A 30-	PI Number	15		<sup>2</sup> Pool Co 1764	ode O	Γ	<sup>3</sup> Pool Nan DIABLO; SAN	ne ANDRES	
<sup>4</sup> Property C 329356	ode				<sup>5</sup> Property N PATHFINDER	Name AFT STATE		6 V	Vell Number 7
<sup>7</sup> OGRID N 330238	0.				<sup>8</sup> Operator 1 SOLIS PARTNE	Name ERS, L.L.C.		9	Elevation 3,835'
					Surface 1	Location			
UL or lot no. F	Section 21	Townshi	ip Range 27-E	Lot Io	In Feet from the 2,310	North/South line NORTH	Feet from the 1,610	East/West line WEST	County CHAVEZ
		10-	-S						8
				<sup>11</sup> Botte	om Hole Location If	Different From Sur	face		State 1
III, or lot no.	Section	Townshi	ip Range	Lot I	dn Feet from the	North/South line	Feet from the	East/West line	County
F	21	10-S	27-E		2,310	NORTH	1,610	WEST	CHAVEZ
<sup>12</sup> Dedicated Acres	<sup>13</sup> Joint o	r Infill	<sup>4</sup> Consolidation	Code <sup>16</sup>	Order No.				
40			×					7	

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

15	2,3101		<sup>17</sup> <b>OPERATOR CERTIFICATION</b> I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
62,650'		12	Debi Garza   Debi Garza   Printed Name   debi.garza@solispartnersllc.com   E-mail Address
			*SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.
			Signature and Seal of Professional Surveyor:

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Department

Submit Original to Appropriate District Office

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

### GAS CAPTURE PLAN

Date: 3/10/2021

 $\boxtimes$  Original

Operator & OGRID No.: [330238] SOLIS PARTNERS L.L.C.\_\_

□ Amended - Reason for Amendment:\_

This Gas Capture Plan outlines actions to be taken by the Operator to reduce well/production facility flaring/venting for new completion (new drill, recomplete to new zone, re-frac) activity.

Note: Form C-129 must be submitted and approved prior to exceeding 60 days allowed by Rule (Subsection A of 19.15.18.12 NMAC).

#### Well(s)/Production Facility – Name of facility

The well(s) that will be located at the production facility are shown in the table below.

Well Name	API	Well Location (ULSTR)	Footages	Expected MCF/D	Flared or Vented	Comments
PATHFINDER AFT STATE #7	30-005- 62775	F-21-10S-27E	2310N 1650W	10	NONE	FLOW TO BATTERY & SALES METER

#### **Gathering System and Pipeline Notification**

Well(s) will be connected to a production facility after flowback operations are complete, if gas transporter system is in place. The gas produced from production facility is dedicated to <u>IACX ROSWELL</u> and will be connected to <u>IACX ROSWELL</u> low pressure gathering system located in <u>\_\_\_\_\_\_\_\_CHAVEZ\_\_\_\_\_\_</u>County, New Mexico. It will require <u>\_\_\_\_\_\_\_</u>' of pipeline to connect the facility to low pressure gathering system. SOLIS PARTNERS L.L.C. provides (periodically) to <u>IACX ROSWELL</u> a drilling, completion and estimated first production date for wells that are scheduled to be drilled in the foreseeable future. In addition, SOLIS PARTNERS L.L.C. and <u>IACX ROSWELL</u> have periodic conference calls to discuss changes to drilling and completion schedules. Gas from these wells will be processed at <u>IACX PATHFINDER AMINE</u> Processing Plant located in Sec.\_\_21\_\_\_, Twn.\_10S\_\_\_\_, Rng.\_\_27E\_\_\_, <u>\_\_\_\_CHAVEZ\_\_\_\_</u>County, New Mexico. The actual flow of the gas will be based on compression operating parameters and gathering system pressures.

#### **Flowback Strategy**

After the fracture treatment/completion operations, well(s) will be produced to temporary production tanks and gas will be flared or vented. During flowback, the fluids and sand content will be monitored. When the produced fluids contain minimal sand, the wells will be turned to production facilities. Gas sales should start as soon as the wells start flowing through the production facilities, unless there are operational issues on <u>IACX ROSWELL</u> system at that time. Based on current information, it is SOLIS PARTNER L.L.C.'s belief the system can take this gas upon completion of the well(s).

Safety requirements during cleanout operations from the use of underbalanced air cleanout systems may necessitate that sand and non-pipeline quality gas be vented and/or flared rather than sold on a temporary basis.

#### **Alternatives to Reduce Flaring**

Below are alternatives considered from a conceptual standpoint to reduce the amount of gas flared.

- Power Generation On lease
  - Only a portion of gas is consumed operating the generator, remainder of gas will be flared
  - Compressed Natural Gas On lease
    - Gas flared would be minimal, but might be uneconomical to operate when gas volume declines
- NGL Removal On lease
  - o Plants are expensive, residue gas is still flared, and uneconomical to operate when gas volume declines



Page 7 of 11



# SOLIS PARTNERS, LLC

WELLBORE DIAGRAM



-
-
and the second s
-
C
and the second s
100
<u> </u>
-
-
00
The second second
5
-
The second
0
-
0
2.1
· ·
-
N.
S.
Ś
5
: 5
0:5/
D: 5/
D: 5/
CD: 5/
CD: 5/
)CD: 5/
0CD: 5/
0CD: 5/
0CD: 5/
v OCD: 5/
y OCD: 5/
by OCD: 5/
by OCD: 5/
1 by OCD: 5/
d by OCD: 5/
d by OCD: 5/
ed by OCD: 5/
ved by OCD: 5/
ved by OCD: 5/
ived by OCD: 5/
vived by OCD: 5/
eived by OCD: 5/
ceived by OCD: 5/
ceived by OCD: 5/
eceived by OCD: 5/
eceived by OCD: 5/
Received by OCD: 5/
Received by OCD: 5/

. 1	-
	-
	0
	_
	-
	~
	0
	2
	0/
	-
	9
- 1	
	<b>Second</b>

1	
1	
1	
1	
l	
Į.	
Į.	
l	
l	
l	
Į.	
I	
I	
I	
I	-
I	
	-
I	-
I	
I	2
	8
	8
	P&
	(P&
	(P&
	7 (P&
	7 (P&
	07 (P&
	07 (P&
	007 (P&
	#007 (P&
	#007 (P&
	#007 (P&
	E #007 (P&
	E #007 (P&
	TE #007 (P&
	VTE #007 (P&)
	ATE #007 (P&
	TATE #007 (P&)
	TATE #007 (P&)
	STATE #007 (P&)
	STATE #007 (P&)
	STATE #007 (P&)
	T STATE #007 (P&)
	T STATE #007 (P&)
	FT STATE #007 (P&)
	<b>VET STATE #007 (P&amp;</b> )
	AFT STATE #007 (P&)
	AFT STATE #007 (P&
	3 AFT STATE #007 (P&)
	R AFT STATE #007 (P&)
	ER AFT STATE #007 (P&)
	ER AFT STATE #007 (P&)
	DER AFT STATE #007 (P&)
	DER AFT STATE #007 (P&)
	VDER AFT STATE #007 (P&)
	NDER AFT STATE #007 (P&)
	INDER AFT STATE #007 (P&)
	FINDER AFT STATE #007 (P&)
	FINDER AFT STATE #007 (P&)
	HEINDER AFT STATE #007 (P&)
	HFINDER AFT STATE #007 (P&)
	THFINDER AFT STATE #007 (P&)
	THFINDER AFT STATE #007 (P&)
	ATHFINDER AFT STATE #007 (P&)
	ATHFINDER AFT STATE #007 (P&)

WELL PERFORATION, ACID JOB, FRAC JOB, & WELL TEST DETAILS

	WATER <u>BWPD</u>	AS E AS SWD			
VTIAL TEST	GAS MCFD	of oil & g ) complet	SWD.	SWD.	
ITIAL POTE	BOPD	NO SHOWS DECIDED TC	Returned to	Returned to	
Z	TEST <u>DATE</u>	8/8/1990			
ACID JOB(S) FRAC JOB(S)	REMARKS				
	SAND <u>SIZE</u>		20/40 10/20		
	SAND LBS		72,500 16,000		
	FLUID	2	MY-T Gel		
	FRAC FLUID <u>GALS</u>	t it ks & Ball Sealer	60,000		
	DATE	1st Treatmeni 3all Sealers 2nd Treatmen 1000# Salt Bloc.	10/29/1990	itor	
	ACID <u>TYPE</u>	20% NEFE HCI In 3 Stages w/ I 20% NEFE HCI In 3 Stages w/ I		15% NEFE HCI + Paraffin Inhib	
	ACID GALS	3,000 15,000		1,000	
	DATE	8/8/1990 8/8/1990		2/19/1991	
PERFS	ZONE	(19') BASAL SA (25') BASAL SA (19') GLORIETTA	(19') BASAL SA (25') BASAL SA (19') GLORIETTA	(19') BASAL SA (25') BASAL SA (19') GLORIETTA	
	BOTTOM	2,506 2,580 2,626	2,506 2,580 2,626	2,506 2,580 2,626	
	TOP	2,488 2,556 2,608	2,488 2,556 2,608	2,488 2,556 2,608	

COMPLETION & TEST DETAILS Released to Imaging: 5/21/2021 9:53:11 AM

PATHFINDER AFT STATE #007 (P&A'd) - WBDiagram - 12-20-2020

District II

District IV

District I 1625 N. French Dr., Hobbs, NM 88240

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410 COMMENTS

Action 26988

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS	

Operator:			OGRID:		Action Number:	Action Type:
SOLIS PARTNERS, L.L.C.	P.O. Box 5790	Midland, TX79704	3302	238	26988	APD
Created By	Comment			Comment	Date	
kpickford	KP GEO Review 5/10/2021			05/10/202	1	

District II

District IV

District I 1625 N. French Dr., Hobbs, NM 88240

Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410

CONDITIO	DNS

Action 26988

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

#### CONDITIONS OF APPROVAL

	P.O. Box 5700 Midland TX79704	OGRID: 330238	Action Number:	Action Type:
SOLIST ARTINERS, E.E.C.		330230	20900	AID
OCD Reviewer	Condition			
ksimmons	See Attached COA's and Plugging Procedures.			