Received by UCD \$3/30/2021 8:06:08 AM U.S. Department of the Interior		Sundry Print Report
BUREAU OF LAND MANAGEMENT		1988 - AV. 200
Well Name: BISTI GALLUP 22 COM	Well Location: T25N / R12W / SEC 22 / NWNE / 36.391517 / -108.097271	County or Parish/State: SAN JUAN / NM
Well Number: 2	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM25449	Unit or CA Name: 2 BISTI GALLUP 22	Unit or CA Number: NMNM121553
US Well Number: 3004534209	Well Status: Oil Well Shut In	Operator: DJR OPERATING LLC

Notice of Intent

Type of Submission: Notice of Intent

Date Sundry Submitted: 08/16/2021

Date proposed operation will begin: 08/16/2021

Type of Action Plug and Abandonment Time Sundry Submitted: 01:18

Procedure Description: DJR Operating, LLC requests permission to Plug & Abandon the subject well according to the attached Procedure, Current & Proposed Wellbore Diagram and Reclamation Plan.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Reclamation_Plan__Bisti_Gallup_22_COM_2_20210816131806.pdf PXA_Procedure_Bisti_Gallup_22_COM_2_20210816131806.pdf Current_WBD_Bisti_Gallup_22_COM_2_20210816131806.pdf Proposed_WBD_Bisti_Gallup_22_COM_2_20210816131806.pdf

R	eceived by OCD: 8/30/2021 8:06:08 AM Well Name: BISTI GALLUP 22 COM	Well Location: T25N / R12W / SEC 22 / NWNE / 36.391517 / -108.097271	County or Parish/State: SAIN	
	Well Number: 2	Type of Well: OIL WELL	Allottee or Tribe Name:	
	Lease Number: NMNM25449	Unit or CA Name: 2 BISTI GALLUP 22	Unit or CA Number: NMNM121553	
	US Well Number: 3004534209	Well Status: Oil Well Shut In	Operator: DJR OPERATING LLC	

Conditions of Approval

Additional Reviews

25N12W10EKg_Central_Bisti_Unit_60_20210827173210.pdf

General_Requirement_PxA_20210827173056.pdf

2629149_NOIA_COM_2_300454209_KR_08272021_20210827173038.pdf

State: NM

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: SHAW-MARIE FORD

Name: DJR OPERATING LLC

Title: Regulatory Specialist

Street Address: 1 Road 3263

City: Aztec

Phone: (505) 632-3476

Email address: sford@djrllc.com

Field Representative

Representative Name:	
Street Address:	
City:	State:
Phone:	
Email address:	

Zip:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK BLM POC Phone: 9708783846 Disposition: Approved Signature: Kenneth Rennick BLM POC Title: Petroleum Engineer

BLM POC Email Address: krennick@blm.gov

Disposition Date: 08/27/2021

Signed on: AUG 16, 2021 01:18 PM

Plug and Abandonment Procedure

for

DJR Operating, LLC Bisti Gallup 22-2 API # 30-045-34209 NW/NE, Unit B, Sec. 22, T25N, R12W San Juan County, NM

I.


- 1. Hold Pre job meeting, comply with all NMOCD, BLM and environmental regulations.
- 2. MIRU prep rig.
- 3. Check and record tubing, casing and bradenhead pressures.
- 4. Remove existing piping from casing valve, RU blow lines from casing valves and blow down casing pressure. Kill well as necessary. Ensure that well is dead or on a vacuum.
- 5. MIRU hot oil unit, pump hot water to clear rods and tubing of paraffin.
- 6. Trip out of hole with rods and pump. Lay down to be sent in for storage/salvage.
- 7. Unset TAC.
- 8. ND WH, NU BOP, function test BOP.
- 9. Trip out of hole with 2 3/8" tubing. LD tubing to be sent in for storage/salvage.
- 10. RDMO prep rig to next location.

II.

- 11. MIRU P&A rig and equipment.
- PU 2-3/8" workstring, TIH with bit and scraper, make sure that the bit and scraper will go to 4938'. Drop standing valve. Pressure test tubing to 1000 psi. Recover standing valve. TOOH.
- 13. Plug 1. Perforations and Gallup: RU cement equipment.
- 14. TIH to 4938'. Mix and spot a 265' plug of Class G cement from 4938' to 4673'.

- 15. Tag TOC. Roll hole. Pressure test casing to 600 psi. If casing does not test, contact engineering.
- 16. Plug 2. Mancos: Mix and spot a 100' balanced plug of Class G cement from 3884' to 3784'.
- 17. Plug 3. Cliff House: Mix and spot a 100' balanced plug of Class G cement from 2337' to 2237'.
- 18. Plug 4. Chacra: Mix and spot a 100' balanced plug of Class G cement from 1612' to 1512'.
- 19. Plug 5: Pictured Cliffs, Fruitland, and Kirtland: Mix and spot a 677' balanced plug of Class G cement from 1275' to 598'.
- 20. Plug 6: Surface casing shoe: Mix and spot balanced plug from 400' to surface with Class G cement.
- 21. RD cementing equipment. Cut off wellhead, fill any exposed annulus with cement as necessary. Install P&A marker as per regulatory requirements. Record GPS coordinates for P&A marker and the Final P&A Report. Photograph the P&A marker and attach to the report.
- 22. RD and MO all rig and cement equipment. Assure that location is free of trash and contamination before moving off.
- 23. Send all reports and attachments to DJR Aztec office for regulatory filings.

Note: All cement is to be Class G mixed at 15.8 ppg, yield 1.15 cu ft / sx. Cement volumes are based on inside capacities + 50' excess and outside capacities + 100% excess.




Proposed Wellbore P&A Diagram DJR Operating, LLC

Bisti Gallup 22-2

API # 30-045-34209 NW/NE, Unit B, Sec 22, T25N, R12W San Juan County, NM

GL	6391'
KB	6403'
Spud Date	2/9/2008



GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.

- 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
- 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)

3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.

3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.

4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.

- 4.1 The cement shall be as specified in the approved plugging plan.
- 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
- 4.3 Surface plugs may be no less than 50' in length.
- 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
- 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
- 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

Page 1

2

5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.

- 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
- 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
- 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
- 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.

6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.

- 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
- 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.

7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .

8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show <u>date</u> well was plugged.

9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.

10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Bisti Gallup 22 Com 2

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Adjust Plug 1 so that the balance plug will be from 4988 to 4673 feet. 50 feet below the bottom perforation at 4938 feet.
 - b) Adjust or lengthened Plug 3 to cover BLM pick for the top of the Mesa Verde (Cliff House) pick at 1976 feet.
 - c) Plug 5 should be brought up to 500 feet to cover the BLM Ojo Alamo pick at 550 feet.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 8/27/2021

BLM FLUID MINERALS Geologic Report

Date Completed: 7/27/2021

Well No. Central Bisti Unit 60 (API# 30-045-05492)			Location	1980	FNL	&	660	FWL
Lease No.	14-20-603-1449		Sec. 10	T25N				R12W
Operator	DJR Operating, LLC		County	San Juan		State	New Mexico	
Total Depth	4970'	PBTD 4911'	Formation	Gallup (I	Mancos)			
Elevation (GL)	6207'		Elevation (K	B) 6219'				

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose Fm					
Nacimiento Fm			Surface	411	Surface/Fresh water sands
Ojo Alamo Ss			411	593	Aquifer (fresh water)
Kirtland Shale			593	796	
Fruitland Fm			796	1120	Coal/Gas/Possible water
Pictured Cliffs Ss			1120	1155	Gas
Lewis Shale			1155	1465	
Chacra			1465	1862	
Cliff House Ss			1862	1988	Water/Possible gas
Menefee Fm			1988	3602	Coal/Ss/Water/Possible O&G
Point Lookout Ss			3602	3773	Probable water/Possible O&G
Mancos Shale			3773	4680	
Gallup			4680	PBTD	O&G/Water
Graneros Shale					
Dakota Ss					O&G/Water

<u>Remarks:</u> P & A

- BLM picks for the tops of the Gallup, Cliff House/Mesaverde and Chacra formations vary from operator picks. See recommended plug adjustments below.
- Bring the top of Plug #3 to 1812' to cover BLM pick for the top of the Cliff House/Mesaverde.

Bring the top of Plug #4 to 1415' to cover BLM pick for the top of the Chacra.

- Log analysis of reference well #2 indicates the Nacimiento and Ojo Alamo sands investigated likely contain fresh water (≤5,000 ppm TDS). P&A procedure has adequate plugs to protect any freshwater sands in this well bore.
- Gallup perforations @ 4682' 4854'.

Reference Well: 1) Formation Tops Same

2) Water Analysis

Giant E & P Co. Carson Unit #23 1980' FSL, 1980' FEL Sec. 19, T25N, R11W GL 6438' KB 6447'

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DJR OPERATING, LLC	371838
1 Road 3263 Action Number:	
Aztec, NM 87410	45024
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	9/1/2021
kpickford	Adhere to BLM approved plugs	9/1/2021

CONDITIONS

Page 11 of 11

Action 45024