ceived by Och: Apply 12022 1:29:54	State of New Mex	xico		For	m C-103 ¹ of 3	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCEDUATION	DIMIGION	30-025-283			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NWI 87	303		& Gas Lease No.		
87505	ICEG AND DEPONIES ON WELLS		19520	TT '. A	, NI	
(DO NOT USE THIS FORM FOR PROPORTION OF THE PROP	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO			me or Unit Agreemer	it Name	
PROPOSALS.) 1. Type of Well: Oil Well ✓ Gas Well ☐ Other			8. Well Number 149			
Name of Operator Occidental Permian LTD			9. OGRID N 157984	Number		
3. Address of Operator				ne or Wildcat		
P.O. Box 4294 Houston, TX 7	7210-4294		HOBBS; GR	AYBURG-SAN ANI	DRES	
4. Well Location	_					
Unit Letter A :	150 feet from the N	line and		et from theE	line	
Section 9	Township 19S Rai	•	NMPM	County LEA		
	11. Elevation (Show whether DR, 3620'		' I			
	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC	COMMENCE DRI CASING/CEMENT OTHER: ertinent details, and . For Multiple Cor	K LLING OPNS. F JOB [t dates, including est	imated date	
Spud Date: 8/31/21 I hereby certify that the information	Rig Release Dat		e and belief.			
		_				
SIGNATURE Roni Math	hewTITLE Regula	tory Advisor		DATE <u>07/21/20</u>	22	
Type or print name Roni Mathew For State Use Only	E-mail address:	roni_mathew@	oxy.com	_ PHONE: <u>(713) 2</u>	<u>15-7827</u>	
APPROVED BY:_ Yeary For Conditions of Appro	itherTITLE_ Con	pliance off	ien A-	DATE 9/12/22		

SHOU 149A09 API: 30-025-28352 Convert to ESP 8/31/2021 - 09/03/2021

8/31/2021: Miru pu and rev unit, Check psi, 1200 psi on tbg, 600 psi on casing, Ruwl, Rih w fishing tool and tagged @37', Worked tool on tight spot but would not go thru, Pooh, Pumped 25 bbls of 10# brine water thru tubing, Rih and fished pardigm jet pump, Dragged out of the hole, Pooh and rdwl, Circulated well with 120 bbls of 10# brine water, Ruwl, Rih and broke disk in jet pump standing valve, Pooh and rdwl, Pumped 50 bbls of 10# brine water down tbg, Well stayed w 0 psi, Nd wh, Nu bop, Ru workfloor, Sion.

9/1/2021: Check psi, 300 psi on tbg, 300 psi on csg, Killed well, Released 5-1/2" lockset packer, Pooh w 129 2-7/8" tbg, jet pump bha, 1 2-7/8" tbg and 5-1/2" lockset packer, Ruwl, Rih w 4.4" gauge run and tagged @4298', Pooh, Rih w 3-1/8" perf guns and perforated 5-1/2" casing from 4143'- 49', Pooh, Rih w .17" perf gun and shot perf @4108', Perf gun did not shoot, Pooh, Waited on new gun for 30 min, Rih w .17" perf gun and perforated 5-1/2" casing @4108', Pooh and rdwl, Rih w 4-3/4" bit, 4-3/4" string mill and 130 2-7/8" tbg, Picked up 6 2-7/8" tbg, Tagged w bit @4298', Rups, Nu sh, Cleaned out asphaltenes from 4298' to 4335', Circ well clean, Rdps, Nd sh, Pooh 40 2-7/8" tbg, Sion.

9/2/2021: Htgsm, Check psi, 200 psi on tbg, 200 psi on csg, Killed well, Pooh w 86 2-7/8" tbg and 4-3/4" bit & string mill, Rih w 5-1/2" packer & plug and 130 2-7/8" tbg, Set 5-1/2" rbp @4152', Ru acid trucks, Acid stim new perfs from 4143-49' w/ 500 gals of 15% pad acid, Released tools, Set rbp @4130' and packer @4100', Acid stim new perf @4108', Flushed tbg, Rd acid trucks, Pooh w 129 2-7/8" tbg and 5-1/2" packer & plug, Rih w 2-7/8" jet wash tool and 136 2-7/8" tbg to 4335', Ru acid trucks, Htgsm, Water washed existing perfs from 4154' - 4338' w 140 bbls of fresh water, Acid washed perfs with 4000 gals of 15% pad acid, Rd acid trucks, Pooh to check valve, Flushed casing w 65 bbls of 10# brine water, Sion.

9/3/21: Circulated wellbore down flowline x POH with Tools x assm ESP x RIH w/ CT line x Landed ESP Tbg. Hangar x QCI Hooked up Feed through x N/D Hydrill & BOP x Hooked up Swing Arm x Rig Down Pulling unit.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 127821

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	127821
	Action Type:
	[C-103] Sub. Workover (C-103R)

CONDITIONS

Created By		Condition Date
kfortner	None	9/12/2022