

Submit a Copy To Appropriate District  
Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-37813
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B0-1565
7. Lease Name or Unit Agreement Name Black Bass State
8. Well Number 1
9. OGRID Number 265378
10. Pool name or Wildcat Hume Queen West
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4157' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator: George A. Chase Jr. DBA; G and C Service	
3. Address of Operator P O Box 1618 ; Artesia, NM 88211	
4. Well Location Unit Letter C : 75 feet from the North line and 1650 feet from the West line Section 24 Township 16S Range 33E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4157' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	PNR <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached plugging report for the Black Bass State # 1.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory A. Chase TITLE Op Admin DATE 08/26/2022

Type or print name Gregory A. Chase E-mail address: chevyc08@hotmail.com PHONE: 575-703-6604

**For State Use Only**

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 9/21/22  
Conditions of Approval (if any):

**Plugging Report  
Black Bass State #1  
API 30-025-37813**

6/24/2022      Moved in rig, backhoe, wireline and plugging tank. Set large matting board and rigged up. Nipple down the tubing and unseated the pump. Laid down 100 rods. Shut down.

6/27/2022      Finish laying down the rods. Installed the BOP and POOH with tubing. 128 joints of 2 7/8" tubing. Made gauge ring run and set 5 1/2" CIBP at 3850'. Tagged CIBP with tubing, circulated MLF and spot 35 sx cement on top of CIBP. POOH and SION.

6/28/2022      Tagged cement at 3502'. Spot 25 sx cement at 2702'. POOH and perforated casing at 1556'. Moved perforation down to be 50' below the surface shoe. Set packer and established rate. Started pumping cement. Returns started to come to the pit from the casing annulus. Circulated cement out of the hole to the pit. POOH with tubing and packer. Found a split joint. Reset packer and pressured up to 500# and held without losing pressure. POOH with packer and RIH with tubing to 1606' and spot 25 sx cement. POOH and SION

6/29/2022      Tagged cement at 1382'. POOH and perforated at 110'. Pressured up on perforations to 550# and held without drop. RIH with tubing to 161' and circulated cement to surface with 15 sx. Laid down remaining tubing and rigged down. Dug out and removed the wellhead. Good existing cement in the 8 5/8" casing. Filled up 5 1/2" casing with less than 1 sack of cement. Installed standard marker, removed the anchors, and cleaned the pit.

Submit a Copy To Appropriate District  
Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-37813
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B0-1565
7. Lease Name or Unit Agreement Name Black Bass State
8. Well Number 1
9. OGRID Number 265378
10. Pool name or Wildcat Hume Queen West
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4157' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator: George A. Chase Jr. DBA; G and C Service	
3. Address of Operator P O Box 1618 ; Artesia, NM 88211	
4. Well Location Unit Letter C : 75 feet from the North line and 1650 feet from the West line Section 24 Township 16S Range 33E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4157' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached plugging report for the Black Bass State # 1.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory A. Chase TITLE Op Admin DATE 08/26/2022

Type or print name Gregory A. Chase E-mail address: chevyc08@hotmail.com PHONE: 575-703-6604

**For State Use Only**

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Conditions of Approval (if any):

**Plugging Report  
Black Bass State #1  
API 30-025-37813**

6/24/2022      Moved in rig, backhoe, wireline and plugging tank. Set large matting board and rigged up. Nipple down the tubing and unseated the pump. Laid down 100 rods. Shut down.

6/27/2022      Finish laying down the rods. Installed the BOP and POOH with tubing. 128 joints of 2 7/8" tubing. Made gauge ring run and set 5 1/2" CIBP at 3850'. Tagged CIBP with tubing, circulated MLF and spot 35 sx cement on top of CIBP. POOH and SION.

6/28/2022      Tagged cement at 3502'. Spot 25 sx cement at 2702'. POOH and perforated casing at 1556'. Moved perforation down to be 50' below the surface shoe. Set packer and established rate. Started pumping cement. Returns started to come to the pit from the casing annulus. Circulated cement out of the hole to the pit. POOH with tubing and packer. Found a split joint. Reset packer and pressured up to 500# and held without losing pressure. POOH with packer and RIH with tubing to 1606' and spot 25 sx cement. POOH and SION

6/29/2022      Tagged cement at 1382'. POOH and perforated at 110'. Pressured up on perforations to 550# and held without drop. RIH with tubing to 161' and circulated cement to surface with 15 sx. Laid down remaining tubing and rigged down. Dug out and removed the wellhead. Good existing cement in the 8 5/8" casing. Filled up 5 1/2" casing with less than 1 sack of cement. Installed standard marker, removed the anchors, and cleaned the pit.

George A. Chase Jr. DBA; G and C Service  
OGRID: 265378

Black Bass State # 1  
24-16S-33E  
75' FNL & 1650' FWL  
30-025-37813

Plugs:

Plug 4: perforate and sqz @161' cmt  
to the surface with 15sx cmt

Plug 3: perforate @ 1,606' sqz 25sx cmt.  
to cover shoe

Plug 2: 25sx top of Yates @ 2702'

Plug 1: 35 sx @ 3502'  
CIBP @ 3850'

Existing Wellbore:

8 5/8" 24# @ 1,506'  
800sx cement

Formation Tops:

Yates	2746'
Queen	3618'
San Andres	4435'

: Perforations: 3913-3938'

Cement 35' Cap

: Perforations 4477'-5107'

5 1/2" 17 # casing to 5,934' 1638 sx cement

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

COMMENTS

Action 138615

COMMENTS

Operator: GEORGE A CHASE JR DBA G AND C SERVICE P.O. Box 1618 Artesia, NM 88211	OGRID: 265378
	Action Number: 138615
	Action Type: [C-103] Sub. Plugging (C-103P)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	9/22/2022

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 138615

CONDITIONS

Operator: GEORGE A CHASE JR DBA G AND C SERVICE P.O. Box 1618 Artesia, NM 88211	OGRID: 265378
	Action Number: 138615
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Need C103Q and marker pics to release	9/21/2022