

Submit 1 Copy To Appropriate District
Office

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>WELL API NO. 30-025-28605</p>
<p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/></p>		<p>5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/></p>
<p>2. Name of Operator Mark L. Shidler, Inc.</p>		<p>6. State Oil & Gas Lease No. LG-6730</p>
<p>3. Address of Operator 1313 Campbell Road, Building D, Houston, TX 77055</p>		<p>7. Lease Name or Unit Agreement Name State 30</p>
<p>4. Well Location Unit Letter <u>K</u> : <u>2310</u> feet from the <u>South</u> line and <u>2227</u> feet from the <u>West</u> line Section <u>30</u> Township <u>17S</u> Range <u>36E</u> NMPM Lea County</p>		<p>8. Well Number 001</p>
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.)</p>		<p>9. OGRID Number 14096</p>
		<p>10. Pool name or Wildcat Double A; Abo South</p>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

Approved for plugging of well bore only. Liability under bond is retained pending Location cleanup & receipt of C-103Q (Subsequent Report of Well Plugging) which may be found at OCD Web Page, OCD Permitting @ www.emnrd.state.nm.us

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory B. Gregson TITLE OPERATIONS MANAGER DATE 29 SEP 2021
Type or print name GREGORY B. GREGSON E-mail address: ggregson@marklshidlerinc.com PHONE: 713-481-6487
For State Use Only

APPROVED BY:

Accepted for record – NMOCDC gc10/25/2022

DATE

Conditions of Approval (if any):

Plugging Report
State 30 #1
30-025-28605

8/30/2021 Move in equipment, set matting board and rig up. Picked up on the rods. Did not feel the pump unseat. Picked up 1" rods and tried to tag up. No tag. Laid down 82 1" rods, 94 7/8" rods, 177 3/4" rods, 6 1" rods, 2 sinker bars, and a 4' X 1" rods sub. No pump. SION

8/31/2021 Dug out cellar and plumbed intermediate head to the steel pit. Installed the BOP. Briefly attempted to release and anchor. Rigged up wireline. RIH with a back off shot. Shot collar at 8423'. Did not back off. POOH and rigged up a stronger shot. Shot collar at 8423' again. Got a back off with second shot. POOH with tubing. 270 joints of 2 7/8" tubing. SION

9/1/2021 Made gauge ring run and set 5.5" CIBP at 8417' on wireline. RIH with tubing and tag the CIBP. Circulated MLF and tested casing to 500#. Casing good. Spot 25 sx Class H cement on to of CIBP. POOH to 7910' and spot 25 sx Class H cement across the DV tool. POOH and SION.

9/2/2021 Tubing was stuck this morning. Would not work free. Stretch test showed tubing stuck at 4779'. RIH with sinker bar and tagged up at 6717'. EOT at 6957'. Loaded tubing and pressure tested to 1000# and held. Shot collar at 4929' and manually backed off tubing. POOH with 129 joints (4024'). Run tubing back in the hole and torqued back up. Rigged up Rotary Wireline. Tubing came free while performing free point. Rig down Rotary. First two stands drug and the freed up. POOH with tubing and SION.

9/3/2021 Tagged cement above DV tool at 7724'. Spot 25 sx cement at 4961' across the San Andres. POOH to 3557' and spot 60 sx cement across the intermediate shoe. POOH and SION.

9/6/2021 Tagged cement at 2927'. POOH and perforated casing at 1915'. Set packer and pressured up on perforations to 750# and held. No drop. Pulled packer and RIH with tubing to 1965' and spot 25 sx cement with CaCl. WOC and tagged at 1712'. Perforated casing at 455'. Pressured up on perforations to 600# and held with no drop. RIH with tubing and circulated cement to surface from 506' with 50 sx cement. Laid down remaining tubing and rigged down. Will dig out and cut off in the morning.

9/7/2021 Dug out wellhead and cut off. Filled up 13 3/8" and 5 1/2" casing strings with 10 sx cement. 8 5/8" casing had cement to surface. Installed regulation marker. Removed the anchor, hauled off fluids, cleaned the pit and moved equipment out.

Mark L. Shidler, Inc.
State 30 #1
API 30-025-28605
WBD After PA

PERF. 455'.

Circulate cement to surface from
455'. Surface Shoe
506'.

13 3/8" 40# casins set @ 405'
with 420 sx. Circulated

Perf. 1915'

Spot 25 sx Class C from 1915'
Top Salt. **TAG @ 1712'**

Spot 60 sx Class C cement from
3549'. Base Salt & Intermediate Shoe
WOC and Tag **@ 2921'.**

8 5/8" 32# casing set at 3499'
Cemented w/1000 sx
TOC @ Surface

Spot 25 Class C from 4942'. Top
San Andres

4942' Top San Andres

Spot 25 sx Class H across DV Tool
from 7910'. WOC and Tag **@ 7724'.**

7910' DV Tool

8417'

Set 5 1/2" CIBP @ : Circulate MLF
Test casing and spot 25 sx Class H
Cement on top

Perforations 8592' to 9222'

5 1/2" 17# casing set at 9322"
Cemented w/1590 sx cement
TOC @ Surface

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 52850

COMMENTS

Operator: MARK L SHIDLER INC 1313 Campbell Road Houston, TX 77055	OGRID: 14096
	Action Number: 52850
	Action Type: [C-103] Sub. Plugging (C-103P)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	10/26/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 52850

CONDITIONS

Operator: MARK L SHIDLER INC 1313 Campbell Road Houston, TX 77055	OGRID: 14096
	Action Number: 52850
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	10/25/2022