	27 AM State of New Mexico		Form Cage
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Re	sources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO.
$\frac{District II}{811 \text{ S. First St., Artesia, NM 88210}}$	OIL CONSERVATION DIV	ISION	30-031-20831
District III - (505) 334-6178	1220 South St. Francis D	r.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	1.00	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	,		5. Suite On the Sub Lieuse 110.
SUNDRY NO	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Hospah Sand Unit	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other		8. Well Number 100	
2. Name of Operator	n Production Company, LLC		9. OGRID Number
3. Address of Operator	on Production Company, LLC		10. Pool name or Wildcat
1414 W Swann Av, Suite 100, Tampa, FL 33606			Upper Hospah
4. Well Location			
Unit LetterH		line and	1190_feet from theE line
Section 36		nge 9W	NMPM County McKinley
	11. Elevation <i>(Show whether DR, RKB,</i> 7135	RT, GR, etc.)	
12. Check	Appropriate Box to Indicate Nature	of Notice, F	Report or Other Data
PERFORM REMEDIAL WORK	CHANGE PLANS COM	EDIAL WORK	LING OPNS. P AND A
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM			
OTHER:		ER: Sub	plugging-C103 P
13. Describe proposed or com of starting any proposed w proposed completion or re	vork). SEE RULE 19.15.7.14 NMAC. For	nt details, and Multiple Com	give pertinent dates, including estimated da pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	vork). SEE RULE 19.15.7.14 NMAC. For	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For a secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re Dominion Production Comp	vork). SEE RULE 19.15.7.14 NMAC. For secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re Dominion Production Comp	vork). SEE RULE 19.15.7.14 NMAC. For secompletion.	Multiple Com	pletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re Dominion Production Comp youd Date: <u>4[30[2</u>	vork). SEE RULE 19.15.7.14 NMAC. For secompletion. pany plugged this well in accordance with the second s	Multiple Com ne attached rep 5 5 (pletions: Attach wellbore diagram of port.
of starting any proposed w proposed completion or re Dominion Production Comp pud Date: <u>4[30[2</u>	vork). SEE RULE 19.15.7.14 NMAC. For secompletion.	Multiple Com ne attached rep 5 5 (pletions: Attach wellbore diagram of port. 23
of starting any proposed w proposed completion or re Dominion Production Comp pud Date: <u>4[30[2</u>	Xeron (19,15,7,14 NMAC). For the secompletion. pany plugged this well in accordance with the secondance withe secondance with the secondance with the secondance	Multiple Com he attached rep 5 [5 [. hy knowledge	223
of starting any proposed w proposed completion or re Dominion Production Comp Spud Date: <u>4[30[2</u>	vork). SEE RULE 19.15.7.14 NMAC. For secompletion. pany plugged this well in accordance with the second s	Multiple Com he attached rep 5 [5 [. hy knowledge	port. 23
of starting any proposed w proposed completion or re Dominion Production Comp pud Date: <u>4[30[2</u>	Xeron (19,15,7,14 NMAC). For the secompletion. pany plugged this well in accordance with the secondance withe secondance with the secondance with the secondance	Multiple Com he attached rep 5 5 (hy knowledge	223

•

Dominion Production Company

Plug And Abandonment End Of Well Report

Hospah Sand Unit #100

2505' FNL & 1190' FEL, Section 36, 18N, 09W

McKinley County, NM / API 30-031-20831

Work Summary:

- 4/30/23 Made BLM and NMOCD P&A operations notifications at 9:00 AM MST.
- 5/1/23 Arrived at location. Held safety meeting. Wrote and reviewed JHA with crew. Moved rig and equipment to location. Prepared location. R/U unit and equipment. Checked well pressures. NU BOP and function tested. R/U floor, tongs, and slips. Secured and shut in well for the day.
- **5/2/23** Arrived at location. Held safety meeting. Wrote and reviewed JHA with crew. Checked well pressures. Blead down well. TIH with a tag sub and 22 joints. Tagged 20' into joint #22. TOOH. Wait on drill collars and mill. TIH with 4-3/4" mill, bit sub, and 10 joints of drill collars. Tagged at 680'. R/U power swivel. Secured and shut in well for the day.
- **5/3/23** Arrived at location. Held safety meeting. Wrote and reviewed JHA with crew. Checked well pressures. Blead down well. Filled hole with 9 bbls of water. Started to drill at 680'. Drilled 2.5' of hard metal, may have been a packer. From there we pushed to and tagged at 1695'. R/D power swivel. TOOH with 44 joints, Left drill collars in the hole. Secured and shut in well for the day.
- **5/4/23** Arrived at location. Held safety meeting. Wrote and reviewed JHA with crew. Checked well pressures. Blead down well. L/D the 10 drill collars left in hole. Filled hole with 17 bbls of water. R/U wireline services. TIH and logged the well. POOH. R/D wireline. TIH to 1695'. R/U cementing services. Filled hole with 15 bbls of

water. Pumped plug #1 from 1695' to 1350' with 34 sx. L/D 8 joints and TOOH with 46 joints. WOC. TIH and tagged plug #1 at 1468'. R/U cementing services. Filled hole with 27 bbls of water. Attempted to pressure test casing but was unsuccessful. Continued pumping plug #1 from 1468'to 1350' with 13 sacks. L/D 4 joints and TOOH. Secured and shut in well for the day.

- 5/5/23 Arrived at location. Held safety meeting. Wrote and reviewed JHA with crew. Checked well pressures. Blead down well. TIH with tag sub to 675'. R/U cementing services. Attempted to pressure test casing but was unsuccessful. Pumped plug #2 from 675' to 400' with 27 sacks. L/D 9 joints and reverse circulated. TOOH and WOC. TIH and tagged top of plug #2 at 450'. TOOH. R/U wireline services. RIH and perforated at 100'. POOH. Circulated well with 40 bbls. TIH with tubing to 200'. R/U cementing services. Pumped plug #3 from 200' to surface with 85 sx. TOOH and L/D tubing. WOC. Tagged cement at 6'. R/D floor, tongs, and slips. ND BOP. Dug around the WH. Performed WH cutoff. Welder installed P&A per all state and federal regulations. R/U cementing services. Topped off casing strings to surface with 19 sx.
- **5/5/23** Arrived at location. Held safety meeting. R/D all equipment. MOL. Travel back to Drake yard.

Plug Summary:

Plug #1: (Perforations, 1,695'-1,350', 47 Sacks Type III Cement)

R/U cementing services. Filled hole with 15 bbls of water. Pumped plug #1 from 1695' to 1350' with 34 sx. L/D 8 joints and TOOH with 46 joints. WOC. TIH and tagged plug #1 at 1468'. R/U cementing services. Filled hole with 27 bbls of water. Attempted to pressure test casing but was unsuccessful. Continued pumping plug #1 from 1468'to 1350' with 13 sacks.

Plug #2: (675'-450', 27 Sacks Type III Cement)

TIH with tag sub to 675'. R/U cementing services. Attempted to pressure test casing but was unsuccessful. Pumped plug #2 from 675' to 400' with 27 sacks. L/D 9 joints and reverse circulated. TOOH and WOC. TIH and tagged top of plug #2 at 450'.

Plug #3: (Surface, 200' to Surface', 104 Sacks Type III Cement (19 sx for top off))

R/U wireline services. RIH and perforated at 100'. POOH. Circulated well with 40 bbls. TIH with tubing to 200'. R/U cementing services. Pumped plug #3 from 200' to surface with 85 sx. TOOH and L/D

tubing. WOC. Tagged cement at 6'. R/D floor, tongs, and slips. ND BOP. Dug around the WH. Performed WH cutoff. Welder installed P&A marker per all state and federal regulations. R/U cementing services. Topped off casing strings to surface with 19 sx.

Completed Wellbore Diagram

Dominion Production Company Hospah Sand Unit #100 API: 30-031-20831 Mckinley County, New Mexico

Surface Casing

6.625" at 40'

Plug 3 200 feet - Surface 200 foot plug 1104 Sacks of Type III Cement


<u>Plug 2</u> 675 feet - 450 feet 225 foot plug 13 Sacks of Type III Cement

<u>Plug 1</u> 1695 feet - 1350 feet 345 foot plug 47 Sacks of Type III Cement

> Perforations 1729 feet - 1750 feet

<u>Production Casing</u> 5.5" at 1833'





District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DOMINION PRODUCTION COMPANY, LLC	291567
1414 W Swann Avenue	Action Number:
Tampa, FL 33606	215504
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
john.harrison	None	5/12/2023

CONDITIONS

Page 6 of 6

Action 215504