Form 3160-3 (June 2015)			OMB N	APPROVED (o. 1004-0137 anuary 31, 2018
UNITED STA DEPARTMENT OF TH BUREAU OF LAND M/	E INTERIOR		5. Lease Serial No.	•
APPLICATION FOR PERMIT TO	6. If Indian, Allotee	or Tribe Name		
1a. Type of work: DRILL	REENTER		7. If Unit or CA Ag	reement, Name and No.
1b. Type of Well: Oil Well Gas Well 1c. Type of Completion: Hydraulic Fracturing	Other Single Zone	Multiple Zone	8. Lease Name and	Well No. [318029]
2. Name of Operator PERMIAN RESOURCES OPERAT	ING, LLC	/2165]	9. API Well No.	30-025-51763
3a. Address		No. (include area code)	10. Field and Pool, XXXX	or Exploratory [96434]
 4. Location of Well (Report location clearly and in accordan At surface At proposed prod. zone 	nce with any State	e requirements.*)	11. Sec., T. R. M. o	r Blk. and Survey or Area
14. Distance in miles and direction from nearest town or pos	t office*		12. County or Paris	h 13. State
15. Distance from proposed* location to nearest property or lease line, ft. (Also to nearest drig. unit line, if any)	16. No of a	cres in lease 17. S	Spacing Unit dedicated to t	this well
18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft.	19. Propose	ed Depth 20.1	BLM/BIA Bond No. in file	:
21. Elevations (Show whether DF, KDB, RT, GL, etc.)	22. Approx 24. Atta	imate date work will start*	23. Estimated durat	ion
The following, completed in accordance with the requirement (as applicable)			the Hydraulic Fracturing	rule per 43 CFR 3162.3-3
 Well plat certified by a registered surveyor. A Drilling Plan. A Surface Use Plan (if the location is on National Forest S SUPO must be filed with the appropriate Forest Service O 		Item 20 above). 5. Operator certification	2	n existing bond on file (see s may be requested by the
25. Signature	Name	e (Printed/Typed)		Date
Title	·			<u> </u>
Approved by (Signature)	Name	e (Printed/Typed)		Date
Title	Offic	e		1
Application approval does not warrant or certify that the app applicant to conduct operations thereon. Conditions of approval, if any, are attached.	licant holds legal	or equitable title to those r	ights in the subject lease w	hich would entitle the
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 12 of the United States any false, fictitious or fraudulent statemed				any department or agency
NGMP Rec 0724/2023 Conf				
		CONDITIO	15 A	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
SL	ROVED WI	TH CONDITION		
(Continued on page 2)		0=/01/0000	*(In	structions on page 2)

Approval Date: 07/21/2023



.

INSTRUCTIONS

GENERAL: This form is designed for submitting proposals to perform certain well operations, as indicated on Federal and Indian lands and leases for action by appropriate Federal agencies, pursuant to applicable Federal laws and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from local Federal offices.

ITEM I: If the proposal is to redrill to the same reservoir at a different subsurface location or to a new reservoir, use this form with appropriate notations. Consult applicable Federal regulations concerning subsequent work proposals or reports on the well.

ITEM 4: Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local Federal offices for specific instructions.

ITEM 14: Needed only when location of well cannot readily be found by road from the land or lease description. A plat, or plats, separate or on the reverse side, showing the roads to, and the surveyed location of, the wen, and any other required information, should be furnished when required by Federal agency offices.

ITEMS 15 AND 18: If well is to be, or has been directionany drilled, give distances for subsurface location of hole in any present or objective productive zone.

ITEM 22: Consult applicable Federal regulations, or appropriate officials, concerning approval of the proposal before operations are started.

ITEM 24: If the proposal will involve hydraulic fracturing operations, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The Privacy Act of 1974 and regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 25 U.S.C. 396; 43 CFR 3160

PRINCIPAL PURPOSES: The information will be used to: (1) process and evaluate your application for a permit to drill a new oil, gas, or service wen or to reenter a plugged and abandoned well; and (2) document, for administrative use, information for the management, disposal and use of National Resource Lands and resources including (a) analyzing your proposal to discover and extract the Federal or Indian resources encountered; (b) reviewing procedures and equipment and the projected impact on the land involved; and (c) evaluating the effects of the proposed operation on the surface and subsurface water and other environmental impacts.

ROUTINE USE: Information from the record and/or the record win be transferred to appropriate Federal, State, and local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecution, in connection with congressional inquiries and for regulatory responsibilities.

EFFECT OF NOT PROVIDING INFORMATION: Filing of this application and disclosure of the information is mandatory only if you elect to initiate a drilling or reentry operation on an oil and gas lease.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM conects this information to anow evaluation of the technical, safety, and environmental factors involved with drilling for oil and/or gas on Federal and Indian oil and gas leases. This information will be used to analyze and approve applications. Response to this request is mandatory only if the operator elects to initiate drilling or reentry operations on an oil and gas lease. The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Conection Clearance Officer (WO-630), 1849 C Street, N.W., Mail Stop 401 LS, Washington, D.C. 20240.

Additional Operator Remarks

Location of Well

0. SHL: SWNE / 2299 FNL / 1965 FEL / TWSP: 24S / RANGE: 34E / SECTION: 27 / LAT: 32.189463 / LONG: -103.455632 (TVD: 0 feet, MD: 0 feet) PPP: SWNE / 2548 FNL / 2090 FEL / TWSP: 24S / RANGE: 34E / SECTION: 27 / LAT: 32.188779 / LONG: -103.456035 (TVD: 9519 feet, MD: 9807 feet) PPP: NWNE / 0 FNL / 2089 FEL / TWSP: 24S / RANGE: 34E / SECTION: 27 / LAT: 32.195782 / LONG: -103.456034 (TVD: 9519 feet, MD: 12355 feet) PPP: NWSE / 2637 FNL / 2089 FEL / TWSP: 24S / RANGE: 34E / SECTION: 27 / LAT: 32.203037 / LONG: -103.456034 (TVD: 9519 feet, MD: 14995 feet) BHL: NWNE / 100 FNL / 2090 FEL / TWSP: 24S / RANGE: 34E / SECTION: 22 / LAT: 32.21001 / LONG: -103.456033 (TVD: 9519 feet, MD: 17013 feet)

BLM Point of Contact

Name: PAMELLA HERNANDEZ Title: LIE Phone: (575) 234-5954 Email: PHERNANDEZ@BLM.GOV

Review and Appeal Rights

A person contesting a decision shall request a State Director review. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME:	Centennial
LEASE NO.:	NMNM126972
LOCATION:	Section 27, T.24 S, R.34 E., NMPM
COUNTY:	Lea County, New Mexico
WELL NAME & NO.:	Solomon Fed Com 501H
SURFACE HOLE FOOTAGE:	2299'/N & 1965'/E
BOTTOM HOLE FOOTAGE:	100'/N & 2090'/E

COA

H2S	C Yes	💽 No	
Potash	None	C Secretary	© R-111-P
Cave/Karst Potential	• Low	C Medium	C High
Cave/Karst Potential	Critical		
Variance	C None	Section Flex Hose	C Other
Wellhead	Conventional	Multibowl	C Both
Wellhead Variance	C Diverter		
Other	4 String	Capitan Reef	□ WIPP
Other	Fluid Filled	Pilot Hole	Open Annulus
Cementing	Contingency	EchoMeter	Primary Cement
	Cement Squeeze		Squeeze
Special Requirements	Water Disposal	COM	🗖 Unit
Special Requirements	Batch Sundry		
Special Requirements	Break Testing	□ Offline	Casing
Variance		Cementing	Clearance

A. HYDROGEN SULFIDE

Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area must meet all requirements from **43 CFR 3176**, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.

B. CASING

- 1. The **13-3/8** inch surface casing shall be set at approximately **1150**_ feet (a minimum of 25 feet (Lea County) into the Rustler Anhydrite, above the salt, and below usable fresh water) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run

to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

- b. Wait on cement (WOC) time for a primary cement job will be a minimum of <u>8</u> <u>hours</u> or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.

Intermediate casing must be kept fluid filled to meet BLM minimum collapse requirement.

2. The minimum required fill of cement behind the **9-5/8** inch intermediate casing is:

• Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the tail cement slurry due to cave/karst.

3. The minimum required fill of cement behind the **5-1/2** inch production casing is: Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.

C. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'
- 2. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **5000** (**5M**) psi.

Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.

- a. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
- b. Manufacturer representative shall install the test plug for the initial BOP test.
- c. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- d. Whenever any seal subject to test pressure is broken, all the tests in 43 CFR 3172 must be followed.

D. SPECIAL REQUIREMENT (S)

Communitization Agreement

- The operator will submit a Communitization Agreement to the Santa Fe Office, 301 Dinosaur Trail Santa Fe, New Mexico 87508, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- The operator will submit an as-drilled survey well plat of the well completion, but are not limited to, those specified in 43 CFR 3171 and 3172.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.
- In addition, the well sign shall include the surface and bottom hole lease numbers. <u>When the Communitization Agreement number is known, it shall also be on the sign.</u>

GENERAL REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)

Eddy County

Email **or** call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, **BLM_NM_CFO_DrillingNotifications@BLM.GOV** (575) 361-2822

Lea County Call the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575) 689-5981

- 1. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
 - a. In the event the operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well, after installing and testing the wellhead, by installing a blind flange of like pressure

Page 3 of 7

rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well(s).

- b. When the operator proposes to set surface casing with Spudder Rig
 - Notify the BLM when moving in and removing the Spudder Rig.
 - Notify the BLM when moving in the 2nd Rig. Rig to be moved in within 90 days of notification that Spudder Rig has left the location.
 - BOP/BOPE test to be conducted per **43 CFR part 3170 Subpart 3172** as soon as 2nd Rig is rigged up on well.
- 2. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.
- 3. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

A. CASING

- 1. Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.
- Wait on cement (WOC) for Potash Areas: After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi for all cement blends, 2) until cement has been in place at least <u>24</u> <u>hours</u>. WOC time will be recorded in the driller's log. The casing intergrity test can be done (prior to the cement setting up) immediately after bumping the plug.
- 3. <u>Wait on cement (WOC) for Water Basin:</u> After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least <u>8 hours</u>. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements. The casing integrity test can be done (prior to the cement setting up) immediately after bumping the plug.

Page 4 of 7

- 4. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. Have well specific cement details onsite prior to pumping the cement for each casing string.
- 5. No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.
- 6. On that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be performed before drilling more than 20 feet of new hole.
- 7. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.
- 8. Whenever a casing string is cemented in the R-111-P potash area, the NMOCD requirements shall be followed.

B. PRESSURE CONTROL

- All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in 43 CFR part 3170 Subpart 3172 and API STD 53 Sec. 5.3.
- 2. If a variance is approved for a flexible hose to be installed from the BOP to the choke manifold, the following requirements apply: The flex line must meet the requirements of API 16C. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor.
- 3. 5M or higher system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
- 4. If the operator has proposed a multi-bowl wellhead assembly in the APD. The following requirements must be met:

- a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
- b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
- c. Manufacturer representative shall install the test plug for the initial BOP test.
- d. Whenever any seal subject to test pressure is broken, all the tests in 43
 CFR part 3170 Subpart 3172 must be followed.
- e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead cement), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
 - b. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the cement plug. The BOPE test can be initiated after bumping the cement plug with the casing valve open. (only applies to single stage cement jobs, prior to the cement setting up.)
 - c. The tests shall be done by an independent service company utilizing a test plug not a cup or J-packer and can be initiated immediately with the casing valve open. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to 43 CFR part 3170 Subpart 3172 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (8 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
 - d. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE.

If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.

- e. The results of the test shall be reported to the appropriate BLM office.
- f. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- g. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.
- h. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the Wolfcamp formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per 43 CFR part 3170 Subpart 3172.

C. DRILLING MUD

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the Wolfcamp formation, and shall be used until production casing is run and cemented.

D. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

ZS 7/20/2023

Approval Date: 07/21/2023

Received by OCD: 7/24/2023 8:26:52 AM



U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Operator

I hereby certify that I, or someone under my direct supervision, have inspected the drill site and access route proposed herein; that I am familiar with the conditions which currently exist; that I have full knowledge of state and Federal laws applicable to this operation; that the statements made in this APD package are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed in conformity with this APD package and the terms and conditions under which it is approved. I also certify that I, or the company I represent, am responsible for the operations conducted under this application. These statements are subject to the provisions of 18 U.S.C. 1001 for the filing of false statements.

NAME: MEGHAN TWELE		Signed on: 06/22/2023									
Title: Sr Regulatory Analyst											
Street Address: 1001 17TH STRE	ET SUITE 1800										
City: DENVER	ity: DENVER State: CO Zip: 80202										
Phone: (720)499-1531											
Email address: MEGHAN.TWELE	@CDEVINC.COM										
Field											
Representative Name:											
Street Address:											
City: S	State:	Zip:									
Phone:											
Email address:											

07/24/2023

Received by OCD: 7/24/2023 8:26:52 AM

AFMSS

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

APD ID: 10400087543

Submission Date: 11/02/2022

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Type: OIL WELL

Well Number: 105H Well Work Type: Drill Highlighted data reflects the most recent changes Show Final Text

Application Data

Section 1 - General

APD ID: 10400087543 Submission Date: 11/02/2022 Tie to previous NOS? N **BLM Office:** Carlsbad **User: MEGHAN TWELE** Title: Sr Regulatory Analyst Federal/Indian APD: FED Is the first lease penetrated for production Federal or Indian? FED Lease number: NMNM126972 Lease Acres: Allotted? **Reservation:** Surface access agreement in place? Agreement in place? NO Federal or Indian agreement: Agreement number: Agreement name: Keep application confidential? Y Permitting Agent? NO **APD Operator: CENTENNIAL RESOURCE PRODUCTION LLC Operator letter of**

Operator Info

Operator Organization Name: CENTENNIAL RESOURCE PRODUCTION LLC Operator Address: 1001 17TH STREET, SUITE 1800 Zip: 80202 **Operator PO Box:** State: CO **Operator City: DENVER Operator Phone:** (720)499-1400

Operator Internet Address:

Section 2 - Well Information

Well in Master Development Plan? NO	Master Development Plan name:								
Well in Master SUPO? NO	Master SUPO name:								
Well in Master Drilling Plan? NO	Master Drilling Plan name:								
Well Name: SOLOMON FEDERAL COM	Well Number: 105H	Well API Number:							
Field/Pool or Exploratory? Field and Pool	Field Name: AVALON A	Pool Name: RED HILLS BONE SPRING, NORTH							

Page 13 of 115

07/24/2023

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Number: 105H

Is the proposed well in an area containing other mineral resources? NATURAL GAS,OIL

Is the propo	sed well in a Helium production area?	N Use Existing Well Pad?	N New surface disturbance?				
Type of Well	Pad: MULTIPLE WELL	Multiple Well Pad Name: SOLOMON 27 SENE	Number: 1				
Well Class:	HORIZONTAL	Number of Legs: 1					
Well Work T	ype: Drill						
Well Type: C	DIL WELL						
Describe We	ell Type:						
Well sub-Ty	pe: INFILL						
Describe su	b-type:						
Distance to	town: 20 Miles Distance to	o nearest well: 30 FT	Distance to lease line: 1965 FT				
Reservoir w	ell spacing assigned acres Measurem	ent: 240 Acres					
Well plat:	Solomon_Federal_Com_105H_C_102	_LPP_SBMT_20221019151917	7.pdf				
	Solomon_Federal_Com_105H_C_102	Lease_Plat_SBMT_20221019	151931.pdf				
Well work st	art Date: 09/26/2023	Duration: 25 DAYS					

Section 3 - Well Location Table

Survey Type: RECTANGULAR

Describe Survey Type:

Datum: NAD83

Survey number: 23782

Vertical Datum: NAVD88

Reference Datum: GROUND LEVEL


Wellbore	NS-Foot	NS Indicator	EW-Foot	EW Indicator	Twsp	Range	Section	Aliquot/Lot/Tract	Latitude	Longitude	County	State	Meridian	Lease Type	Lease Number	Elevation	MD	ТИD	Will this well produce from this
SHL Leg #1	229 9	FNL	196 5	FEL	24S	34E		Aliquot SWNE	32.18946 3	- 103.4556 32	LEA	NEW MEXI CO		F	FEE	346 3	0	0	Y
KOP Leg #1	229 9	FNL	196 5	FEL	24S	34E	<u> </u>	Aliquot SWNE	32.18946 3	- 103.4556 32	LEA	NEW MEXI CO		F	FEE	- 557 8	905 7	904 1	Y

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC


Well Name: SOLOMON FEDERAL COM

Well Number: 105H

Wellbore	NS-Foot	NS Indicator	EW-Foot	EW Indicator	Twsp	Range	Section	Aliquot/Lot/Tract	Latitude	Longitude	County	State	Meridian	Lease Type	Lease Number	Elevation	MD	TVD	Will this well produce from this
PPP Leg #1-1	254 8	FNL	209 0	FEL	24S	34E	27	Aliquot SWNE	32.18877 9	- 103.4560 35	LEA	NEW MEXI CO	NEW MEXI CO	F	FEE	- 605 6	980 7	951 9	Y
PPP Leg #1-2	0	FNL	208 9	FEL	24S	34E	27	Aliquot NWNE	32.19578 2	- 103.4560 34	LEA	NEW MEXI CO	NEW MEXI CO	F	FEE	- 605 6	123 55	951 9	Y
PPP Leg #1-3	263 7	FNL	208 9	FEL	24S	34E	27	Aliquot NWSE	32.20303 7	- 103.4560 34	LEA	NEW MEXI CO	NEW MEXI CO	F	FEE	- 605 6	149 95	951 9	Y
EXIT Leg #1	100	FNL	209 0	FEL	24S	34E	22	Aliquot NWNE	32.21001	- 103.4560 33	LEA	NEW MEXI CO	NEW MEXI CO	F	NMNM 126972	- 696 8	179 16	104 31	Y
BHL Leg #1	100	FNL	209 0	FEL	24S	34E	22	Aliquot NWNE	32.21001	- 103.4560 33	LEA	NEW MEXI CO		F	NMNM 126972	- 605 6	170 13	951 9	Y



Page 16 of 115





Section 1 - Geologic Formations

Formation ID	Formation Name	Elevation	True Vertical	Measured Depth	Lithologies	Mineral Resources	Producing Formatio
9061635	RUSTLER	3524	1082	1082	SANDSTONE	NONE	N
9061645	SALADO	1816	1708	1708	SALT	NONE	N
9061646	LAMAR	-1904	5428	5428	ANHYDRITE	NONE	N
9061636	BELL CANYON	-1954	5478	5478	SANDSTONE	NATURAL GAS, OIL	N
9061637	CHERRY CANYON	-2867	6391	6391	SANDSTONE	NATURAL GAS, OIL	N
9061638	MANZANITA	-3027	6551	6551	SANDSTONE	NATURAL GAS, OIL	N
9061639	BRUSHY CANYON	-4307	7831	7831	OTHER : Carbonate	NATURAL GAS, OIL	N
9061640	AVALON SAND	-5834	9358	9358	SHALE	CO2, NATURAL GAS, OIL	N

Section 2 - Blowout Prevention

Pressure Rating (PSI): 5M

Rating Depth: 9518

Equipment: The BOP and related equipment will meet or exceed the requirements of a 5M-psi system as set forth in On Shore Order No. 2. See attached BOP Schematic. A. Casinghead: 13 5/8 5,000 psi SOW x 13 5,000 psi WP Intermediate Spool: 13 5,000 psi WP x 11 5,000 psi WP Tubinghead: 11 5,000 psi WP x 7 1/16" 15,000 psi WP B. Minimum Specified Pressure Control Equipment Annular preventer One Pipe ram, One blind ram Drilling spool, or blowout preventer with 2 side outlets. Choke side will be a 3-inch minimum diameter, kill line shall be at least 2-inch diameter 3 inch diameter choke line 2 3 inch choke line valves 2 inch kill line 2 chokes with 1 remotely controlled from rig floor (see Figure 2) 2 2 inch kill line valves and a check valve Upper kelly cock valve with handle available When the expected pressures approach working pressure of the system, 1 remote kill line tested to stack pressure (which shall run to the outer edge of the substructure and be unobstructed) Lower kelly cock valve with handle available Safety valve(s) and subs to fit all drill string connections in use Inside BOP or float sub available Pressure gauge on choke manifold All BOPE connections subjected to well pressure shall be flanged, welded, or clamped Fill-up line above the uppermost preventer. C. Auxiliary Equipment Audio and visual mud monitoring equipment shall be placed to detect volume changes indicating loss or gain of circulating fluid volume. (OOS 1, III.C.2) Gas Buster will be used below intermediate casing setting depth. Upper and lower kelly cocks with handles, safety valve and subs to fit all drill string connections and a pressure gauge installed on choke manifold.

Requesting Variance? YES

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC
Well Name: SOLOMON FEDERAL COM
Well

Well Number: 105H

Variance request: Flex hose, well control and offline cement variances, see attachments in section 8.

Testing Procedure: The BOP test shall be performed before drilling out of each casing string and will occur at a minimum: a. when initially installed b. whenever any seal subject to test pressure is broken c. following related repairs d. at 30 day intervals e. checked daily as to mechanical operating conditions. The ram type preventer(s) will be tested using a test plug to 250 psi (low) and 5,000 psi (high) (casinghead WP) with a test plug upon its installation onto the 13 surface casing. If a test plug is not used, the ram type preventer(s) shall be tested to 70% of the minimum internal yield pressure of the casing. The annular type preventer(s) shall be tested to 50% of its working pressure. Pressure will be maintained for at least 10 minutes or until provisions of the test are met, whichever is longer. A Sundry Notice (Form 3160 5), along with a copy of the BOP test report, shall be submitted to the local BLM office within 5 working days following the test. If the bleed line is connected into the buffer tank (header), all BOP equipment including the buffer tank and associated valves will be rated at the required BOP pressure. The BLM office will be provided with a minimum of four (4) hours notice of BOP testing to allow witnessing. The BOP Configuration, choke manifold layout, and accumulator system, will be in compliance with Onshore Order 2 for a 5,000 psi system. A remote accumulator will be used. Pressures, capacities, and specific placement and use of the manual and/or hydraulic controls, accumulator controls, bleed lines, etc., will be identified at the time of the BLM 'witnessed BOP test. Any remote controls will be capable of both opening and closing all preventers and shall be readily accessible

Choke Diagram Attachment:

10M_Choke_Manifold_20221026150451.pdf

BOP Diagram Attachment:

BOP_Schematic_CoFlex_Choke_5K_20221026150454.pdf

Section	3 -	Casing
---------	-----	--------

Casing ID	String Type	Hole Size	Csg Size	Condition	Standard	Tapered String	Top Set MD	Bottom Set MD	Top Set TVD	Bottom Set TVD	Top Set MSL	Bottom Set MSL	Calculated casing length MD	Grade	Weight	Joint Type	Collapse SF	Burst SF	Joint SF Type	Joint SF	Body SF Type	Body SF
	CONDUCT OR	26	20.0	NEW	API	N	0	120	0	120	3463	3343	120	H-40	-	OTHER - WELD						
2	SURFACE	17.5	13.375	NEW	API	N	0	1150	0	1150	3463	2313	1150	J-55		OTHER - BTC	1.99	4.81	DRY	13.6 1	DRY	13.6 1
	INTERMED IATE	12.2 5	9.625	NEW	API	N	0	5450	0	5450	3461	-1987	5450	J-55	40	LT&C	1.28	1.4	DRY	2.39	DRY	2.89
	PRODUCTI ON	8.75	5.5	NEW	API	N	0	9057	0	9041	3461	-5578	9057	OTH ER	-	OTHER - TCBC-HT	2.37	2.69	DRY	3.54	DRY	3.54
	PRODUCTI ON	8.5	5.5	NEW	API	N	9057	17013	9041	9518	-5578	-6055	7956	OTH ER		OTHER - TCBC-HT	2.25	2.56	DRY	67.1 9	DRY	67.1 9

Casing Attachments

Received by OCD: 7/24/2023 8:26:52 AM Page 20 of 115 **Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC** Well Name: SOLOMON FEDERAL COM Well Number: 105H **Casing Attachments** Casing ID: 1 CONDUCTOR String **Inspection Document:** Spec Document: **Tapered String Spec:** Casing Design Assumptions and Worksheet(s): Casing ID: 2 String SURFACE **Inspection Document: Spec Document: Tapered String Spec:** Casing Design Assumptions and Worksheet(s): CASING_ASSUMPTIONS_WORKSHEET_20221026151336.pdf Casing ID: 3 INTERMEDIATE String **Inspection Document: Spec Document: Tapered String Spec:** Casing Design Assumptions and Worksheet(s): CASING_ASSUMPTIONS_WORKSHEET_20221026150757.pdf

Received by OCD: 7/24/2023 8:26:52 AM

Page 21 of 115

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Number: 105H

Casing Attachments

Casing ID: 4	String	PRODUCTION
Inspection Document:		
Spec Document:		
Tapered String Spec:		
Casing Design Assump	otions and W	/orksheet(s):
CASING_ASSUM	PTIONS_WO	RKSHEET_20221026150937.pdf
Technical_Data_S	heet_HIS_TC	BC_HT_5.5_20P110RY_20221026153535.pdf
Casing ID: 5	String	PRODUCTION
Inspection Document:		
Spec Document:		
Tapered String Spec:		
Casing Design Assump	otions and W	lorksheet(s):
CASING ASSUM	PTIONS_WO	RKSHEET_20221026151058.pdf

Technical_Data_Sheet_HIS_TCBC_HT_5.5_20_P110RY_20221026153545.pdf

Section	Section 4 - Cement										
String Type	Lead/Tail	Stage Tool Depth	Top MD	Bottom MD	Quantity(sx)	Yield	Density	Cu Ft	Excess%	Cement type	Additives
CONDUCTOR	Lead		0	120	121	1.49	12.9	181		Grout	Bentonite 4% BWOC, Cellophane #sx, CaCl2 2% BWOC

SURFACE	Lead	0	650	250	1.8	13.5	903	100	Class C Premium	Premium Gel Bentonite
										4%, C-45 Econolite
										0.25%,

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Number: 105H

String Type	Lead/Tail	Stage Tool Depth	Top MD	Bottom MD	Quantity(sx)	Yield	Density	Cu Ft	Excess%	Cement type	Additives
											Phenoseal 0.25#/sk, CaCl 1%, Defoamer C- 41P 0.75%
SURFACE	Tail		650	1150	445	1.34	14.8	695	100	Class C Premium	C-45 Econolite 0.10%, CaCl 1.0%
INTERMEDIATE	Lead		0	4950	665	3.42	10.7	3214	100	TXI Lightweight	Salt 1.77/sk, C-45 Econolite 2.25%, STE 6.00%, Citric Acid 0.18%, C-19 0.10%, CSA-1000 0.20%, C- 530P 0.30%, CTB-15 LCM 7#/sk, Gyp Seal 8#/sk
INTERMEDIATE	Tail		4950	5450	210	1.34	14.8	188	20	Class C Premium	C-45 Econolite 0.10%, Citric acid 0.05%, C503P 0.25%
PRODUCTION	Lead		0	9057	889	3.41	10.6	3032	30	TXI Lightweight	Salt 8.98#/sk, STE 6.00%, Citric acid 0.20%, CSA-1000 0.23%, C47B 0.10%, C- 503P 0.30%
PRODUCTION	Tail		9057	1701 3	1837	1.24	14.2	2278	25	50:25:25 Class H: Poz: CPO18	Citric acid 0.03%, CSA- 1000 0.05%, C47B 0.25%, C-503P 0.30%
PRODUCTION	Lead		0	9057	889	3.41	10.6	3032	30	TXI Lightweight	Salt 8.98#/sk, STE 6.00%, Citric acid 0.20%, CSA-1000 0.23%, C47B 0.10%, C- 503P 0.30%
PRODUCTION	Tail		9057	1701 3	1837	1.24	14.2	2278	25	50:25:25 Class H: Poz: CPO18	Citric acid 0.03%, CSA- 1000 0.05%, C47B 0.25%, C-503P 0.30%

Well Number: 105H

Page 23 of 115

Section 5 - Circulating Medium

Mud System Type: Closed

Will an air or gas system be Used? NO

Description of the equipment for the circulating system in accordance with Onshore Order #2:

Diagram of the equipment for the circulating system in accordance with Onshore Order #2:

Describe what will be on location to control well or mitigate other conditions: Sufficient quantities of mud materials will be on the well site at all times for the purpose of assuring well control and maintaining wellbore integrity. Surface interval will employ fresh water mud. The intermediate hole will utilize a diesel emulsified brine fluid to inhibit salt washout and prevent severe fluid losses. The production hole will employ oil base fluid to inhibit formation reactivity and of the appropriate density to maintain well control.

Describe the mud monitoring system utilized: Centrifuge separation system. Open tank monitoring with EDR will be used for drilling fluids and return volumes. Open tank monitoring will be used for cement and cuttings return volumes. Mud properties will be monitored at least every 24 hours using industry accepted mud check practices.

Circulating Medium Table

Top Depth	Bottom Depth	Mud Type	Min Weight (Ibs/gal)	Max Weight (Ibs/gal)	Density (lbs/cu ft)	Gel Strength (lbs/100 sqft)	Hd	Viscosity (CP)	Salinity (ppm)	Filtration (cc)	Additional Characteristics
0	1150	OTHER : FW	8.6	9.5							
1150	5450	OTHER : Brine	9	10							
0	1701 3	OIL-BASED MUD	8.8	10							

Section 6 - Test, Logging, Coring

List of production tests including testing procedures, equipment and safety measures:

Will utilize MWD/LWD (Gamma ray logging) from intermediate hole to TD of the well.

List of open and cased hole logs run in the well:

GAMMA RAY LOG, DIRECTIONAL SURVEY,

Coring operation description for the well:

N/A

Received by OCD: 7/24/2023 8:26:52 AM

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Number: 105H

Section 7 - Pressure

Anticipated Bottom Hole Pressure: 4949

Anticipated Surface Pressure: 2654

Anticipated Bottom Hole Temperature(F): 170

Anticipated abnormal pressures, temperatures, or potential geologic hazards? NO

Describe:

Contingency Plans geoharzards description:

Contingency Plans geohazards

Hydrogen Sulfide drilling operations plan required? YES

Hydrogen sulfide drilling operations

 $H2S_Contingency_Plan_Solomon_Federal_Com_105H_106H__304H__404H_20221026152901.pdf$

Section 8 - Other Information

Proposed horizontal/directional/multi-lateral plan submission:

Solomon_Federal_Com_105H___Plan_1_08_05_22_AC_Report_20221026152930.pdf Solomon_Federal_Com_105H___Plan_1_08_05_22_20221026152935.pdf


Other proposed operations facets description:

Other proposed operations facets attachment:

Solomon_Federal_Com_105H_WBD__Proposed__20221026152952.pdf Solomon_Federal_Com_105H_Batch_Setting___Aug_2022_20221026153026.pdf GEOPROG_Solomon_Federal_Com_105H_PRELIM_20221026153048.pdf CDEV_Multi_Bowl_Procedure_Solomon_Federal_Com_105H_20221026153052.pdf

Other Variance attachment:

CDEV_Well_Control_Plan_Bonesprings_20211029125013.pdf H_P_Flex_Hose_Specs_Continental_Hose_SN_67255_20200228112930.pdf Flex_Hose_Variance_Request___Solomon_Federal_Com_105H_20221026153109.pdf Solomon_Federal_Com_105H_Offline_Cementing_Procedure___Aug_2022_20221026153114.pdf




.

Page 25 of 115

Received by OCD: 7/24/2023 8:26:52 AM

H&P Rig



CASING ASSUMPTIONS WORKSHEET:

Centralizer Program:

Surface:	 - 3 welded bow spring centralizers, one on each of the bottom 3 joints, plus one on the shoe joint (4 minimum) - No Cement baskets will be run
Production:	 - 1 welded bow spring centralizer on a stop ring 6' above float shoe - 1 centralizer every other joint to the top of the tail cement - 1 centralizer every 4 joints to 500' below the top of the lead cement - The actual number and placement of centralizers will be determined from hole deviation and potential production zones. Centralizers will be run for maximum practical standoff and through all potential productive zones.

• All casing strings below the conductor shall be tested, prior to drilling out the casing shoe, to 0.22 psi/ft of casing string length or 1500 psi, whichever is greater, but not to exceed 70% of the internal yield pressure of the casing. If pressure declines more than 10 percent in 30 minutes, corrective action will be taken.

No freshly hard banded pipe will be rotated in the surface casing

- CENTENNIAL RESOURCE DEVELOPOMENT will not employ an air-drill rig for the surface casing. The casing shoe will be tested by drilling 5'-10' out from under the shoe and pressure testing to the maximum expected mud weight equivalent as shown in the mud program listed in the drilling plan.

CASING ASSUMPTIONS WORKSHEET:

Centralizer Program:

Surface:	 - 3 welded bow spring centralizers, one on each of the bottom 3 joints, plus one on the shoe joint (4 minimum) - No Cement baskets will be run
Production:	 - 1 welded bow spring centralizer on a stop ring 6' above float shoe - 1 centralizer every other joint to the top of the tail cement - 1 centralizer every 4 joints to 500' below the top of the lead cement - The actual number and placement of centralizers will be determined from hole deviation and potential production zones. Centralizers will be run for maximum practical standoff and through all potential productive zones.

• All casing strings below the conductor shall be tested, prior to drilling out the casing shoe, to 0.22 psi/ft of casing string length or 1500 psi, whichever is greater, but not to exceed 70% of the internal yield pressure of the casing. If pressure declines more than 10 percent in 30 minutes, corrective action will be taken.

No freshly hard banded pipe will be rotated in the surface casing

- CENTENNIAL RESOURCE DEVELOPOMENT will not employ an air-drill rig for the surface casing. The casing shoe will be tested by drilling 5'-10' out from under the shoe and pressure testing to the maximum expected mud weight equivalent as shown in the mud program listed in the drilling plan.



Size	5.5
Grade	P110 RY
Weight	20

TCBC-HT

SeAH Steel

	Coupling and Pipe Dimensions (in)										
	Outer Diameter	Inner Diameter	Coupling	Mako un Loss	Wall Thickness	Drift					
Coupling	6.300	5.383	Length	wake-up Loss	wall mickness	Diameter					
Pipe	*******	4.778	8.250	4.125	0.361	4.653					
Pin		4.778									

Torque Values (ft-lbs)									
	Field End Make	Max. Working	Yield Torque						
Minimum	Optimum ^{2.}	Maximum	Torque ^{1.}	field forque					
10,000	13,500	18,500	22,250	25,200					


Yield Stress (x1000 lbs.)						
Tensile	Compressive					
100%	100%					

Maximum Pressure (psi)						
Internal	External					
100%	100%					



^{1.} Max. Working Torque value is not to be exceeded during operation.

^{2.} If Optimum Torque does not meet the Base of Triangle Stamp, M/U to the Base of Triangle.



*Data are for information purposes only. Though HIS has made efforts to ensure accuracy, HIS makes no warranty for loss or damage due to its use. *Released to Imaging: 7/27/2023 9:22:50 AM*



5.5" 20# .361" P-110 Restricted Yield (RY)

Dimensions (Nominal)

Outside Diameter	5.500	in.
Wall	0.361	in.
Inside Diameter	4.778	in.
Drift	4.653	in.
Weight, T&C	20.000	lbs/ft
Weight, PE	19.830	lbs/ft

Performance Properties (Minimum)

Minimum Yield Strength Maximum Yield Strength	110000 125000	psi psi
Collapse, PE	11100	psi
Internal Yield Pressure		
PE	12630	psi
LTC	12360	psi
BTC	12360	psi
Yield Strength, Pipe Body	641	1000 lbs
Joint Strength		
LTC	548	1000 lbs
BTC	667	1000 lbs

Note: SeAH Steel has produced this specification sheet for general information only. SeAH does not assume liability or responsibility for any loss or injury resulting from the use of information or data contained herein. All applications for the material described are at the customer's own risk and responsibility.

CASING ASSUMPTIONS WORKSHEET:

Centralizer Program:

Surface:	 - 3 welded bow spring centralizers, one on each of the bottom 3 joints, plus one on the shoe joint (4 minimum) - No Cement baskets will be run
Production:	 - 1 welded bow spring centralizer on a stop ring 6' above float shoe - 1 centralizer every other joint to the top of the tail cement - 1 centralizer every 4 joints to 500' below the top of the lead cement - The actual number and placement of centralizers will be determined from hole deviation and potential production zones. Centralizers will be run for maximum practical standoff and through all potential productive zones.

• All casing strings below the conductor shall be tested, prior to drilling out the casing shoe, to 0.22 psi/ft of casing string length or 1500 psi, whichever is greater, but not to exceed 70% of the internal yield pressure of the casing. If pressure declines more than 10 percent in 30 minutes, corrective action will be taken.

No freshly hard banded pipe will be rotated in the surface casing

- CENTENNIAL RESOURCE DEVELOPOMENT will not employ an air-drill rig for the surface casing. The casing shoe will be tested by drilling 5'-10' out from under the shoe and pressure testing to the maximum expected mud weight equivalent as shown in the mud program listed in the drilling plan.



Size	5.5
Grade	P110 RY
Weight	20

TCBC-HT


SeAH Steel

	Coupling and Pipe Dimensions (in)					
	Outer Diameter	uter Diameter Inner Diameter Coupling Make-up Loss Wall Thickness		Drift		
Coupling	6.300	5.383	Length	Wake-up Loss	wait mickness	Diameter
Pipe	······································	4.778	8.250	4.125	0.361	4.653
Pin		4.778				

Torque Values (ft-lbs)				
Field End Make-Up			Max. Working	Yield Torque
Minimum	Optimum ^{2.}	Maximum	Torque ^{1.}	field forque
10,000	13,500	18,500	22,250	25,200


Yield Stress (x1000 lbs.)			
Tensile Compressive			
100%	100%		

Maximum Pressure (psi)		
Internal	External	
100%	100%	



^{1.} Max. Working Torque value is not to be exceeded during operation.

^{2.} If Optimum Torque does not meet the Base of Triangle Stamp, M/U to the Base of Triangle.



*Data are for information purposes only. Though HIS has made efforts to ensure accuracy, HIS makes no warranty for loss or damage due to its use. *Released to Imaging: 7/27/2023 9:22:50 AM*



5.5" 20# .361" P-110 Restricted Yield (RY)

Dimensions (Nominal)

Outside Diameter	5.500	in.
Wall	0.361	in.
Inside Diameter	4.778	in.
Drift	4.653	in.
Weight, T&C	20.000	lbs/ft
Weight, PE	19.830	lbs/ft

Performance Properties (Minimum)

Minimum Yield Strength Maximum Yield Strength	110000 125000	psi psi
Collapse, PE	11100	psi
Internal Yield Pressure		
PE	12630	psi
LTC	12360	psi
BTC	12360	psi
Yield Strength, Pipe Body	641	1000 lbs
Joint Strength		
LTC	548	1000 lbs
BTC	667	1000 lbs

Note: SeAH Steel has produced this specification sheet for general information only. SeAH does not assume liability or responsibility for any loss or injury resulting from the use of information or data contained herein. All applications for the material described are at the customer's own risk and responsibility.

CASING ASSUMPTIONS WORKSHEET:

Centralizer Program:

Surface:	 - 3 welded bow spring centralizers, one on each of the bottom 3 joints, plus one on the shoe joint (4 minimum) - No Cement baskets will be run
Production:	 1 welded bow spring centralizer on a stop ring 6' above float shoe 1 centralizer every other joint to the top of the tail cement 1 centralizer every 4 joints to 500' below the top of the lead cement The actual number and placement of centralizers will be determined from hole deviation and potential production zones. Centralizers will be run for maximum practical standoff and through all potential productive zones.

• All casing strings below the conductor shall be tested, prior to drilling out the casing shoe, to 0.22 psi/ft of casing string length or 1500 psi, whichever is greater, but not to exceed 70% of the internal yield pressure of the casing. If pressure declines more than 10 percent in 30 minutes, corrective action will be taken.

No freshly hard banded pipe will be rotated in the surface casing

- CENTENNIAL RESOURCE DEVELOPOMENT will not employ an air-drill rig for the surface casing. The casing shoe will be tested by drilling 5'-10' out from under the shoe and pressure testing to the maximum expected mud weight equivalent as shown in the mud program listed in the drilling plan.



H₂S CONTINGENCY PLAN

FOR

CENTENNIAL RESOURCE PRODUCTION, LLC. Solomon Federal 105H, 106H, 304H, 404H

Lea County, New Mexico

02-19-2021 This plan is subject to updating

Centennial Res	source Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico
		Table of Contents	
Section	1.0 – Introduction		
Ι.	Purpose		
11.	Scope & Applicability		
Section	•	on	
Ι.	Activation Requirement	S	
11.	Emergency Evacuation		
	Emergency Response Ac		
		us Conditions	
		S Release Event	6
Ι.	Local & State Law Enfor	cement	
II. 	General Public		
III.	New Mexico Oil Conserv		
IV.	New Mexico Environme	•	
V.	Bureau of Land Manage		-
	•••	t List	7
l. 	Centennial Managemen	tPersonnel	
II. 	Lea County Sheriff	una Datural	
III.	New Mexico State High	way Patrol	
IV.	Fire / EMS		
V.	Lea County Hospital		
VI.	Emergency Response Co		
VII.	New Mexico Oil Conserv		
VIII.	New Mexico Environme		
IX.	Bureau of Land Manage	ment	
X.	Other Agencies	for which an	0.13
	-	formation	
I. II.	Site Safety Information		
III.	Directions to Location Plat of Location includin	a CBS Coordinatos	
IV.	Routes of Ingress & Egre	-	
V.	ROE Map		
V. VI.	Residences in ROE		
VII.	Public Roads in ROE		
		ation	13-15
.		of Hydrogen Sulfide Gas	ل±-ى±
ı. II.	•	/ Toxicological Information	
	Environmental Hazards		
		ation	
.	OSHA Information		
 II.		vation Division & Bureau of Land Managem	ient
		ents	
		ve Equipment	
Append			
.	Appendix A – H ₂ S SDS		
	Appendix $B - SO_2 SDS$		

•

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Section 1.0 – Introduction

I. Purpose

The purpose of this contingency plan (Plan) is to provide Centennial Resource Production, LLC. (Centennial) with an organized plan of action for alerting and protecting Centennial employees, the general public, and any potential first responders prior to any intentional release or immediately following the accidental / unintentional release of a potentially hazardous volume / concentration of Hydrogen Sulfide Gas (H2S).

II. Scope & Applicability

This Plan applies to all planned, unplanned, uncontrolled and/or unauthorized releases of hazardous concentrations of H2S or any associated hazardous byproducts of combustion, occurring at any Centennial owned or operated facilities including but not limited to: wells, flowlines, pipelines, tank batteries, production facilities, SWD facilities, compressor stations, gas processing plants, drilling / completions / workover operations, and any other applicable company owned property.

Section 2.0 - Plan Implementation

I. Activation Requirements

In accordance with the requirements of Bureau of Land Management Onshore Order #6 and NMAC 19.15.11, this Plan shall be activated in advance of any authorized, planned, unplanned, uncontrolled, or unauthorized release of a hazardous volume / concentration of H_2S gas, or SO^2 , which could potentially adversely impact the workers, general public or the environment.

II. Emergency Evacuation

In the event of an unplanned, uncontrolled, or unauthorized release of a hazardous volume / concentration of H_2S gas, the first priority is to ensure the safety of the workers and general public. Upon discovery and subsequent determination of an applicable release, which cannot be quickly mitigated, immediately by using 911, notify local authorities to begin the process of alerting the general public, evacuate any residents within the Radius of Exposure (ROE), and limit any general public or employee access to any areas within the ROE of the affected facility.

III. Emergency Response Activities

The purpose of emergency response actions is to take steps to quickly mitigate / stop the ongoing release of the hazardous source of H_2S . Upon discovery of any hazardous release, immediately notify Centennial management to activate the Emergency Response Team (ERT). Once Centennial supervision arrives and assesses the situation, a work plan identifying the proper procedures shall be developed to stop the release.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Section 3.0 - Potential Hazardous Conditions & Response Actions

During a planned or unplanned release of H₂S, there are several hazardous conditions that are presented both to employees, the general public, and emergency responders. These specific hazardous conditions are identified in the tables below.

✓ **H2S OPERATING CONDITIONS – RESPONSE ACTIONS TO CONSIDER** H₂S CONDITION 1: POTENTIAL DANGER TO LIFE AND HEALTH -> WARNING SIGN **GREEN** H₂S concentration <10 ppm detected by location monitors **General Actions During Condition 1** Notify Site Supervisor / Centennial Person-in-Charge (PIC) of any observed increase in ambient H₂S concentrations All personnel check safety equipment is in adequate working order & store in accessible location Sensitize crews with safety meetings. Limit visitors and non-essential personnel on location Continuously monitor H₂S concentrations and check calibration of sensors Ensure H₂S scavenger is on location. H₂S CONDITION 2: MODERATE DANGER TO LIFE AND HEALTH → WARNING SIGN YELLOW H_2S concentration >10 ppm and < 30 ppm in atmosphere detected by location monitors: **General Actions During Condition 2** Sound H₂S alarm and/or display yellow flag. Account for on-site personnel Upon sounding of an area or personal H₂S monitor alarm when 10 ppm is reached, proceed to a safe briefing area upwind of the location immediately (see MA-4, Figure 5-1). Don proper respiratory protection. Alert other affected personnel If trained and safe to do so undertake measures to control source H2S discharge and eliminate possible ignition sources. Initiate Emergency Shutdown procedures as deemed necessary to correct or control the specific situation. Account for on-site personnel at safe briefing area. Stay in safe briefing area if not working to correct the situation. Keep Site Supervisor / Centennial PIC informed. Notify applicable government agencies (Appendix A) If off-site impact; notify any neighbors within Radius of Exposure (ROE), Fig 5.11 Continuously monitor H₂S until readings below 10 ppm. Evacuated area shall not be re-entered except by trained and authorized personnel utilizing appropriate respiratory protection; or until "all clear" sounded by Centennial PIC / Site Supervisor.

-

Centennial Resource Production, LLC. H₂S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H

> 30 ppm H ₂ S concentration in air detected by location monitors: Extreme danger to life	
General Actions During Condition 3	
Sound H ₂ S alarm and/or display red flag.	
Account for on-site personnel	
Move away from H ₂ S source and get out of the affected area.	
Proceed to designated safe briefing area; alert other affected personnel.	
Account for personnel at safe briefing area.	
If trained and safe to do so undertake measures to control source H2S discharge and eliminate possible ignition sources. Initiate Emergency Shutdown procedures as deemed necessary to correct or control the specific situation.	
Notify vehicles or situation and divert all traffic away from location.	
Centennial Peron-in-Charge will make appropriate community notifications.	
Red warning flag must be on display until the situation has been corrected and the Centennial Person-in-Charge determines it is safe to resume operations under Condition 1 .	
Notify management of the condition and action taken. If H ₂ S concentration is increasing and steps to correct the situation are not successful – or at any time if well control is questionable – alert all responsible parties for possible activation of the H ₂ S Contingency Plan. If well control at the surface is lost, determine if situation warrants igniting the well.	
If uncontrolled flow at the surface occurs, the Centennial PIC, with approval, if possible, from those coordinating the emergency (as specified in the site-specific H ₂ S Contingency Plan) are responsible for determining if the situation warrants igniting the flow of the uncontrolled well. This decision should be made only as a last resort and in a situation where it is obvious that human life is in danger and there is no hope of controlling the flow under prevailing conditions.	
If the flow is ignited, burning H ₂ S will be converted to sulfur dioxide (SO ₂), which is also highly toxic. Do not assume that area is safe after the flow is ignited. If the well is ignited, evacuation of the area is mandatory, because SO ₂ will remain in low-lying places under no-wind conditions.	
 Keep Site Supervisor / Centennial PIC informed. Notify applicable government agencies and local law enforcement (Appendix A) If off-site impact; notify any neighbors within the Radius of Exposure (ROE), see example in Figure 5-11. 	
Continuously monitor H ₂ S until readings fall below 10 ppm.	
Evacuated area shall not be re-entered except by trained and authorized personnel utilizing appropriate respiratory protection; or until "all clear" sounded by Centennial PIC / Site Supervisor.	
IF ABOVE ACTIONS CANNOT BE ACCOMPLISHED IN TIME TO PREVENT EXPOSURE TO THE PUBLIC	
Alert public (directly or through appropriate government agencies) who may be subject to potentially harmful exposure levels.	

Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico	
Make recommendations to public officials regarding blocking unauthorized access to the unsafe area and assist as appropriate.			
Make recommendations to pub appropriate.	lic officials regarding evacuating the publ	ic and assist as	

Monitor ambient air in the area of exposure (after following abatement measures) to determine when it is safe for re-entry.

Section 4.0 - Notification of H₂S Release Event

I. Local & State Law Enforcement

Prior to the planned / controlled release of a hazardous concentration of H_2S gas or any associated byproducts of the combustion of H_2S gas, notify local law enforcement agencies regarding the contents of this plan.

In the event of the discovery of an unplanned/uncontrolled release of a hazardous concentration of H₂S gas or any associated byproducts of combustion, immediately notify local and/or state law enforcement agencies of the situation and ask for their assistance.

II. General Public

In the event of a planned or unplanned release of a hazardous concentration of H₂S gas or any associated byproducts of combustion, notify local law enforcement agencies and ask for their assistance in alerting the general public and limiting access to any public roads that may be impacted by such a release.

III. New Mexico Oil Conservation Division

The Centennial HSE Department will make any applicable notification to the New Mexico OCD regarding any release of a hazardous concentration of H_2S Gas or any associated byproducts of combustion.

IV. New Mexico Environment Department

The Centennial HSE Department will make any applicable notifications to the NMED regarding any release of a hazardous concentration of H_2S gas or any associated byproducts of combustion.

V. Bureau of Land Management

The Centennial Regulatory Department will make any applicable notifications to the BLM regarding any release of a hazardous concentration of H₂S gas or any associated byproducts of combustion.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Section 5.0 - Emergency Contact List

EMERGENCY CONTACT LIST					
CEN	CENTENNIAL RESOURCE PRODUCTION, LLC.				
POSITION	NAME	OFFICE	CELL	ALT PHONE	
	Opera	ations			
Operations Superintendent	Cory Lewis	432.305.1009	432.557.4274		
Operations Assistant Superintendent	Josh Graham	432.940.3191	432.940.3191		
Drilling Superintendent	Jason Fitzgerald	432.315.0146	318-347-3916		
Production Foreman	Manual Mata	432.664.0278	575.408.0216		
Drilling Engineer	Ronny Hise	432.315.0144	432.770.4786		
Production Engineer	Brandon Morin	432.315.0140	432.231.7671		
Vice President Operations	Clayton Smith	720.499.1416	361.215.2494		
	HSE & Re	egulatory	1		
HSE Manager	Derrick Melton	720-499-2294	432-296-8720		
Regulatory Manager	Heidi Kaczor	720.499.1422	303.204.8877		
Air Quality	Montgomery Floyd	432-315-0123	432-425-8321		
Environmental	Jamon Hohensee	432-315-0132	432-241-4283		
HSE Consultant	Adam Hicks		903-426-4556		
	Local, State, & F	ederal Agen	cies		
Lea County Sheriff		575-396-3611		911	
New Mexico State Highway Patrol		505-757-2297		911	
Eunice Fire / EMS		575-394-3258		911	
Lea County Hospital		575-492-5000			
Standard Safety – Safety Contractor	John Blake	(432) 653-0393	(432) 813-7745		
New Mexico Oil Conservation Division – District 1 Office – Hobbs, NM.		575-393-6161			
New Mexico Environment Department – District III Office – Hobbs, NM		575-397-6910			
New Mexico Oil Conservation Division – Hobbs, NM	24 Hour Emergency	575-393-6161			
Bureau of Land Management – Carlsbad, NM		575-234-5972			
U.S. Fish & Wildlife		502-248-6911			

Section 6.0 – Drilling Location Information

I. Site Safety Information

- 1. Safe Briefing Area
 - a. There shall be two areas that will be designated as "SAFE BRIEFING AREAs". If H_2S is detected in concentrations equal to or in excess of 10 ppm all personnel not assigned emergency duties are to assemble in the designated Safe Briefing area for instructions. These two areas shall be positioned in accessible locations to facilitate the availability of self-contained breathing air devices. The briefing areas shall be positioned no less than 250' from the wellhead and in such locations that at least one briefing area will be upwind from the well at all times.

2. Wind Indicators

a. 4 Windsocks will be installed at strategic points on the facility.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

3. Danger Signs

a. A warning sign indicating the possible well conditions will be displayed at the location entrance.


DANGER POISONOUS GAS HYDROGEN SULFIDE DO NOT APPROACH IF AMBER LIGHTS ARE FLASHING

- 4. <u>H₂S Detectors and Alarms</u>
 - a. Continuous monitoring type H₂S detectors, capable of sensing a minimum of 5ppm H₂S in air will be located centrally located at the tanks, heater treater, and combustor. Continuous monitoring type SO₂ detector will also be located at the combustor. The automatic H₂S alarm/flashing light will be located at the site entrance and in front of tank battery.
- 5. Safety Trailer
 - a. A safety trailer equipped with an emergency cascade breathing air system with 2 ea. Work/escape packs, a stretcher, 2 OSHA approved full body harnesses, and a 20# Class ABC fire extinguisher shall be available at the site in close proximity to the safe briefing area. The cascade system shall be able to be deployed to the drill floor when needed to provide safe breathing air to the workers as needed.
- 6. <u>Well Control Equipment</u>
 - a. The location shall have a flare line to a remote automatic ignitor and back up flare gun, placed 150' from the wellhead.
 - b. The location shall be equipped with a remotely operated choke system and a mud gas separator.
- 7. Mud Program
 - a. Company shall have a mud program that contains sufficient weight and additives to control H_2S .
- 8. <u>Metallurgy</u>
 - a. All drill strings, casing, tubing, wellhead, BOP, spools, kill lines, choke manifold and lines, and valves shall be suitable for anticipated H₂S volume and pressure.
- 9. Communication
 - a. The location shall be equipped with a means of effective communication such as a cell phones, intercoms, satellite phones or landlines.

II. Directions to Location

From the intersection of highway 18 and highway 128 in Jal, New Mexico, proceed in a northwesterly, then westerly direction along highway 128 approximately 18 miles to the junction of this road and NM County Road 2B to the south; turn left and proceed in a southerly direction approximately 2.0 miles to the lease road for the Solomon Pad. Turn left and proceed to location.

1. Plat of Location




2. Routes of Ingress & Egress (MAP)



Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

3. Residences in proximity to the 3000' Radius of Exposure (ROE) (MAP)

Map of 3000' ROE Perimeter



There are no residences or public gathering places with the 3000' ROE

100 PPM, 300 PPM, & 500 PPM Max ROE under worst case scenario

Enter H ₂ S in PPM	1500	
Enter Gas flow in mcf/day (maximum worst case conditions)	2500	
500 ppm radius of exposure (public road)	<u>105</u>	feet
300 ppm radius of exposure	<u>146</u>	feet
100 ppm radius of exposure (public area)	<u>230</u>	feet

- Location GPS Coordinates *Lat: 32.189353, Long: -103.455632*
- 4. Public Roads in proximity of the Radius of Exposure (ROE)

There are no public roads that would be within the 500 PPM ROE. The closest public road is New Mexico Highway 128, which is 1.45 miles from the location. County Road 2B is 1645' from this location.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Section 7.0 – Hazard Communication

I. Physical Characteristics of Hydrogen Sulfide Gas

Hydrogen sulfide (H₂S) is a colorless, poisonous gas that is soluble in water. It can be present in crude oils, condensates, natural gas and wastewater streams.

 H_2S is heavier than air with a vapor density of 1.189 (air = 1.0); however, H_2S is most often mixed with other gases. These mixtures of H_2S and other gases can be heavier or lighter than air. If the H_2S -containing mixture is heavier, it can collect in low areas such as ditches, ravines, firewalls, and pits; in storage tanks; and in areas of poor ventilation. Please see physical properties in **Table 7.0**.

With H₂S the sense of smell is rapidly lost allowing lethal concentrations to be accumulated without warning. The toxicity of hydrogen sulfide at varying concentrations is indicated in the **Table 7.1**.

Warning: Do not use the mouth-to-mouth method if a victim ingested or inhaled hydrogen sulfide. Give artificial respiration with the aid of a pocket mask equipped with a one-way valve or other proper respiratory medical device.

Properties of H2S	Description
Vapor Density > 1 = 1.189 Air = 1	 H2S gas is slightly heavier than air, which can cause it to settle in low places and build in concentration. Produced as a mixture with other gases associated with oil and gas production.
Flammable Range 4.3%-46% 43000 ppm – 460000 ppm	 H2S can be extremely flammable / explosive when these concentrations are reached by volume in air.

Table 7.0. Physical Properties of H₂S

Although H₂S is primarily a respiratory hazard, it is also flammable and forms an explosive mixture at concentrations of 4.3%–46.0% (40,000ppm – 460,000 ppm) by volume in air.

H₂S can be encountered when:

- Venting and draining equipment.
- Opening equipment (separators, pumps, and tanks).
- Opening piping connections ("line breaking").
- Gauging and sampling storage tanks.
- Entering confined spaces.
- Working around wastewater pits, skimmers, and treatment facilities.
- II. Human Health Hazards Toxicological Information

Centennial Resource Production, LLC.	H₂S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Table 7.1. Hazards & Toxicity

Concentration	Symptoms/Effects		
(ppm)			
0.00011-0.00033 ppm	Typical background concentrations		
0.01-1.5 ppm	Odor threshold (when rotten egg smell is first noticeable to some). Odor becomes more offensive at 3-5 ppm. Above 30 ppm, odor described as sweet or sickeningly sweet.		
2-5 ppm	Prolonged exposure may cause nausea, tearing of the eyes, headaches or loss of sleep. Airway problems (bronchial constriction) in some asthma patients.		
20 ppm	Possible fatigue, loss of appetite, headache, irritability, poor memory, dizziness.		
50-100 ppm	Slight conjunctivitis ("gas eye") and respiratory tract irritation after 1 hour. May cause digestive upset and loss of appetite.		
100 ppm	Coughing, eye irritation, loss of smell after 2-15 minutes (olfactory fatigue). Altered breathing, drowsiness after 15-30 minutes. Throat irritation after 1 hour. Gradual increase in severity of symptoms over several hours. Death may occur after 48 hours.		
100-150 ppm	Loss of smell (olfactory fatigue or paralysis).		
200-300 ppm	Marked conjunctivitis and respiratory tract irritation after 1 hour. Pulmonary edema may occur from prolonged exposure.		
500-700 ppm	Staggering, collapse in 5 minutes. Serious damage to the eyes in 30 minutes. Death after 30-60 minutes.		
700-1000 ppm	Rapid unconsciousness, "knockdown" or immediate collapse within 1 to 2 breaths, breathing stops, death within minutes.		
1000-2000 ppm	Nearly instant death		

III. Environmental Hazards

H₂S and its associated byproducts from combustion presents a serious environmental hazard. Sulphur Dioxide SO₂ is produced as a constituent of flaring H₂S Gas and can present hazards associated, which are

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

similar to H₂S. Although SO₂ is heavier than air, it will be picked up by a breeze and carried downwind at elevated temperatures. Since Sulfur Dioxide is extremely irritating to the eyes and mucous membranes of the upper respiratory tract, it has exceptionally good warning powers in this respect. The following table indicates the toxic nature of the gas. Please see the attached SDS in Appendix B for reference.

	SULFUR DIOXIDE TOXICITY			
Conce	entration	Effects		
%SO ₂ PPM				
0.0005 3 to 5 Pungent odor-normally a person can detect SO ₂ in this range.				
0.0012 12 Throat irritation, coughing, and constriction of the chest tearing and smarting of eyes.				
0.15	150	So irritating that it can only be endured for a few minutes.		
0.05	500	Causes a sense of suffocation, even with first breath.		

Section 8.0 - Regulatory Information

I. OSHA & NIOSH Information

II. Table 8.0. OSHA & NIOSH H₂S Information

PEL, IDLH, TLV	Description		
NIOSH PEL 10 PPM	 PEL is the Permissible Exposure Limit that an employee may be exposed up to 8 hr / day. 		
OSHA General Industry Ceiling PEL – 20 PPM	 The maximum exposure limit, which cannot be exceeded for any length of time. 		
IDLH 100 PPM	 Immediately Dangerous to Life and Health 		
Centennial PEL 10 PPM	 Centennial Policy Regarding H2S for employee safety 		

III. New Mexico OCD & BLM – H₂S Concentration Threshold Requirements

New Mexico NMAC 19.15.11 and Onshore Order #6 identify two Radii of Exposure (ROE) that identify potential danger to the public and require additional compliance measures. Centennial is required to install safety devices, establish safety procedures and develop a written H₂S contingency plan for sites where the H₂S concentrations are as follows.

H₂S Radius of Exposure	Description	Control and Equipment Requirements
100 ppm	Distance from a release to where the H ₂ S concentration in the air will dilute below 100ppm	ROE > 50-ft and includes any part of a "public area" (residence, school, business, etc., or any area that can be expected to be populated). ROE > 3,000-ft

Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H,	Lea County, New Mexico
	404H	

500 ppm	Distance from a release to where the H ₂ S concentration in the air will dilute below 500ppm	ROE > 50-ft and includes any part of a public road (public roads are tax supported roads or any road used for public access or use)
---------	---	---

Calculating H₂S Radius of Exposure

The ROE of an H₂S release is calculated to determine if a potentially hazardous volume of H₂S gas at 100 or 500 parts per million (ppm) is within a regulated distance requiring further action. If information about the concentration of H₂S and the potential gas release volume is known, the location of the Muster Areas will be set, and safety measures will be implemented based on the calculated radius of exposure (ROE). NMAC 19.15.11 – Hydrogen Sulfide Safety defines the ROE as the radius constructed with the gas's point of escape as its center and its length calculated by the following Pasquill-Gifford equations:

To determine the extent of the **<u>100 ppm ROE</u>**:

 $x = [(1.589) \text{ (mole fraction H}_2S)(Q)]^{(.6258)}$.

To determine the extent of the **500 ppm ROE**:

 $x = [(0.4546) \text{ (mole fraction H}_2S)(Q)]^{(.6258)}$.

Table 8.2. Calculating H2S Radius of Exposure

ROE Variable	Description	
X =	ROE in feet	
Q =	Max volume of gas released determined to be released in cubic feet per day (ft ³ /d) normalized to standard temperature and pressure, 60°F and 14.65 psia	
Mole fraction H ₂ S =	Mole fraction of H ₂ S in the gaseous mixture released.	

The volume used as the escape rate in determining the ROE is specified in the rule as follows:

- The maximum daily volume rate of gas containing H₂S handled by that system element for which the ROE is calculated.
- For existing gas wells, the current adjusted open-flow rate, or the operator's estimate of the well's capacity to flow against zero back-pressure at the wellhead.

New Mexico Oil Conservation Division & BLM Site Requirements under NMAC 19.15.11 & Onshore Order #6

- Two cleared areas will be designated as Safe Briefing Areas. During an emergency, personnel will
 assemble in one of these areas for instructions from the Centennial Person-in-Charge. Prevailing
 wind direction should be considered in locating the briefing areas 200' or more on either side of the
 well head. One area should offset the other at an angle of 45° to 90° with respect to prevailing wind
 direction to allow for wind shifts during the work period.
- In the event of either an intentional or accidental releases of hydrogen sulfide, safeguards to protect the general public from the harmful effects of hydrogen sulfide must be in place for operations. A summary of the provisions in each of three H₂S ROE cases is included in Table 8.3.
 - **CASE 1** -100 ppm ROE < 50'

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

- **CASE 2** 100 ppm ROE is 50' or greater, but < 3000' and does not penetrate public area.
- **CASE 3** -100 ppm ROE is 50' or greater and penetrates a public area or 500 ppm ROE includes a public road. Also if 100 ppm ROE > 3000' regardless of public area.

Table 8.3. NMAC 19.15.11 Compliance Requirements Drilling & Production

NMAC 19.15.11 & BLM COMPLIANCE REQUIREMENTS - DRILLING & PRODUCTION			
PROVISION	CASE 1	CASE 2	CASE 3
H ₂ S Concentration Test	Х	X	X
H-9	Х	X	Х
Training	Х	X	Х
District Office Notification	Х	X	Х
Drill Stem Tests Restricted	X*	X*	X
BOP Test	X*	X*	X
Materials		X	Х
Warning and Marker		X	X
Security		Х	Х
Contingency Plan			X
Control and Equipment Safety			Х
Monitors		X**	X**
Mud (ph Control or Scavenger)			X*
Wind Indicators		X**	Х
Protective Breathing Equipment		X**	Х
Choke Manifold, Secondary Remote Control, and Mud-Gas Separator			Х
Flare Stacks			X*

Section 9.0 - Training Requirements

Training

The following elements are considered a minimum level of training for personnel assigned to operations who may encounter H₂S as part of routine or maintenance work.

- The hazards, characteristics, and properties of hydrogen sulfide (H₂S) and (SO₂).
- Sources of H₂S and SO₂.
- Proper use of H₂S and SO₂ detection methods used at the workplace.
- Recognition of, and proper response to, the warning signals initiated by H₂S and SO₂ detection systems in use at the workplace.
- Symptoms of H₂S exposure; symptoms of SO₂ exposure
- Rescue techniques and first aid to victims of H₂S and SO₂ exposure.
- Proper use and maintenance of breathing equipment for working in H₂S and SO₂ atmospheres, as appropriate theory and hands-on practice, with demonstrated proficiency (29 *CFR* Part 1910.134).
- Workplace practices and relevant maintenance procedures that have been established to protect personnel from the hazards of H₂S and SO₂.
- Wind direction awareness and routes of egress.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

- Confined space and enclosed facility entry procedures (if applicable).
- Emergency response procedures that have been developed for the facility or operations.
- Locations and use of safety equipment.
- Locations of safe briefing areas.

Refresher training will be conducted annually.

Section 10.0 - Personal Protective Equipment

I. <u>Personal H₂S Monitors</u>

All personnel engaged in planned or unplanned work activity to mitigate the release of a hazardous concentration of H₂S shall have on their person a personal H2S monitor.

- II. Fixed H₂S Detection and Alarms
 - 4 channel H₂S monitor
 - 4 wireless H₂S monitors
 - H₂S alarm system (Audible/Red strobe)
 - Personal gas monitor for each person on location
 - Gas sample tubes

III. Flame Resistant Clothing

All personnel engaged in planned or unplanned work activity associated with this Plan shall have on the appropriate level of FRC clothing.

IV. <u>Respiratory Protection</u>

The following respiratory protection equipment shall be available at each drilling location.

- Working cascade system available on rig floor and pit system & 750' of air line hose
- Four (4) breathing air manifolds
- Four (4) 30-minute rescue packs
- Five (5) work/Escape units
- Five (5) escape units
- One (1) filler hose for the work/escape/rescue units

Supplied air (airline or SCBA) respiratory protection against hydrogen sulfide exposure is required in the following situations:

- When routine or maintenance work tasks involve exposure to H₂S concentrations of 10 ppm or greater.
- When a fixed location area monitor alarms, and re-entry to the work area is required to complete a job.
- When confined spaces are to be entered without knowledge of H₂S levels present, or if initial measurements are to be taken of H₂S levels.
- During rescue of employees suspected of H₂S overexposure.
- For specific tasks identified with significant exposure potential and outlined in local program guidelines.
- All respiratory equipment for hydrogen sulfide must be of the supplied-air type, equipped with pressure-demand regulators and operated in the pressure-demand mode only. This is the only type of respiratory protection recommended for hydrogen sulfide application. Equipment should be approved by NIOSH/MSHA or other recognized national authority as required. If airline units are used, a five-minute egress bottle should also be carried.

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

- Gas masks or other air-purifying respirators MUST NEVER BE USED FOR HYDROGEN SULFIDE due to the poor warning properties of the gas.
- Use of respiratory protection should be accompanied by a written respiratory protection program.

Centennial Resource Production, LLC.	H₂S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Appendix A H₂S SDS



Supersedes: 10-15-2013

.1. Product identifier	
Product form	: Substance
lame	: Hydrogen sulfide
AS No	: 7783-06-4
ormula	: H2S
ther means of identification	: Hydrogen sulfide
roduct group	: Core Products
2. Recommended use and restriction	ons on use
ecommended uses and restrictions	: Industrial use Use as directed
.3. Supplier	
rraxair Canada inc. 200 – 1 City Centre Drive Alississauga - Canada L5B 1M2 1-905-803-1600 - F 1-905-803-1682 www.praxair.ca	
.4. Emergency telephone number	
mergency number	: 1-800-363-0042 Call emergency number 24 hours a day only for spills, leaks, fire, exposure, or accidents involving this product. For routine information, contact your supplier or Praxair sales representative.
ECTION 2: Hazard identification	
1. Classification of the substance o	or mixture
HS-CA classification	
lam. Gas 1 H220 iquefied gas H280 icute Tox. 2 (Inhalation: gas) H330 TTOT SE 3 H335	
.2. GHS Label elements, including p	recautionary statements
.2. GHS Label elements, including p GHS-CA labelling	recautionary statements
SHS-CA labelling	recautionary statements
SHS-CA labelling	: GHS02 : DANGER
HS-CA labelling	HS02 GHS04 GHS06 GHS07
	HS02 GHS04 GHS06 GHS07

EN (English)

SDS ID : E-4611

1/9

nnial Resource Production, LLC.	H ₂ S Co	ntingency Plan		Lea County, New Mex
	Solomon Fede	ral 105H, 106H	304H,	
		404H		
	Hydrogen su	lfide		
IPRAXAIR	Safety Data Sheet	E-4611		
a	according to the Hazardous Pro Date of issue: 10-15-1979	ducts Regulation (February Revision date: 08-10-201		0-15-2013
	Jate 01133de. 10-10-1075	Revision date: 00-10-201	o Supersedes. 1	- 10-2013
 2.3. Other hazards Other hazards not contributing to the classification 2.4. Unknown acute toxicity (GHS No data available 	Avoid release to Wear protective protection Leaking gas fire In case of leaka Store locked up Dispose of cont Protect from su Close valve afte Do not open val When returning Do not depend	nly outdoors or in a well o the environment gloves, protective cloth c Do not extinguish, unle ge, eliminate all ignition	ng, eye protection, re ess leak can be stopp sources ance with container S perature exceeds 52 npty uipment prepared for t valve outlet cap or esence of gas	Supplier/owner instructions °C (125°F) • use
		4-		
SECTION 3: Composition/infor 3.1. Substances	mation on ingredien	ts		
Name	CAS No.	% (Vol.) C	ommon Name (syn	onvms)
Hame		/0 (10)		
Hydrogen sulfide	(CAS No) 7783-06-4			Hydrogen sulphide / Sulfur hydride /
Hydrogen sulfide (Main constituent)	(CAS No) 7783-06-4			Hydrogen sulphide / Sulfur hydride / ydrogen sulphide / Hydrogensulfide
(Main constituent) 3.2. Mixtures	(CAS No) 7783-06-4			
(Main constituent)	(CAS No) 7783-06-4			
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures	s			
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures	s ures	S	Jlfureted hydrogen / Dih	ydrogen sulphide / Hydrogensulfide
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures	S ures : Remove to frest give artificial res physician. : The liquid may warm water not	h air and keep at rest in spiration. If breathing is o cause frostbite. For expo to exceed 105°F (41°C)	a position comfortabl ifficult, trained perso sure to liquid, immed . Water temperature	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a tiately warm frostbite area with should be tolerable to normal
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation	S ures : Remove to fresi give artificial res physician. : The liquid may i warm water not skin. Maintain s returned to the - with warm wate : Immediately flue away from the e	h air and keep at rest in spiration. If breathing is of cause frostbite. For export to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syeballs to ensure that a	a position comfortabl ifficult, trained perso sure to liquid, immer . Water temperature 15 minutes or unti n massive exposure, r on and treatment as water for at least 15 i	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact	S ures : Remove to fresi give artificial res physician. : The liquid may warm water not skin. Maintain s returned to the with warm wate : Immediately flus away from the e ophthalmologist	h air and keep at rest in spiration. If breathing is of cause frostbite. For export to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syeballs to ensure that a	a position comfortabl lifficult, trained perso sure to liquid, immed . Water temperature 15 minutes or until n massive exposure, n on and treatment as water for at least 15 i I surfaces are flushe	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact	S ures : Remove to fresi give artificial res physician. : The liquid may warm water not skin. Maintain a returned to the with warm wate : Immediately flus away from the e ophthalmologist : Ingestion is not	h air and keep at rest in spiration. If breathing is of to exceed 105°F (41°C) skin warming for at least affected area. In case of affected area. In case of r. Seek medical evaluati sh eyes thoroughly with eyeballs to ensure that a t immediately. considered a potential m	a position comfortabl lifficult, trained perso isure to liquid, immed . Water temperature 15 minutes or until n massive exposure, n on and treatment as water for at least 15 i I surfaces are flushe	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion	S ures : Remove to fresi give artificial res physician. : The liquid may warm water not skin. Maintain a returned to the with warm wate : Immediately flus away from the e ophthalmologist : Ingestion is not	h air and keep at rest in spiration. If breathing is of to exceed 105°F (41°C) skin warming for at least affected area. In case of affected area. In case of r. Seek medical evaluati sh eyes thoroughly with eyeballs to ensure that a t immediately. considered a potential m	a position comfortabl lifficult, trained perso isure to liquid, immed . Water temperature 15 minutes or until n massive exposure, n on and treatment as water for at least 15 i I surfaces are flushe	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms and	S ures : Remove to frest give artificial res physician. : The liquid may warm water not skin. Maintains returned to the with warm wate : Immediately flue away from the eis ophthalmologist : Ingestion is not	h air and keep at rest in spiration. If breathing is o to exceed 106°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syebalts to ensure that a t immediately. considered a potential m yed)	a position comfortabl lifficult, trained perso isure to liquid, immed . Water temperature 15 minutes or until n massive exposure, n on and treatment as water for at least 15 i I surfaces are flushe	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms and No additional information available	S ures : Remove to fresi give artificial res- physician. : The liquid may i warm water not skin. Maintain s returned to the - with warm wate : Immediately flue away from the e ophthalmologist : Ingestion is not and effects (acute and dela and special treatment, if	h air and keep at rest in spiration. If breathing is of cause frostbite. For export to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syeballs to ensure that a timmediately. considered a potential re yed)	a position comfortabl ifficult, trained perso sure to liquid, immet . Water temperature 15 minutes or until massive exposure, r on and treatment as water for at least 15 r I surfaces are flushe pute of exposure.	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms at No additional information available 4.3. Immediate medical attention Other medical advice or treatment	S ures : Remove to fress give artificial res- physician. : The liquid may warm water not skin. Maintain a returned to the with warm wate : Immediately flus away from the e ophthalmologist : Ingestion is not ind effects (acute and dela and special treatment, if : Obtain medical	h air and keep at rest in spiration. If breathing is of cause frostbite. For export to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syeballs to ensure that a timmediately. considered a potential re yed)	a position comfortabl ifficult, trained perso sure to liquid, immet . Water temperature 15 minutes or until massive exposure, r on and treatment as water for at least 15 r I surfaces are flushe pute of exposure.	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. ninutes. Hold the eyelids open and d thoroughly. Contact an
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms an No additional information available 4.3. Immediate medical attention Other medical advice or treatment SECTION 5: Fire-fighting measures	S ures : Remove to fresi give artificial res- physician. : The liquid may u- warm water not skin. Maintain s- returned to the i- with warm watee : Immediately fluu- away from the e- ophthalmologist : Ingestion is not nd effects (acute and deland and special treatment, if i- : Obtain medical sures	h air and keep at rest in spiration. If breathing is of cause frostbite. For export to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with syeballs to ensure that a timmediately. considered a potential re yed)	a position comfortabl ifficult, trained perso sure to liquid, immet . Water temperature 15 minutes or until massive exposure, r on and treatment as water for at least 15 r I surfaces are flushe pute of exposure.	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. ninutes. Hold the eyelids open and d thoroughly. Contact an
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms at No additional information available 4.3. Immediate medical attention Other medical advice or treatment SECTION 5: Fire-fighting measures 5.1. Suitable extinguishing media	S ures : Remove to fress give artificial res- physician. : The liquid may warm water not skin. Maintain a returned to the with warm watee : Immediately flue away from the e ophthalmologist : Ingestion is not nd effects (acute and delated and special treatment, if i : Obtain medical sures	h air and keep at rest in spiration. If breathing is of cause frostbite. For expo to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with eyeballs to ensure that at immediately. considered a potential m yed) necessary assistance. Treat with co	a position comfortabl lifficult, trained perso sure to liquid, immed . Water temperature 15 minutes or until n massive exposure, r on and treatment as water for at least 15 f I surfaces are flushe pute of exposure.	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a tiately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. minutes. Hold the eyelids open and d thoroughly. Contact an
(Main constituent) 3.2. Mixtures Not applicable SECTION 4: First-aid measures 4.1. Description of first aid measures First-aid measures after inhalation First-aid measures after skin contact First-aid measures after eye contact First-aid measures after ingestion 4.2. Most important symptoms an No additional information available 4.3. Immediate medical attention Other medical advice or treatment SECTION 5: Fire-fighting measures	S ures : Remove to fress give artificial res- physician. : The liquid may warm water not skin. Maintain a returned to the with warm watee : Immediately flue away from the e ophthalmologist : Ingestion is not nd effects (acute and delated and special treatment, if i : Obtain medical sures	h air and keep at rest in spiration. If breathing is of cause frostbite. For expor- to exceed 105°F (41°C) skin warming for at least affected area. In case of r. Seek medical evaluati sh eyes thoroughly with sh eyes thoroughly with considered a potential re yed) necessary assistance. Treat with co	a position comfortabl lifficult, trained perso sure to liquid, immed . Water temperature 15 minutes or until n massive exposure, r on and treatment as water for at least 15 f I surfaces are flushe pute of exposure.	ydrogen sulphide / Hydrogensulfide e for breathing. If not breathing, nnel should give oxygen. Call a diately warm frostbite area with should be tolerable to normal ormal coloring and sensation have emove clothing while showering soon as possible. ninutes. Hold the eyelids open and d thoroughly. Contact an

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

2/9

•

Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H,	Lea County, New Mexico
	404H	

	rding to the Hazardous Products Regulation (February 11, 2015) of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013
Date	01/3306, 10-10-10-10-10-10-10-10-10-10-20-10 Superseues, 10-10-20-13
5.3. Specific hazards arising from th	e hazardous product
Fire hazard	EXTREMELY FLAMMABLE GAS. If venting or leaking gas catches fire, do not extinguish flames. Flammable vapors may spread from leak, creating an explosive reignition hazard. Vapors can be ignited by pilot lights, other flames, smoking, sparks, heaters, electrical equipment, static discharge, or other ignition sources at locations distant from product handling point. Explosive atmospheres may linger. Before entering an area, especially a confined area, check the atmosphere with an appropriate device.
Explosion hazard	: EXTREMELY FLAMMABLE GAS. Forms explosive mixtures with air and oxidizing agents.
Reactivity	: No reactivity hazard other than the effects described in sub-sections below.
Reactivity in case of fire	: No reactivity hazard other than the effects described in sub-sections below.
5.4. Special protective equipment ar	nd precautions for fire-fighters
Firefighting instructions	: DANGER! Toxic, flammable liquefied gas
	Evacuate all personnel from the danger area. Use self-contained breathing apparatus (SCBA) and protective clothing. Immediately cool containers with water from maximum distance. Stop flow of gas if safe to do so, while continuing cooling water spray. Remove ignition sources if safe to do so. Remove containers from area of fire if safe to do so. On-site fire brigades must comply with their provincial and local fire code regulations.
Special protective equipment for fire fighters	: Standard protective clothing and equipment (Self Contained Breathing Apparatus) for fire fighters.
Other information	: Containers are equipped with a pressure relief device. (Exceptions may exist where authorized by TC.).
SECTION 6: Accidental release m	
6.1. Personal precautions, protective General measures	e equipment and emergency procedures
	DANGER! Toxic, flammable liquefied gas. Forms explosive mixtures with air and oxidizing agents. Immediately evacuate all personnel from danger area. Use self-contained breathing apparatus where needed. Remove all sources of ignition if safe to do so. Reduce vapors with fog or fine water spray, taking care not to spread liquid with water. Shut off flow if safe to do so Ventilate area or move container to a well-ventilated area. Flammable vapors may spread from leak and could explode if reignited by sparks or flames. Explosive atmospheres may linger. Before entering area, especially confined areas, check atmosphere with an appropriate device.
6.2. Methods and materials for conta	ainment and cleaning up
Methods for cleaning up	Try to stop release. Reduce vapour with fog or fine water spray. Prevent waste from contaminating the surrounding environment. Prevent soil and water pollution. Dispose of contents/container in accordance with local/regional/national/international regulations. Contact supplier for any special requirements.
6.3. Reference to other sections	
For further information refer to section 8:	Exposure controls/personal protection
SECTION 7: Handling and storag	e
7.1. Precautions for safe handling	
Precautions for safe handling	: Leak-check system with soapy water; never use a flame
	All piped systems and associated equipment must be grounded
	Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use only non-sparking tools. Use only explosion-proof equipment

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

3/9

•

Centennial Resource Production, LLC.	H₂S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	



Hydrogen sulfide

Safety Data Sheet E-4611 according to the Hazardous Products Regulation (February 11, 2015) Date of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013

7.2. Conditions for safe storage, including any incompatibilities

Storage conditions

: Store only where temperature will not exceed 125°F (52°C). Post "No Smoking/No Open Flames" signs in storage and use areas. There must be no sources of ignition. Separate packages and protect against potential fire and/or explosion damage following appropriate codes and requirements (e.g, NFPA 30, NFPA 55, NFPA 70, and/or NFPA 221 in the U.S.) or according to requirements determined by the Authority Having Jurisdiction (AHJ). Always secure containers upright to keep them from falling or being knocked over. Install valve protection cap, if provided, firmly in place by hand when the container is not in use. Store full and empty containers separately. Use a first-in, first-out inventory system to prevent storing full containers for long periods. For other precautions in using this product, see section 16

OTHER PRECAUTIONS FOR HANDLING, STORAGE, AND USE: When handling product under pressure, use piping and equipment adequately designed to withstand the pressures to be encountered. Never work on a pressurized system. Use a back flow preventive device in the piping. Gases can cause rapid suffocation because of oxygen deficiency; store and use with adequate ventilation. If a leak occurs, close the container valve and blow down the system in a safe and environmentally correct manner in compliance with all international, federal/national, state/provincial, and local laws; then repair the leak. Never place a container where it may become part of an electrical circuit.

SECTION 8: Exposure of	controls/personal protection	
8.1. Control parameters		
Hydrogen sulfide (7783-06-4	1)	
USA - ACGIH	ACGIH TLV-TWA (ppm)	1 ppm
USA - ACGIH	ACGIH TLV-STEL (ppm)	5 ppm
USA - OSHA	OSHA PEL (Ceiling) (ppm)	20 ppm
Canada (Quebec)	VECD (mg/m ³)	21 mg/m ³
Canada (Quebec)	VECD (ppm)	15 ppm
Canada (Quebec)	VEMP (mg/m ³)	14 mg/m ³
Canada (Quebec)	VEMP (ppm)	10 ppm
Alberta	OEL Ceiling (mg/m ³)	21 mg/m ³
Alberta	OEL Ceiling (ppm)	15 ppm
Alberta	OEL TWA (mg/m ³)	14 mg/m ³
Alberta	OEL TWA (ppm)	10 ppm
British Columbia	OEL Ceiling (ppm)	10 ppm
Manitoba	OEL STEL (ppm)	5 ppm
Manitoba	OEL TWA (ppm)	1 ppm
New Brunswick	OEL STEL (mg/m³)	21 mg/m ³
New Brunswick	OEL STEL (ppm)	15 ppm
New Brunswick	OEL TWA (mg/m³)	14 mg/m ³
New Brunswick	OEL TWA (ppm)	10 ppm
New Foundland & Labrador	OEL STEL (ppm)	5 ppm
New Foundland & Labrador	OEL TWA (ppm)	1 ppm
Nova Scotia	OEL STEL (ppm)	5 ppm
Nova Scotia	OEL TWA (ppm)	1 ppm
Nunavut	OEL Ceiling (mg/m ³)	28 mg/m ³
Nunavut	OEL Ceiling (ppm)	20 ppm
Nunavut	OEL STEL (mg/m ³)	21 mg/m ³
Nunavut	OEL STEL (ppm)	15 ppm
Nunavut	OEL TWA (mg/m³)	14 mg/m ³
Nunavut	OEL TWA (ppm)	10 ppm
Northwest Territories	OEL STEL (ppm)	15 ppm

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

4/9

Centennial Resource Production, LLC.

H ₂ S Contingency Plan
Solomon Federal 105H, 106H, 304H,
404H



Hydrogen sulfide Safety Data Sheet E-4611 according to the Hazardous Products Regulation (February 11, 2015)

Date of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013

Hydrogen sulfide (7783-	06-4)		
Northwest Territories	OEL TWA (ppm)	10 ppm	
Ontario	OEL STEL (ppm)	15 ppm	
Ontario	OEL TWA (ppm)	10 ppm	
Prince Edward Island	OEL STEL (ppm)	5 ppm	
Prince Edward Island	OEL TWA (ppm)	1 ppm	
Québec	VECD (mg/m ³)	21 mg/m ³	
Québec	VECD (ppm)	15 ppm	
Québec	VEMP (mg/m ³)	14 mg/m ³	
Québec	VEMP (ppm)	10 ppm	
Saskatchewan	OEL STEL (ppm)	15 ppm	
Saskatchewan	OEL TWA (ppm)	10 ppm	
Yukon	OEL STEL (mg/m ³)	27 mg/m³	
Yukon	OEL STEL (ppm)	15 ppm	
Yukon	OEL TWA (mg/m ³)	15 mg/m ³	
Yukon	OEL TWA (ppm)	10 ppm	

Appropriate engineering controls

: Use corrosion-resistant equipment. Use an explosion-proof local exhaust system. Local exhaust and general ventilation must be adequate to meet exposure standards. MECHANICAL (GENERAL): Inadequate - Use only in a closed system. Use explosion proof equipment and

	lighting.
8.3. Individual protection measures	/Personal protective equipment
Personal protective equipment	: Safety glasses. Face shield. Gloves.
Hand protection	: Wear work gloves when handling containers. Wear heavy rubber gloves where contact with product may occur.
Eye protection	: Wear goggles and a face shield when transfilling or breaking transfer connections. Select in accordance with the current CSA standard Z94.3, "Industrial Eye and Face Protection", and any provincial regulations, local bylaws or guidelines.
Respiratory protection	: Respiratory protection: Use respirable fume respirator or air supplied respirator when working in confined space or where local exhaust or ventilation does not keep exposure below TLV. Select in accordance with provincial regulations, local bylaws or guidelines. Selection should be based on the current CSA standard 294.4, "Selection, Care, and Use of Respirators." Respirators should also be approved by NIOSH and MSHA. For emergencies or instances with unknown exposure levels, use a self-contained breathing apparatus (SCBA).
Thermal hazard protection	 Wear cold insulating gloves when transfilling or breaking transfer connections. Standard EN 511 - Cold insulating gloves.
Other information	: Other protection : Safety shoes for general handling at customer sites. Metatarsal shoes and cuffless trousers for cylinder handling at packaging and filling plants. Select in accordance with the current CSA standard Z195, "Protective Foot Wear", and any provincial regulations, local bylaws or guidelines. For working with flammable and oxidizing materials, consider the use of flame resistant anti-static safety clothing.

9.1. Information on basic	physical and chemical properties
Physical state	: Gas
Appearance	: Colorless gas. Colorless liquid at low temperature or under high pressure.
Molecular mass	: 34 g/mol
Colour	: Colourless.
Odour	: Odour can persist. Poor warning properties at low concentrations. Rotten eggs.
Odour threshold	: Odour threshold is subjective and inadequate to warn of overexposure.

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

5/9

Centennial Resource Production,

Lea County, New Mexico

, LLC.	H ₂ S Contingency Plan	
	Solomon Federal 105H, 106H, 304H,	
	404H	1



Hydrogen sulfide Safety Data Sheet E-4611 according to the Hazardous Products Regulation (February 11, 2015) Date of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013

pН	: Not applicable.
pH solution	: No data available
Relative evaporation rate (butylacetate=1)	: No data available
Relative evaporation rate (ether=1)	: Not applicable.
Melting point	: -86 °C
Freezing point	: -82.9 °C
Boiling point	: -60.3 °C
Flash point	: Not applicable.
Critical temperature	: 100.4 °C
Auto-ignition temperature	: 260 °C
Decomposition temperature	: No data available
Vapour pressure	: 1880 kPa
Vapour pressure at 50 °C	: No data available
Critical pressure	: 8940 kPa
Relative vapour density at 20 °C	: >=
Relative density	: No data available
Relative density of saturated gas/air mixture	: No data available
Density	: No data available
Relative gas density	: 1.2
Solubility	: Water: 3980 mg/l
Log Pow	: Not applicable.
Log Kow	: Not applicable.
Viscosity, kinematic	: Not applicable.
Viscosity, dynamic	: Not applicable.
Viscosity, kinematic (calculated value) (40 °C)	: No data available
Explosive properties	: Not applicable.
Oxidizing properties	: None.
Flammability (solid, gas)	:
	4.3 - 46 vol %

9.2.	Other information		
Gas gro	ир	:	Liquefied gas
Additional information		:	Gas/vapour heavier than air. May accumulate in confined spaces, particularly at or below ground level

SECTION 10: Stability and reactivity	
10.1. Reactivity	
Reactivity	: No reactivity hazard other than the effects described in sub-sections below.
Chemical stability	: Stable under normal conditions.
Possibility of hazardous reactions	: May react violently with oxidants. Can form explosive mixture with air.
Conditions to avoid	: Avoid moisture in installation systems. Keep away from heat/sparks/open flames/hot surface - No smoking.
Incompatible materials	: Ammonia. Bases. Bromine pentafluoride. Chlorine trifluoride. chromium trioxide. (and heat). Copper. (powdered). Fluorine. Lead. Lead oxide. Mercury. Nitric acid. Nitrogen trifluoride. nitrogen sulfide. Organic compounds. Oxidizing agents. Oxygen difluoride. Rubber. Sodium. (and moisture). Water.
Hazardous decomposition products	: Thermal decomposition may produce : Sulfur. Hydrogen.
SECTION 11: Toxicological informa	ion
SECTION IT. TOXICOlOgical Informa	
11.1. Information on toxicological effects	
Acute toxicity (oral)	: Not classified
Acute toxicity (dermal)	: Not classified

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

Centennial Resource

Lea County, New Mexico

Production, LLC.	H ₂ S Contingency Plan	
	Solomon Federal 105H, 106H, 304H,	
	404H	

PRAXAIR

Hydrogen sulfide Safety Data Sheet E-4611 according to the Hazardous Products Regulation (February 11, 2015)

Date of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013

Acute toxicity (inhalation)	: Inhalation:gas: FATAL IF INHALED.
Hydrogen sulfide (\f)7783-06-4	
LC50 inhalation rat (mg/l)	0.99 mg/l (Exposure time: 1 h)
LC50 inhalation rat (ppm)	356 ppm/4h
ATE CA (gases)	356.0000000 ppmv/4h
ATE CA (vapours)	0.9900000 mg/l/4h
ATE CA (dust,mist)	0.9900000 mg/l/4h
Skin corrosion/irritation	: Not classified
	pH: Not applicable.
Serious eye damage/irritation	: Not classified
	pH: Not applicable.
Respiratory or skin sensitization	: Not classified
Germ cell mutagenicity	: Not classified
Carcinogenicity	: Not classified
Reproductive toxicity	: Not classified
Specific target organ toxicity (single exposure)	: MAY CAUSE RESPIRATORY IRRITATION.
Specific target organ toxicity (repeated exposure)	: Not classified

Aspiration hazard

: Not classified

: VERY TOXIC TO AQUATIC LIFE.	
[flow-through])	
low-through])	
d or water pollution.	

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

7/9

Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico

PRAXAIR	S
	ac

 Hydrogen sulfide

 Safety Data Sheet E-4611

 according to the Hazardous Products Regulation (February 11, 2015)

 Date of issue: 10-15-1979
 Revision date: 08-10-2016

 Supersedes: 10-15-2013

13.1. Disposal methods	
Waste disposal recommendations	: Do not attempt to dispose of residual or unused quantities. Return container to supplier.
SECTION 14: Transport information	
14.1. Basic shipping description	
In accordance with TDG	
TDG	
UN-No. (TDG)	: UN1053
TDG Primary Hazard Classes	: 2.3 - Class 2.3 - Toxic Gas.
TDG Subsidiary Classes	: 2.1
Proper shipping name	: HYDROGEN SULPHIDE
ERAP Index	: 500
Explosive Limit and Limited Quantity Index	: 0
Passenger Carrying Ship Index	: Forbidden
Passenger Carrying Road Vehicle or Passenger	
Carrying Railway Vehicle Index	
14.3. Air and sea transport	
IMDG	
UN-No. (IMDG)	: 1053
Proper Shipping Name (IMDG)	: HYDROGEN SULPHIDE
Class (IMDG)	: 2 - Gases
MFAG-No	: 117
IATA	
UN-No. (IATA)	: 1053
Proper Shipping Name (IATA)	: Hydrogen sulphide
Class (IATA)	: 2
SECTION 15: Regulatory information	n .
15.1. National regulations	
Hydrogen sulfide (7783-06-4)	
Listed on the Canadian DSL (Domestic Substa	nces List)
15.2. International regulations	
Hydrogen sulfide (7783-06-4)	
Listed on the AICS (Australian Inventory of Che	
Listed on IECSC (Inventory of Existing Chemic Listed on the EEC inventory EINECS (Europea	in Inventory of Existing Commercial Chemical Substances)
Listed on the Japanese ENCS (Existing & New	Chemical Substances) inventory
Listed on the Korean ECL (Existing Chemicals Listed on NZIoC (New Zealand Inventory of Ch	
Listed on PICCS (Philippines Inventory of Cher	
Listed on the United States TSCA (Toxic Subst	tances Control Act) inventory
Listed on INSQ (Mexican national Inventory of	Chemical Substances)
SECTION 16: Other information	
SECTION 10. Other information	: 15/10/1979
Date of issue	10/00/0010
	: 10/08/2016
Date of issue	: 10/08/2016 : 15/10/2013
Date of issue Revision date	
Date of issue Revision date Supersedes	: 15/10/2013 : Users of breathing apparatus must be trained. Ensure operators understand the toxicity haza
Date of issue Revision date Supersedes Indication of changes:	: 15/10/2013
Date of issue Revision date Supersedes Indication of changes: Training advice	 15/10/2013 Users of breathing apparatus must be trained. Ensure operators understand the toxicity haza Ensure operators understand the flammability hazard.
Date of issue Revision date Supersedes Indication of changes: Training advice This document is only controlled while on the Praxai	: 15/10/2013 : Users of breathing apparatus must be trained. Ensure operators understand the toxicity haza

•

Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico

PRAXAIR	Hydrogen sulfide Safety Data Sheet E-4611 according to the Hazardous Products Regulation (February 11, 2015)
	Date of issue: 10-15-1979 Revision date: 08-10-2016 Supersedes: 10-15-2013
Other information	: When you mix two or more chemicals, you can create additional, unexpected hazards. Obtain and evaluate the safety information for each component before you produce the mixture. Consult an industrial hygienist or other trained person when you evaluate the end product. Before using any plastics, confirm their compatibility with this product
	Praxair asks users of this product to study this SDS and become aware of the product hazards and safety information. To promote safe use of this product, a user should (1) notify employees, agents, and contractors of the information in this SDS and of any other known product hazards and safety information, (2) furnish this information to each purchaser of the product, and (3) ask each purchaser to notify its employees and customers of the product hazards and safety information
	The opinions expressed herein are those of qualified experts within Praxair Canada Inc. We believe that the information contained herein is current as of the date of this Safety Data Sheet. Since the use of this information and the conditions of use are not within the control of Praxair Canada Inc, it is the user's obligation to determine the conditions of safe use of the product. Praxair Canada Inc, SDSs are furnished on sale or delivery by Praxair Canada Inc, or the independent distributors and suppliers who package and sell our products. To obtain current SDSs for these products, contact your Praxair cales representative, local distributor, or supplier, or download from www.praxair.ca. If you have questions regarding Praxair SDSs, would like the document number and date of the latest SDS, or would like the names of the Praxair suppliers in your area, phone or write Praxair Canada Inc, (Phone: 1-888-257-5149; Address: Praxair Canada Inc, 1 City Centre Drive, Suite 1200, Mississauga, Ontario, L5B 1M2).
	PRAXAIR and the Flowing Airstream design are trademarks or registered trademarks of Praxair Technology, Inc. in the United States and/or other countries.
NFPA health hazard	: 4 - Very short exposure could cause death or serious residual injury even though prompt medical attention was given.
NFPA fire hazard	: 4 - Will rapidly or completely vaporize at normal pressure and temperature, or is readily dispersed in air and will burn readily.
NFPA reactivity	: 0 - Normally stable, even under fire exposure conditions, and are not reactive with water.
HMIS III Rating	
Health	: 2 Moderate Hazard - Temporary or minor injury may occur
Flammability	: 4 Severe Hazard - Flammable gases, or very volatile flammable liquids with flash points below 73 F, and boiling points below 100 F. Materials may ignite spontaneously with air. (Class IA)
Physical	: 2 Moderate Hazard - Materials that are unstable and may undergo violent chemical changes at normal temperature and pressure with low risk for explosion. Materials may react violently with water or form peroxides upon exposure to air.

SDS Canada (GHS) - Praxair

This information is based on our current knowledge and is intended to describe the product for the purposes of health, safety and environmental requirements only. It should not therefore be construed as guaranteeing any specific property of the product.

This document is only controlled while on the Praxair Canada Inc. website and a copy of this controlled version is available for download. Praxair cannot assure the integrity or accuracy of any version of this document after it has been downloaded or removed from our website.

EN (English)

SDS ID : E-4611

9/9

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	

Appendix B SO₂ SDS



Safety Data Sheet

Material Name: SULFUR DIOXIDE

SDS ID: MAT22290

al Name: SULFUR DIOXIDE	SUS ID: MAT
Section 1 - PRODUCT AND COMPANY IDENTIFICATION	
Material Name	
SULFUR DIOXIDE	
Synonyms	
MTG MSDS 80; SULFUROUS ACID ANHYDRIDE; SULFUROUS OXIDE; SULPHUR DIOXID	
SULFUROUS ANHYDRIDE; FERMENTICIDE LIQUID; SULFUR DIOXIDE(SO2); SULFUR O	XIDE;
SULFUR OXIDE(SO2)	
Chemical Family	
inorganic, gas	
Product Description	
Classification determined in accordance with Compressed Gas Association standards.	
Product Use	
Industrial and Specialty Gas Applications.	
Restrictions on Use	
None known.	
Details of the supplier of the safety data sheet	
MATHESON TRI-GAS, INC.	
3 Mountainview Road	
Warren, NJ 07059	
General Information: 1-800-416-2505	
Emergency #: 1-800-424-9300 (CHEMTREC)	
Outside the US: 703-527-3887 (Call collect)	
Section 2 - HAZARDS IDENTIFICATION	
Classification in accordance with paragraph (d) of 29 CFR 1910.1200.	
Gases Under Pressure - Liquefied gas	
Acute Toxicity - Inhalation - Gas - Category 3	
Skin Corrosion/Irritation - Category 1B	
Serious Eye Damage/Eye Irritation - Category 1	
Simple Asphyxiant	
GHS Label Elements	
Symbol(s)	
Signal Word	
Signal Word Danger	
Danger	
Danger Hazard Statement(s)	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated.	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled.	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled. Causes severe skin burns and eye damage.	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled. Causes severe skin burns and eye damage. May displace oxygen and cause rapid suffocation.	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled. Causes severe skin burns and eye damage.	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled. Causes severe skin burns and eye damage. May displace oxygen and cause rapid suffocation. Precautionary Statement(s) Prevention	
Danger Hazard Statement(s) Contains gas under pressure; may explode if heated. Toxic if inhaled. Causes severe skin burns and eye damage. May displace oxygen and cause rapid suffocation. Precautionary Statement(s)	

Page 1 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

	Centennial Resource Production, LLC.	H ₂ S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico
MATHESON			

Material Name: SULFUR DIOXIDE

Wash thoroughly after handling. Do not breathe dusts or mists. Response IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. IF ON SKIN (or hair): Remove/take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor. Specific treatment (see label). Storage Store in a well-ventilated place. Keep container tightly closed. Store locked up Protect from sunlight. Disposal Dispose of contents/container in accordance with local/regional/national/international regulations. Other Hazards Contact with liquified gas may cause frostbite.

Section 3 - COMPOSITION / INFORMATION ON INGREDIENTS		GREDIENTS
CAS	Component Name	Percent
7446-09-5	Sulfur dioxide	100.0
	Section 4 - FIRST AID MEASURES	

Inhalation

IF INHALED: Remove person to fresh air and keep at rest in a position comfortable for breathing. Get immediate medical attention.

Skin

IF ON SKIN (or hair): Remove/take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. If frostbite or freezing occur, immediately flush with plenty of lukewarm water (105-115°F; 41-46°C). If warm water is not available, gently wrap affected parts in blankets. DO NOT induce vomiting. Get immediate medical attention.

Eyes

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Get immediate medical attention.

Ingestion

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Get immediate medical attention. Most Important Symptoms/Effects

Acute

Toxic if inhaled, frostbite, suffocation, respiratory tract burns, skin burns, eye burns

Delayed

No information on significant adverse effects.

- Indication of any immediate medical attention and special treatment needed
- Treat symptomatically and supportively.

Note to Physicians

For inhalation, consider oxygen.

Page 2 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

SDS ID: MAT22290

Solomon Federal 105H, 106H, 304H, 404H	Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
404H		Solomon Federal 105H, 106H, 304H,	
		404H	



Sat	ety Data Sheet
al Name: SULFUR DIOXIDE	SDS ID: MA
Section 5 -	FIRE FIGHTING MEASURES
Extinguishing Media	
Suitable Extinguishing Media	
	fires: Use regular foam or flood with fine water spray.
Unsuitable Extinguishing Media	
None known.	
Special Hazards Arising from the Chemica	d d
Negligible fire hazard. Hazardous Combustion Products	
sulfur oxides	
Fire Fighting Measures	
	he without risk. Cool containers with water spray until well after the fire
	p unnecessary people away, isolate hazard area and deny entry.
Special Protective Equipment and Precaut	
	ng self contained breathing apparatus (SCBA) for protection against
possible exposure.	
Section 6 - ACC	IDENTAL RELEASE MEASURES
Personal Precautions, Protective Equipment	nt and Emergency Procedures
Wear personal protective clothing and equipr	nent, see Section 8.
Methods and Materials for Containment a	
	d area and deny entry. Stay upwind and keep out of low areas.
	uation radius: 150 feet. Stop leak if possible without personal risk.
Reduce vapors with water spray. Do not get v	vater directly on material.
Environmental Precautions	
Avoid release to the environment.	
	HANDLING AND STORAGE
Precautions for Safe Handling	with the second se
	o not breathe gas, fumes, vapor, or spray. Wash hands thoroughly after
	tilated area. Wear protective gloves/protective clothing/eye
	rk clothing should not be allowed out of the workplace. Do not eat, p only in original container. Avoid release to the environment.
Conditions for Safe Storage, Including any	
Store in a well-ventilated place. Keep contain	
Store locked up.	ter ugnuy erosea.
Protect from sunlight.	
	nt regulations and standards. Protect from physical damage. Store
outside or in a detached building. Keep separa	

outside or in a detached building. Keep separated from incompatible substances.

Incompatible Materials

bases, combustible materials, halogens, metal carbide, metal oxides, metals, oxidizing materials, peroxides, reducing agents

Section 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

Component Exposure Limits

Sulfur dioxide	7446-09-5
ACGIH:	0.25 ppm STEL

Page 3 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	



Material Name: SULFUR DIOXIDE

NIOSH:	2 ppm TWA ; 5 mg/m3 TWA	
	5 ppm STEL ; 13 mg/m3 STEL	
	100 ppm IDLH	
OSHA (US):	5 ppm TWA ; 13 mg/m3 TWA	
Mexico:	0.25 ppm STEL [PPT-CT]	

ACGIH - Threshold Limit Values - Biological Exposure Indices (BEI)

There are no biological limit values for any of this product's components.

Engineering Controls

Provide local exhaust or process enclosure ventilation system. Ensure compliance with applicable exposure limits. Individual Protection Measures, such as Personal Protective Equipment

Eye/face protection

Wear splash resistant safety goggles with a faceshield. Contact lenses should not be worn. Provide an emergency eye wash fountain and quick drench shower in the immediate work area.

Skin Protection

Wear appropriate chemical resistant clothing. Wear chemical resistant clothing to prevent skin contact. Respiratory Protection

Any self-contained breathing apparatus that has a full facepiece and is operated in a pressure-demand or other positive-pressure mode.

Glove Recommendations

Wear appropriate chemical resistant gloves.

Sectio	on 9 - PHYSICAL A	ND CHEMICAL PROPERTIE	S
Appearance	colorless gas	Physical State	gas
Odor	irritating odor	Color	colorless
Odor Threshold	3 - 5 ppm	рН	(Acidic in solution)
Melting Point	-73 °C (-99 °F)	Boiling Point	-10 °C (14 °F)
Boiling Point Range	Not available	Freezing point	Not available
Evaporation Rate	>1 (Butyl acetate = 1)	Flammability (solid, gas)	Not available
Autoignition Temperature	Not available	Flash Point	(Not flammable)
Lower Explosive Limit	Not available	Decomposition temperature	Not available
Upper Explosive Limit	Not available	Vapor Pressure	2432 mmHg @ 20 °C
Vapor Density (air=1)	2.26	Specific Gravity (water=1)	1.462 at -10 °C

Page 4 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

SDS ID: MAT22290

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	



Mate

-2290

Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	Partition coefficient: n-octanol/water Kinematic viscosity Density Molecular Formula Benzene, sulfuryl chloride, nitrobe ILITY AND REACTIVITY ture or explode if exposed to heat. e, metal oxides, metals, oxidizing r	ſ	
Not available liquified gas 64.06 eid, ether, chloroform, Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	Density Molecular Formula Benzene, sulfuryl chloride, nitrobe ILITY AND REACTIVITY ture or explode if exposed to heat.	Not available S-O2	
liquified gas 64.06 cid, ether, chloroform, Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	Molecular Formula Benzene, sulfuryl chloride, nitrobe ILITY AND REACTIVITY ture or explode if exposed to heat.	enzenes, Toluene, acetone	
64.06 cid, ether, chloroform, Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	Benzene, sulfuryl chloride, nitrobe ILITY AND REACTIVITY ture or explode if exposed to heat.	enzenes, Toluene, acetone	
cid, ether, chloroform, Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	ILITY AND REACTIVITY	ſ	
Section 10 - STAB ed. and pressure. actions al. Containers may rupt halogens, metal carbid	ILITY AND REACTIVITY	ſ	
ed. and pressure. actions al. Containers may rupt halogens, metal carbid	ture or explode if exposed to heat.		
and pressure. actions al. Containers may rupt halogens, metal carbid		materials, peroxides, reducinț	
Incompatible Materials bases, combustible materials, halogens, metal carbide, metal oxides, metals, oxidizing materials, peroxides, reducing agents Hazardous decomposition products oxides of sulfur Section 11 - TOXICOLOGICAL INFORMATION Information on Likely Routes of Exposure Inhalation Toxic if inhaled. Causes damage to respiratory system, burns, difficulty breathing Skin Contact skin burns			
	Debuical information		
hea, stomach pain		ing selected endpoints are	
1	hea, stomach pain /LC50 al have been reviewed	hea, stomach pain /LC50 al have been reviewed in various sources and the followi	

Page 5 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

ntonnial Basa	urco Droduct	ion LLC	H-S Contingency Plan	Los County, Now Movice
ntennial Reso	urce Product	ion, llc.	H₂S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico
	MATH	ESON		
	askThe Gas	Professionals'*		
			Safety Data Sheet	
Mater	tial Name: SULF Toxic if inhaled, Delayed Effects No information of Irritation/Corre respiratory tract	frostbite, suff on significant a osivity Data	ocation, respiratory tract burns, skin burns, eye burns	SDS ID: MAT22290
	Respiratory Ser No data availabl Dermal Sensitiz No data availabl Component Ca	c. ation c.		
	Sulfur dioxide	7446-09-5		
	ACGIH:		ssifiable as a Human Carcinogen	
	IARC: Germ Cell Mut		(4 [1992] (Group 3 (not classifiable))	
	No data availabl Tumorigenic D No data availabl Reproductive T	c. ata c		
	No target organs	Organ Toxici identified. Organ Toxici	ty - Single Exposure ty - Repeated Exposure	
	Aspiration haza Not applicable.	ions Aggrava	ted by Exposure	
	6		ection 12 - ECOLOGICAL INFORMATION	
	Component An No LOLI ecotox Persistence and No data availabl Bioaccumulativ No data availabl	icity data are a Degradability c. e Potential	vailable for this product's components.	
	Mobility No data availabl	c.	ortion 12 DISDOCAL CONSIDERATIONS	1
	Component Wa	ds nts/container i ste Numbers	ection 13 - DISPOSAL CONSIDERATIONS n accordance with local/regional/national/international regula d waste numbers for this product's components.	ations.
	US DOT Inform Shipping Name	snation:	section 14 - TRANSPORT INFORMATION	
	supping Name	, SOLFOR DI	OAIDE	

Centennial Resource Production, LLC.	H ₂ S Contingency Plan	Lea County, New Mexico
	Solomon Federal 105H, 106H, 304H,	
	404H	



Material Name: SULFUR DIOXIDE

Hazard Class: 2.3 UN/NA #: UN1079 Required Label(s): 2.3

IMDG Information: Shipping Name: SULPHUR DIOXIDE Hazard Class: 2.3 UN#: UN1079 Required Label(s): 2.3

TDG Information: Shipping Name: SULFUR DIOXIDE Hazard Class: 2.3 UN#: UN1079 Required Label(s): 2.3

International Bulk Chemical Code

This material does not contain any chemicals required by the IBC Code to be identified as dangerous chemicals in bulk.

Section 15 - REGULATORY INFORMATION

U.S. Federal Regulations

This material contains one or more of the following chemicals required to be identified under SARA Section 302 (40 CFR 355 Appendix A), SARA Section 313 (40 CFR 372.65), CERCLA (40 CFR 302.4), TSCA 12(b), and/or require an OSHA process safety plan.

Sulfur dioxide	7446-09-5
SARA 302:	500 lb TPQ
OSHA (safety):	1000 lb TQ (Liquid)
SARA 304:	500 lb EPCRA RQ

SARA Section 311/312 (40 CFR 370 Subparts B and C) reporting categories

Gas Under Pressure; Acute toxicity; Skin Corrosion/Irritation; Serious Eye Damage/Eye Irritation; Simple Asphyxiant

U.S. State Regulations

The following components appear on one or more of the following state hazardous substances lists:

Component	CAS	CA	MA	MN	NJ	PA
Sulfur dioxide	7446-09-5	Yes	Yes	Yes	Yes	Yes

California Safe Drinking Water and Toxic Enforcement Act (Proposition 65)



This product can expose you to chemicals including Sulfur dioxide , which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.


Page 7 of 9

Issue date: 2021-01-30 Revision 8.0

Print date: 2021-01-30

SDS ID: MAT22290

nnial Resource Production, LLC.	H₂S Contingency Plan Solomon Federal 105H, 106H, 304H, 404H	Lea County, New Mexico						
ask The Gas Professionals								
usk The das Professionals								
	Safety Data Sheet							
Material Name: SULFUR DIOXI	•	SDS ID: MAT22290						
Sulfur dioxide 7446-09-5								
Repro/Dev. Tox developme	ental toxicity, 7/29/2011							
Component Analysis - Inver Sulfur dioxide (7446-09-5)	ntory							
US CA AU CN EU	J JP - ENCS JP - ISHL KR KECI - Annex 1 K	R KECI - Annex 2						
Yes DSL Yes Yes EI	N Yes Yes N	0						
KR - REACH CCA MX	NZ PH TH-TECI TW, CN VN (Draft)							
	NZ PH TH-TECI TW, CN VN (Draft) Yes Yes Yes Yes Yes							
10	Section 16 - OTHER INFORMATION							
NFPA Ratings	NFPA Ratings							
	Hazard Scale: 0 = Minimal 1 = Slight 2 = Moderate 3 = Serious 4 = Severe							
SDS update: 02/10/2016	Summary of Changes SDS update: 02/10/2016							
Key / Legend ACGIH - American Conferer	Key / Legend ACGIH - American Conference of Governmental Industrial Hygienists; ADR - European Road Transport; AU -							
	Il Oxygen Demand; C - Celsius; CA - Canada; CA/MA/ unesota/New Jersey/Pennsylvania*; CAS - Chemical Ab							
Comprehensive Environment	al Response, Compensation, and Liability Act; CFR - C	ode of Federal Regulations						
Deutsche Forschungsgemeins	abelling, and Packaging; CN - China; CPR - Controlled chaft; DOT - Department of Transportation; DSD - Dar	ngerous Substance Directive;						
	List; EC – European Commission; EEC - European Ecology ing Commercial Chemical Substances); EINECS - Euro							
	nces; ENCS - Japan Existing and New Chemical Substa ency; EU - European Union; F - Fahrenheit; F - Backgr							
Exposure Indices); IARC - In	ternational Agency for Research on Cancer; IATA - Int	ernational Air Transport						
Immediately Dangerous to Li	onal Civil Aviation Organization; IDL - Ingredient Disc fe and Health; IMDG - International Maritime Dangero	us Goods; ISHL - Japan						
-	aw; IUCLID - International Uniform Chemical Informa coefficient; KR KECI Annex 1 - Korea Existing Chem							
Existing Chemicals List (KE	CL); KR KECI Annex 2 - Korea Existing Chemicals Inv CL), KR - Korea; LD50/LC50 - Lethal Dose/ Lethal Co	ventory (KECI) / Korea						
- Korea Registration and Eva	uation of Chemical Substances Chemical Control Act; 1	LEL - Lower Explosive Limit;						
	DLI - List Of LIsts [™] - ChemADVISOR's Regulatory Da orkplace; MEL - Maximum Exposure Limits; MX – M							
- National Fire Protection Ag	ency; NIOSH - National Institute for Occupational Safe Nq - Non-quantitative; NSL - Non-Domestic Substanc	ty and Health; NJTSR - New						
National Toxicology Program	r; NZ - New Zealand; OSHA - Occupational Safety and	Health Administration; PEL-						
	PH - Philippines; RCRA - Resource Conservation and R horisation, and restriction of Chemicals; RID - Europea							
-	Reauthorization Act; Sc - Semi-quantitative; STEL - Sh							
Page 8 of 9	Issue date: 2021-01-30 Revision 8.0	Print date: 2021-01-30						







PHOENIX TECHNOLOGY SERVICES

Centennial Resources Development, Inc.

Lea County, NM (NAD83 - UTM Zone 13) Sheba/Solomon Solomon Federal Com 105H


OH

Plan: Plan 1 08-05-22

Standard Planning Report

05 August, 2022





Measured Depth (usft)	Inclination (°)	Azimuth (°)	Vertical Depth (usft)	+N/-S (usft)	+E/-W (usft)	Dogleg Rate (°/100usft)	Build Rate (°/100usft)	Turn Rate (°/100usft)	TFO (°)	Target
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.000	
2,000.00	0.00	0.00	2,000.00	0.00	0.00	0.00	0.00	0.00	0.000	
3,000.23	10.00	210.90	2,995.15	-74.72	-44.73	1.00	1.00	0.00	210.903	
3,395.12	10.00	210.90	3,384.05	-133.57	-79.95	0.00	0.00	0.00	0.000	
4,395.35	0.00	0.00	4,379.20	-208.29	-124.68	1.00	-1.00	0.00	180.000	
9,057.18	0.00	0.00	9,041.04	-208.29	-124.68	0.00	0.00	0.00	0.000	
9,807.18	90.00	0.00	9,518.50	269.17	-124.65	12.00	12.00	0.00	0.003	
17,013.18	90.00	0.00	9,518.50	7,475.17	-124.21	0.00	0.00	0.00	0.000	BHL - Solomon Fe

8/5/2022 1:18:39PM



Planning Report



Database:	USA Compass	Local Co-ordinate Reference:	Well Solomon Federal Com 105H
Company:	Centennial Resources Development, Inc.	TVD Reference:	RKB @ 3488.50usft (TBD)
Project:	Lea County, NM (NAD83 - UTM Zone 13)	MD Reference:	RKB @ 3488.50usft (TBD)
Site:	Sheba/Solomon	North Reference:	True
Well:	Solomon Federal Com 105H	Survey Calculation Method:	Minimum Curvature
Wellbore:	OH		
Design:	Plan 1 08-05-22		

Planned Survey

Measured Depth (usft)	Inclination (°)	Azimuth (°)	Vertical Depth (usft)	+N/-S (usft)	+E/-W (usft)	Vertical Section (usft)	Dogleg Rate (°/100usft)	Build Rate (°/100usft)	Turn Rate (°/100usft)
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1,082.50	0.00	0.00	1,082.50	0.00	0.00	0.00	0.00	0.00	0.00
Rustler									
1,708.50	0.00	0.00	1,708.50	0.00	0.00	0.00	0.00	0.00	0.00
Salado									
2,000.00	0.00	0.00	2,000.00	0.00	0.00	0.00	0.00	0.00	0.00
	n 1.00°/100' Bւ								
2,100.00	1.00	210.90	2,099.99	-0.75	-0.45	-0.74	1.00	1.00	0.00
2,200.00	2.00	210.90	2,199.96	-2.99	-1.79	-2.96	1.00	1.00	0.00
2,300.00	3.00	210.90	2,299.86	-6.74	-4.03	-6.67	1.00	1.00	0.00
2,400.00	4.00	210.90	2,399.68	-11.98	-7.17	-11.85	1.00	1.00	0.00
2,500.00	5.00	210.90	2,499.37	-18.71	-11.20	-18.52	1.00	1.00	0.00
2,600.00	6.00	210.90	2,598.90	-26.93	-16.12	-26.66	1.00	1.00	0.00
2,700.00	7.00	210.90	2,698.26	-36.64	-21.93	-36.27	1.00	1.00	0.00
2,800.00	8.00	210.90	2,797.40	-47.84	-28.64	-47.36	1.00	1.00	0.00
2,900.00	9.00	210.90	2,896.30	-60.53	-36.23	-59.92	1.00	1.00	0.00
3,000.00	10.00	210.90	2,994.93	-74.69	-44.71	-73.93	1.00	1.00	0.00
3,000.23	10.00	210.90	2,995.15	-74.72	-44.73	-73.97	1.00	1.00	0.00
Hold 10.00	° Inc at 210.90	° Azm							
3,100.00	10.00	210.90	3,093.41	-89.59	-53.63	-88.69	0.00	0.00	0.00
3,200.00	10.00	210.90	3,191.89	-104.49	-62.55	-103.44	0.00	0.00	0.00
3,300.00	10.00	210.90	3,290.37	-119.40	-71.47	-118.19	0.00	0.00	0.00
3,395.12	10.00	210.90	3,384.05	-133.57	-79.95	-132.23	0.00	0.00	0.00
	°/100' Drop	040.00	0.000.05	104.00	00.00	100.04	4.00	4.00	0.00
3,400.00	9.95	210.90	3,388.85	-134.30	-80.39	-132.94	1.00	-1.00	0.00
3,500.00	8.95	210.90	3,487.49	-148.39	-88.82	-146.89	1.00	-1.00	0.00
3,600.00	7.95	210.90	3,586.40	-161.00	-96.37	-159.38	1.00	-1.00	0.00
3,700.00	6.95	210.90	3,685.56 3,784.92	-172.13	-103.03	-170.40 -179.95	1.00	-1.00 -1.00	0.00
3,800.00 3,900.00	5.95 4.95	210.90 210.90	3,764.92 3,884.47	-181.78 -189.93	-108.81 -113.69	-179.95	1.00 1.00	-1.00	0.00 0.00
4,000.00	3.95	210.90	3,984.17	-196.60	-117.68	-194.61	1.00	-1.00	0.00
4,100.00 4,200.00	2.95 1.95	210.90 210.90	4,083.98 4,183.89	-201.76 -205.44	-120.77 -122.97	-199.73 -203.37	1.00 1.00	-1.00 -1.00	0.00 0.00
4,200.00	0.95	210.90	4,183.86	-207.61	-122.97	-205.57	1.00	-1.00	0.00
4,395.35	0.00	0.00	4,379.20	-208.29	-124.68	-206.19	1.00	-1.00	0.00
Begin Vert									
4.534.65	0.00	0.00	4,518.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
,	lether Anhydr		1,010.00	200.20	124.00	200.10	0.00	0.00	0.00
5,444.65	0.00	0.00	5,428.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
Lamar									
5,494.65	0.00	0.00	5,478.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
Bell Canyo									
6,407.65	0.00	0.00	6,391.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
Cherry Ca									
6,567.65	0.00	0.00	6,551.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
Manzanita	Lime								
7,847.65	0.00	0.00	7,831.50	-208.29	-124.68	-206.19	0.00	0.00	0.00
Brushy Ca									
9,057.18	0.00	0.00	9,041.04	-208.29	-124.68	-206.19	0.00	0.00	0.00
	gin 12.00°/100'								
9,100.00	5.14	0.00	9,083.80	-206.38	-124.68	-204.28	12.00	12.00	0.00
9,200.00	17.14	0.00	9,181.73	-187.09	-124.68	-185.00	12.00	12.00	0.00
9,300.00	29.14	0.00	9,273.52	-147.87	-124.67	-145.78	12.00	12.00	0.00

8/5/2022 1:18:39PM

Page 3

COMPASS 5000.15 Build 93A



Planning Report



Database:	USA Compass	Local Co-ordinate Reference:	Well Solomon Federal Com 105H
Company:	Centennial Resources Development, Inc.	TVD Reference:	RKB @ 3488.50usft (TBD)
Project:	Lea County, NM (NAD83 - UTM Zone 13)	MD Reference:	RKB @ 3488.50usft (TBD)
Site:	Sheba/Solomon	North Reference:	True
Well:	Solomon Federal Com 105H	Survey Calculation Method:	Minimum Curvature
Wellbore:	OH		
Design:	Plan 1 08-05-22		

Planned Survey

[easured Depth (usft)	Inclination (°)	Azimuth (°)	Vertical Depth (usft)	+N/-S (usft)	+E/-W (usft)	Vertical Section (usft)	Dogleg Rate (°/100usft)	Build Rate (°/100usft)	Turn Rate (°/100usft)
1	9,361.92	36.57	0.00	9,325.50	-114.30	-124.67	-112.22	12.00	12.00	0.00
В	Sone Sprin									
	9,400.00	41.14	0.00	9,355.15	-90.42	-124.67	-88.34	12.00	12.00	0.00
	9,404.47	41.67	0.00	9,358.50	-87.46	-124.67	-85.38	12.00	12.00	0.00
	valon	44.07	0.00	0.070.50	00.00	404.07	00.50	10.00	40.00	0.00
	9,431.97	44.97	0.00	9,378.50	-68.60	-124.67	-66.52	12.00	12.00	0.00
	arget Top 9.500.00	at 0'VS 53.14	0.00	9,423.05	-17.25	-124.67	-15.18	12.00	12.00	0.00
	-,									
	9,600.00	65.14	0.00	9,474.25	68.43	-124.66	70.49	12.00	12.00	0.00
	9,700.00 9,800.00	77.14 89.14	0.00 0.00	9,506.52 9,518.45	162.89 261.99	-124.66 -124.65	164.93 264.02	12.00 12.00	12.00 12.00	0.00 0.00
	9,807.18	90.00	0.00	9,518.50	269.17	-124.05	204.02	12.00	12.00	0.00
		.00° Inc at 0.0		0,010.00	200.11	121.00	211.20	12.00	12.00	0.00
	9,900.00	90.00	0.00	9,518.50	361.99	-124.64	364.01	0.00	0.00	0.00
	0,000.00	90.00	0.00	9,518.50	461.99	-124.64	464.00	0.00	0.00	0.00
	0,000.00	90.00	0.00	9,518.50	561.99	-124.64	404.00 563.98	0.00	0.00	0.00
	0,200.00	90.00	0.00	9,518.50	661.99	-124.63	663.97	0.00	0.00	0.00
	0,300.00	90.00	0.00	9,518.50	761.99	-124.62	763.95	0.00	0.00	0.00
1	0,400.00	90.00	0.00	9,518.50	861.99	-124.61	863.94	0.00	0.00	0.00
1	0,500.00	90.00	0.00	9,518.50	961.99	-124.61	963.93	0.00	0.00	0.00
	0,600.00	90.00	0.00	9,518.50	1,061.99	-124.60	1,063.91	0.00	0.00	0.00
	0,700.00	90.00	0.00	9,518.50	1,161.99	-124.60	1,163.90	0.00	0.00	0.00
	0,800.00	90.00	0.00	9,518.50	1,261.99	-124.59	1,263.88	0.00	0.00	0.00
	0,900.00	90.00	0.00	9,518.50	1,361.99	-124.58	1,363.87	0.00	0.00	0.00
	1,000.00	90.00	0.00	9,518.50	1,461.99	-124.58	1,463.86	0.00	0.00	0.00
	1,100.00 1,200.00	90.00 90.00	0.00 0.00	9,518.50 9,518.50	1,561.99 1,661.99	-124.57 -124.57	1,563.84 1,663.83	0.00 0.00	0.00 0.00	0.00 0.00
	1,300.00	90.00	0.00	9,518.50 9,518.50	1,761.99	-124.57	1,763.81	0.00	0.00	0.00
	1,400.00	90.00	0.00	9,518.50	1,861.99	-124.55	1,863.80	0.00	0.00	0.00
	1,500.00	90.00	0.00	9,518.50	1,961.99	-124.55	1,963.79	0.00	0.00	0.00
	1,600.00	90.00	0.00	9,518.50	2,061.99	-124.55	2,063.77	0.00	0.00	0.00
	1,700.00	90.00	0.00	9,518.50	2,161.99	-124.54	2,163.76	0.00	0.00	0.00
	1,800.00	90.00	0.00	9,518.50	2,261.99	-124.53	2,263.75	0.00	0.00	0.00
1	1,900.00	90.00	0.00	9,518.50	2,361.99	-124.52	2,363.73	0.00	0.00	0.00
1	2,000.00	90.00	0.00	9,518.50	2,461.99	-124.52	2,463.72	0.00	0.00	0.00
	2,100.00	90.00	0.00	9,518.50	2,561.99	-124.51	2,563.70	0.00	0.00	0.00
	2,200.00	90.00	0.00	9,518.50	2,661.99	-124.50	2,663.69	0.00	0.00	0.00
	2,300.00 2,400.00	90.00 90.00	0.00 0.00	9,518.50 9,518.50	2,761.99 2,861.99	-124.50 -124.49	2,763.68 2,863.66	0.00 0.00	0.00 0.00	0.00 0.00
					-					
	2,500.00	90.00	0.00	9,518.50	2,961.99	-124.49	2,963.65	0.00	0.00	0.00
	2,600.00 2,700.00	90.00 90.00	0.00 0.00	9,518.50 9,518.50	3,061.99 3,161.99	-124.48 -124.47	3,063.63 3,163.62	0.00 0.00	0.00 0.00	0.00 0.00
	2,800.00	90.00	0.00	9,518.50	3,261.99	-124.47	3,263.61	0.00	0.00	0.00
	2,900.00	90.00	0.00	9,518.50	3,361.99	-124.46	3,363.59	0.00	0.00	0.00
1:	3,000.00	90.00	0.00	9,518.50	3,461.99	-124.46	3,463.58	0.00	0.00	0.00
	3,100.00	90.00	0.00	9,518.50	3,561.99	-124.45	3,563.56	0.00	0.00	0.00
1	3,200.00	90.00	0.00	9,518.50	3,661.99	-124.44	3,663.55	0.00	0.00	0.00
	3,300.00	90.00	0.00	9,518.50	3,761.99	-124.44	3,763.54	0.00	0.00	0.00
	3,400.00	90.00	0.00	9,518.50	3,861.99	-124.43	3,863.52	0.00	0.00	0.00
	3,500.00	90.00	0.00	9,518.50	3,961.99	-124.43	3,963.51	0.00	0.00	0.00
	3,600.00	90.00	0.00	9,518.50	4,061.99	-124.42	4,063.49	0.00	0.00	0.00
	3,700.00 3,800.00	90.00 90.00	0.00 0.00	9,518.50 9,518.50	4,161.99 4,261.99	-124.41 -124.41	4,163.48 4,263.47	0.00 0.00	0.00 0.00	0.00 0.00
I.	5,000.00	90.00	0.00	9,010.00	4,201.99	-124.41	4,203.47	0.00	0.00	0.00

8/5/2022 1:18:39PM

COMPASS 5000.15 Build 93A



Planning Report



Database:	USA Compass	Local Co-ordinate Reference:	Well Solomon Federal Com 105H
Company:	Centennial Resources Development, Inc.	TVD Reference:	RKB @ 3488.50usft (TBD)
Project:	Lea County, NM (NAD83 - UTM Zone 13)	MD Reference:	RKB @ 3488.50usft (TBD)
Site:	Sheba/Solomon	North Reference:	True
Well:	Solomon Federal Com 105H	Survey Calculation Method:	Minimum Curvature
Wellbore:	ОН	-	
Design:	Plan 1 08-05-22		

Planned Survey

Measured Depth (usft)	Inclination (°)	Azimuth (°)	Vertical Depth (usft)	+N/-S (usft)	+E/-W (usft)	Vertical Section (usft)	Dogleg Rate (°/100usft)	Build Rate (°/100usft)	Turn Rate (°/100usft)
13,900.00	90.00	0.00	9,518.50	4,361.99	-124.40	4,363.45	0.00	0.00	0.00
14,000.00	90.00	0.00	9,518.50	4,461.99	-124.40	4,463.44	0.00	0.00	0.00
14,100.00	90.00	0.00	9,518.50	4,561.99	-124.39	4,563.43	0.00	0.00	0.00
14,200.00	90.00	0.00	9,518.50	4,661.99	-124.38	4,663.41	0.00	0.00	0.00
14,300.00	90.00	0.00	9,518.50	4,761.99	-124.38	4,763.40	0.00	0.00	0.00
14,400.00	90.00	0.00	9,518.50	4,861.99	-124.37	4,863.38	0.00	0.00	0.00
14,500.00	90.00	0.00	9,518.50	4,961.99	-124.37	4,963.37	0.00	0.00	0.00
14,600.00	90.00	0.00	9,518.50	5,061.99	-124.36	5,063.36	0.00	0.00	0.00
14,700.00	90.00	0.00	9,518.50	5,161.99	-124.35	5,163.34	0.00	0.00	0.00
14,800.00	90.00	0.00	9,518.50	5,261.99	-124.35	5,263.33	0.00	0.00	0.00
14,900.00	90.00	0.00	9,518.50	5,361.99	-124.34	5,363.31	0.00	0.00	0.00
15,000.00	90.00	0.00	9,518.50	5,461.99	-124.34	5,463.30	0.00	0.00	0.00
15,100.00	90.00	0.00	9,518.50	5,561.99	-124.33	5,563.29	0.00	0.00	0.00
15,200.00	90.00	0.00	9,518.50	5,661.99	-124.32	5,663.27	0.00	0.00	0.00
15,300.00	90.00	0.00	9,518.50	5,761.99	-124.32	5,763.26	0.00	0.00	0.00
15,400.00	90.00	0.00	9,518.50	5,861.99	-124.31	5,863.24	0.00	0.00	0.00
15,500.00	90.00	0.00	9,518.50	5,961.99	-124.31	5,963.23	0.00	0.00	0.00
15,600.00	90.00	0.00	9,518.50	6,061.99	-124.30	6,063.22	0.00	0.00	0.00
15,700.00	90.00	0.00	9,518.50	6,161.99	-124.29	6,163.20	0.00	0.00	0.00
15,800.00	90.00	0.00	9,518.50	6,261.99	-124.29	6,263.19	0.00	0.00	0.00
15,900.00	90.00	0.00	9,518.50	6,361.99	-124.28	6,363.18	0.00	0.00	0.00
16,000.00	90.00	0.00	9,518.50	6,461.99	-124.28	6,463.16	0.00	0.00	0.00
16,100.00	90.00	0.00	9,518.50	6,561.99	-124.27	6,563.15	0.00	0.00	0.00
16,200.00	90.00	0.00	9,518.50	6,661.99	-124.26	6,663.13	0.00	0.00	0.00
16,300.00	90.00	0.00	9,518.50	6,761.99	-124.26	6,763.12	0.00	0.00	0.00
16,400.00	90.00	0.00	9,518.50	6,861.99	-124.25	6,863.11	0.00	0.00	0.00
16,500.00	90.00	0.00	9,518.50	6,961.99	-124.25	6,963.09	0.00	0.00	0.00
16,600.00	90.00	0.00	9,518.50	7,061.99	-124.24	7,063.08	0.00	0.00	0.00
16,700.00	90.00	0.00	9,518.50	7,161.99	-124.23	7,163.06	0.00	0.00	0.00
16,800.00	90.00	0.00	9,518.50	7,261.99	-124.23	7,263.05	0.00	0.00	0.00
16,900.00	90.00	0.00	9,518.50	7,361.99	-124.22	7,363.04	0.00	0.00	0.00
17,000.00	90.00	0.00	9,518.50	7,461.99	-124.22	7,463.02	0.00	0.00	0.00
17.013.18	90.00	0.00	9,518.50	7,475.17	-124.21	7,476.20	0.00	0.00	0.00

Design Targets									
Target Name - hit/miss target - Shape	Dip Angle (°)	Dip Dir. (°)	TVD (usft)	+N/-S (usft)	+E/-W (usft)	Northing (usft)	Easting (usft)	Latitude	Longitude
FTP - Solomon Feder - plan misses targ - Point			9,518.50 at 9410.28	-248.64 usft MD (936	-124.68 2.82 TVD, -	11,687,658.98 83.57 N, -124.67	, ,	2° 11' 19.605876 N	N 3° 27' 21.725181 W
BHL - Solomon Fede - plan hits target o - Rectangle (side	center		9,518.50 .00)	7,475.17	-124.21	11,695,380.93	2,117,811.33	2° 12' 36.034573 N	N 3° 27' 21.719838 W

8/5/2022 1:18:39PM

Received by OCD: 7/24/2023 8:26:52 AM



Planning Report




Database: Company:	USA Compass Centennial Resources Development, Inc.	Local Co-ordinate Reference: TVD Reference:	Well Solomon Federal Com 105H RKB @ 3488.50usft (TBD)
Project:	Lea County, NM (NAD83 - UTM Zone 13)	MD Reference:	RKB @ 3488.50usft (TBD)
Site:	Sheba/Solomon	North Reference:	True
Well:	Solomon Federal Com 105H	Survey Calculation Method:	Minimum Curvature
Wellbore:	ОН		
Design:	Plan 1 08-05-22		

Formations

Measured Depth (usft)	Vertical Depth (usft)	Name	Lithology	Dip (°)	Dip Direction (°)
1,082.50	1,082.50	Rustler			
1,708.50	1,708.50	Salado			
4,534.65	4,518.50	BX BLM (Flether Anhydrite)			
5,444.65	5,428.50	Lamar			
5,494.65	5,478.50	Bell Canyon			
6,407.65	6,391.50	Cherry Canyon			
6,567.65	6,551.50	Manzanita Lime			
7,847.65	7,831.50	Brushy Canyon			
9,361.92	9,325.50	Bone Spring Lime			
9,404.47	9,358.50	Avalon			
9,431.97	9,378.50	Target Top at 0'VS			

Plan Annotations

Measured	Vertical	Local Coor	dinates	
Depth (usft)	Depth (usft)	+N/-S (usft)	+E/-W (usft)	Comment
2,000.00	2,000.00	0.00	0.00	KOP, Begin 1.00°/100' Build
3,000.23	2,995.15	-74.72	-44.73	Hold 10.00° Inc at 210.90° Azm
3,395.12	3,384.05	-133.57	-79.95	Begin 1.00°/100' Drop
4,395.35	4,379.20	-208.29	-124.68	Begin Vertical Hold
9,057.18	9,041.04	-208.29	-124.68	KOP2, Begin 12.00°/100' Build
9,807.18	9,518.50	269.17	-124.65	LP, Hold 90.00° Inc at 0.00° Azm
17,013.18	9,518.50	7,475.17	-124.21	TD at 17013.18



Centennial Resource Development New Mexico Multi-Well Pad Drilling Batch Setting Procedures

<u>13-3/8" Surface Casing</u> - CRD intends to Batch set all 13-3/8" casing to a depth approved in the APD. 17-1/2" Surface Holes will be batch drilled by a rig. Appropriate notifications will be made prior to spudding the well, running and cementing casing and prior to skidding to the rig to the next well on pad.

- 1. Drill 17-1/2" Surface hole to Approved Depth with Rig and perform wellbore cleanup cycles. Trip out and rack back drilling BHA.
- 2. Run and land 13-3/8" 54.5# J55 BTC casing see Illustration 1-1 Below to depth approved in APD.
- 3. Set packoff and test to 5k psi
- 4. Offline Cement
- 5. Install nightcap with Pressure Gauge on wellhead. Nightcap is shown on final wellhead Stack up Illustration #2-2 page 3.
- 6. Skid Rig to adjacent well to drill Surface hole.
- Surface casing test will be performed by the rig in order to allow ample time for Cement to develop 500psi compressive strength. Casing test to 0.22 psi/ft or 1500 psi whichever is greater - not to exceed 70% casing burst.




Illustration 1-1

<u>Intermediate Casing</u> – CRD intends to Batch set all intermediate casing strings to a depth approved in the APD, typically set into Lamar. 12-1/4" Intermediate Holes will be batch drilled by the rig. Appropriate notifications will be made prior Testing BOPE, and prior to running/cementing all casing strings.

- 1. Rig will remove the nightcap and install and test BOPE.
- 2. Test Surface casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 3. Install wear bushing then drill out 13-3/8" shoe-track plus 20' and conduct FIT to minimum of the MW equivalent anticipated to control the formation pressure to the next casing point.
- 4. Drill Intermediate hole to approved casing point. Trip out of hole with BHA to run Casing.
- 5. Remove wear bushing then run and land Intermediate Casing with mandrel hanger in wellhead.
- 6. Cement casing to surface with floats holding.
- 7. Washout stack then run wash tool in wellhead and wash hanger and pack-off setting area.
- 8. Install pack-off and test void to 5,000 psi for 15 minutes. Nightcap shown on final wellhead stack up illustration 2-2 on page 3.
- 9. Test casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 10. Install nightcap skid rig to adjacent well to drill Intermediate hole.




Illustration 2-2

<u>Production Casing</u> – CRD intends to Batch set all Production casings with Rig. Appropriate notifications will be made prior Testing BOPE, and prior to running/cementing all casing strings.

- 1. Big Rig will remove the nightcap and install and test BOPE.
- 2. Install wear bushing then drill Intermediate shoe-track plus 20' and conduct FIT to minimum MW equivalent to control the formation pressure to TD of well.
- 3. Drill Vertical hole to KOP Trip out for Curve BHA.
- 4. Drill Curve, landing in production interval Trip for Lateral BHA.
- 5. Drill Lateral / Production hole to Permitted BHL, perform cleanup cycles and trip out to run 5-1/2" Production Casing.
- 6. Remove wear bushing then run 5-1/2" production casing to TD landing casing mandrel in wellhead.
- 7. Cement 5-1/2" Production string to surface with floats holding.

- 8. Run in with wash tool and wash wellhead area install pack-off and test void to 5,000psi for 15 minutes.
- 9. Install BPV in 5-1/2" mandrel hanger Nipple down BOPE and install nightcap.
- 10. Test nightcap void to 5,000psi for 30 minutes per illustration 2-2 page 3.
- 11. Skid rig to adjacent well on pad to drill production hole.


GEOLOGIC PROG


.

			WELL	NAME	Solomon	Federal C	om 105H	7/21/	2022
	-0-		AR	EA	Soloi	mon	API		
CENIT			HZ TA	RGET	Avalon		WI %		
CEN1		NIAL	LAT LE	NGTH	7,7	00	AFE#		
RESOURCE	E DEVELOPM	ent, llc	TRRC P	ERMIT			COUNTY	Le	а
	TWNP	RNG	SECT	ION	FOOT	AGE		COMMENT	
SHL	24S	34E	2	7	2299' FNL,	1965' FEL	On le	ease. Drill S t	:o N.
FTP/PP	24S	34E	2			2090' FEL			
LTP	24S	34E	2			2090' FEL			
BHL	24S	34E	2			2090' FEL			
					25'	KB ELEV	3,488		
GEOLOGIST	Ali S	loan	<u>/</u>	Ali.Sloan@d	devinc.com		(8	32) 269-969	4
LOGG	ING				No open ho	le logging			
		Μ	WD GR froi	m drill out o	of surface ca	asing to TD			
MUDLOO	GGING				No	ne			
FC	ORMATION		TVD	SSTVD	THICK	NESS	FINAL MD	FINAL TVD	DELTA
	Rustler		1,082'	2,406'	62	6'			
	Salado		1,708'	1,780'	2,8	10'			
BX BLM (F	letcher An	hydrite)	4,518'	-1,030'	910'				
	Lamar		5,428'	-1,940'	50)'			
В	ell Canyon		5,478'	-1,990'	91	3'			
Ch	erry Canyoi	n	6,391'	-2,903'	16	0'			
Ma	nzanita Lim	e	6,551'	-3,063'	1,2	80'			
Bru	ushy Canyo	n	7,831'	-4,343'	1,4	94'			
Bon	e Spring Lin	ne	9,325'	-5,837'	33	3'			
	Avalon		9,358'	-5,870'	97				
	BSG Sand		10,328'	-6,840'	22				
	BSG Shale		10,549'	-7,061'	37				
	SBSG Sand		10,924'	-7,436'	46	7'			
T	FBSG Carb		11,391'	-7,903'					
-	et Top at 0'		9,378'	-5,890'	20	0'			
Targe	et Base at O	' VS	9,578'	-6,090'					
HZ TARGET AT 0' VS		' VS	9,518'	-6,030'					
	KBTVD = 95 Target Win		S, INC = 90.0 10'	0 deg					

Page	<i>82</i>	of	115
------	-----------	----	-----

	0	FFSET TY	PE WELLS	S				
	DRILLIN	G WELL	Solomor	n Federal Co	m 105H	7/21/	2022	
	HZ TA	RGET	Ava	lon	AREA	Solomon		
ENTENNIAL	SECON	NDARY TYP	E LOG		PRIMARY TYPE LOG			
	1	Buff '22' 1			Solomo	on Fed Com	505H	
RESOURCE DEVELOPMENT, LLC	3	0-025-2823	5		30	0-025-4869	2	
LOCATION	24S/34E/2	2;1980' FSL/	1980' FWL		24S/34E/2	2; 400' FNL/	2190' FWL	
DISTANCE	4720' N	W of Projec	ted FTP		200' E	of Projecte	ed FTP	
DIRECTION SURVEY		Ν				Y		
KB ELEV		3,551'				3,487'		
FORMATION	TVD	SSTVD	DELTA		TVD	SSTVD	DELTA	
Lamar	5,440'	-1,889'			5,412'	-1,925'		
Bell Canyon	5,466'	-1,915'	928'		5 <i>,</i> 454'	-1,967'	927	
Cherry Canyon	6,394'	-2,843'	221'		6,381'	-2,894'	224	
Manzanita Lime	6,615'	-3,064'	1,208'		6,605'	-3,118'	1,301	
Brushy Canyon	7,823'	-4,272'	1,451'		7,906'	-4,419'	1,403	
Bone Spring Lime	9,274'	-5,723'	34'		9 <i>,</i> 309'	-5,822'	26	
Avalon	9,308'	-5,757'	1,033'		9,335'	-5,848'	962	
FBSG Sand	10,341'	-6,790'	229'		10,297'	-6,810'	221	
SBSG Shale	10,570'	-7,019'	359'		10,518'	-7,031'	336	
SBSG Sand	10,929'	-7,378'	442'		10,854'	-7,367'	496	
TBSG Carb	11,371'	-7,820'	935'		11,350'	-7,863'	914	
WFMP	12,306'	-8,755'	102'		12,264'	-8,777'		
WFMP A	12,408'	-8,857'		-				
Reservoir Top								
Reservoir Base								






•

GEOPHYSICAL DATA	
POTENTIAL GEOHAZARDS	
SEISMIC DISPLAYS	

GEOLOGIC PROG

•

							= /2 4 /2 2 2 2
			NAME		Federal Co		7/21/2022
			REA	Solo	-		
CFNTI	ENNIAL		ARGET	Ava		WI %	
	EVELOPMENT, LLC		ENGTH	77	00	AFE#	1.55
						COUNTY	Lea
GEOLOGIST	Ali Sloan			devinc.com		(8	32) 269-9694
			viua Loggin TB	g Company			
Co	ntact 1			nail			phone
	ntact 2			nail			phone
	ntact 3			nail			phone
		v distribut		quirements	and proto	n	phone
	@cdevinc.com; Ali.Sloa			-			ltenback@cdevinc.com;
		Dai	ilv email dis	stribution li	st		
		Final dis	stribution d	lata require	ments		
		Final di	stribution d	lata require	ments		
		Final di	stribution d		ments		
Contact	Information	Final dis	Final distri			l data	Cuttings
Centenn Development,	Information ial Resource c/o Joe Woodske, reet, Suite 1800,		Final distril Hard (2 copies Vertical, 2	bution list	Digita	l data inal set	
Centenn Development,	ial Resource c/o Joe Woodske,	Reports email	Final distril Hard (2 copies Vertical, 2	bution list Copies of 5" MD 2 copies of	Digita		No Dried Samples to
Centenn Development,	ial Resource c/o Joe Woodske,	Reports email	Final distril Hard (2 copies Vertical, 2	bution list Copies of 5" MD 2 copies of	Digita		
Centenn Development, 1001 17th st MWD Only: Ce Developm	ial Resource c/o Joe Woodske,	Reports email	Final distril Hard (2 copies Vertical, 2 5" Horizo 2 copies MD verti	bution list Copies of 5" MD 2 copies of	Digita	inal set	No Dried Samples t
Centenn Development, 1001 17th st MWD Only: Ce Developm	ial Resource c/o Joe Woodske, reet, Suite 1800, entennial Resource ent, c/o Sarah	Reports email final set email	Final distril Hard (2 copies Vertical, 2 5" Horizo 2 copies MD verti	bution list Copies of 5" MD 2 copies of ontal and of the 5" cal logs 2	Digita email f	inal set	No Dried Samples to
Centenn Development, 1001 17th st MWD Only: Ce Developm Ferreyros, 100:	ial Resource c/o Joe Woodske, reet, Suite 1800, entennial Resource ent, c/o Sarah	Reports email final set email	Final distril Hard (2 copies Vertical, 2 5" Horizo 2 copies MD verti	bution list Copies of 5" MD 2 copies of ontal and of the 5" cal logs 2 of the 5"	Digita email f	inal set	No Dried Samples to be Collected
Centenn Development, 1001 17th st MWD Only: Ce Developm Ferreyros, 1003	ial Resource c/o Joe Woodske, reet, Suite 1800, entennial Resource ent, c/o Sarah 1 17th street, Suite	Reports email final set email final set	Final distril Hard (2 copies Vertical, 2 5" Horizo 2 copies MD verti	bution list Copies of 5" MD 2 copies of ontal and of the 5" cal logs 2 of the 5"	Digita email f email f	inal set	No Dried Samples to be Collected




Solomon Federal Com 105H

Centennial Drilling Plan for 3-Casing String Bone Springs Formation

13-3/8" x 9-5/8" x 5-1/2" Casing Design

1. Drill 17-1/2" surface hole to Total Depth with Rig and perform wellbore cleanup cycles. 2. Run and land 13-3/8" casing to Depth.

- 3. Cement 13-3/8" casing cement to surface.
- 4. Cut / Dress Conductor and 13-3/8" casing as needed, weld on Multi-bowl system with baseplate supported by 20" conductor.
- 5. Test Weld to 70% of 13-3/8" casing collapse. Place nightcap with Pressure Gauge on wellhead and test seals to 70% of Casing Collapse.
- 6. Bleed Pressure if necessary and remove nightcap. Nipple up and test BOPE with test plug per Onshore Order 2.
- 7. Test casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 8. Install wear bushing then drill out 13-3/8" shoe-track plus 20' and conduct FIT to minimum of the MW equivalent anticipated to control the formation pressure to the next casing point.
- 9. Drill 12-1/4" Intermediate hole to 9-5/8" casing point. (Base Capitan Reef).
- 10. Remove wear bushing then run and land 9-5/8" Intermediate Casing with mandrel hanger in wellhead.
- 11. Cement 9-5/8 casing cement to surface.
- 12. Washout stack then run wash tool in wellhead and wash hanger and pack-off setting area.
- 13. Install pack-off and test to 5000 psi for 15 minutes.
 - a. Test casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 14. Install wear bushing then drill out 9-5/8" shoe-track plus 20' and conduct FIT to minimum MW equivalent to control the formation pressure to TD of well.
- 15. Drill 8-3/4" Vertical hole to KOP Trip out for Curve BHA.
- 16. Drill 8-3/4" Curve, landing in production interval Trip for Lateral BHA.
- 17. Drill 7-7/8" Lateral to Permitted BHL, perform cleanup cycles and trip out to run 5-1/2" Production Casing.
- 18. Remove wear bushing then run 5-1/2" production casing to TD landing casing mandrel in wellhead.
- 19. Cement 5-1/2" Production string to surface.
- 20. Run in with wash tool and wash wellhead area install pack-off and test to 5000psi for 15 minutes.
- 21. Install BPV in 5-1/2" mandrel hanger Nipple down BOPE and install nightcap.
- 22. Test nightcap void to 5000psi for 30 minutes.



Released to Imaging: 7/27/2023 9:22:50 AM

Centennial Resource Development - Well Control Plan

A. Component and Preventer Compatibility Table

Component	OD (inches)	Preventer	RWP
Drillpipe	5	Upper VBR: 3.5 – 5.5	10M
		Lower VBR: 3.5 – 5.5	
Heavyweight Drillpipe	5	Upper VBR: 3.5 – 5.5	10M
		Lower VBR: 3.5 – 5.5	
Drill collars and MWD tools	6 ¾	Annular	5M
Mud Motor	6 ¾	Annular	5M
Production Casing	5-1/2	Upper VBR: 3.5 – 5.5	10M
		Lower VBR: 3.5 – 5.5	
All	0 - 13 5/8	Annular	5M
Open-hole	-	Blind rams	_10M

VBR = Variable Bore Rams

RWP = Rated Working Pressure

MWD = Measurement While Drilling (directional tools)

B. Well Control Procedures

I. <u>General Procedures While Drilling:</u>

- 1. Sound alarm (alert crew).
- 2. Space out drill-string.
- 3. Shut down pumps and stop rotary.
- 4. Open HCR
- 5. Shut-in well utilizing upper VBRs.
- 6. Close choke
- 7. Confirm shut-in.
- 8. Notify rig manager and Centennial company representative.
- 9. Call Centennial drilling engineer
- 10. Read and record
 - I. Shut-in drillpipe pressure (SIDPP) and shut-in casing pressure (SCIP).
 - II. Pit gain
 - III. Time
- 11. Regroup, identify forward plan

II. General Procedure While Tripping

- 1. Sound alarm (alert crew).
- 2. Stab full opening safety valve and close
- 3. Space out drillstring.
- 4. Open HCR
- 5. Shut-in well utilizing upper VBRs
- 6. Close choke
- 7. Confirm shut-in.
- 8. Notify rig manager and Centennial company representative.
- 9. Call Centennial drilling engineer
- 10. Read and record:
 - I. SIDPP AND SICP
 - II. Pit gain
 - III. Time
- 11. Regroup and identify forward plan.

III. General Procedure While Running Casing

- 1. Sound alarm (alert crew)
- 2. Stab full opening safety valve and close
- 3. Space out string.
- 4. Open HCR
- 5. Shut-in well utilizing upper VBRs.
- 6. Close choke
- 7. Confirm shut-in.
- 8. Notify rig manager and Centennial company representative.
- 9. Call Centennial drilling engineer
- 10. Read and record:
 - I. SIDPP AND SICP
 - II. Pit gain
 - III. Time
- 11. Regroup and identify forward plan.

IV. General Procedure With No Pipe In Hole (Open Hole)

- 1. Sound alarm (alert crew)
- 2. Open HCR
- 3. Shut-in with blind rams
- 4. Close choke
- 5. Confirm shut-in
- 6. Notify rig manager and Centennial company representative.
- 7. Call Centennial drilling engineer
- 8. Read and record:
 - I. SIDPP AND SICP
 - II. Pit gain
 - III. Time
- 9. Regroup and identify forward plan.

V. General Procedures While Pulling BHA Thru BOP Stack

Ι.

1. Prior to pulling last joint of drillpipe thru stack:

- Perform flow check, if flowing
 - a. Sound alarm, alert crew
 - b. Stab full opening safety valve and close
 - c. Space out drillstring with tool joint just beneath the upper pipe ram.
 - d. Open HCR
 - e. Shut-in utilizing upper VBRs
 - f. Close choke
 - g. Confirm shut-in
 - h. Notify rig manager and Centennial company representative.
 - i. Call Centennial drilling engineer
 - j. Read and record:
 - i. SIDPP and SICP
 - ii. Pit gain
 - iii. Time
- II. Regroup and identify forward plan

2. With BHA in the BOP stack and compatible ram preventer and pipe combo immediately available:

- a. Sound alarm, alert crew
- b. Stab full opening safety valve and close
- c. Space out drillstring with tool joint just beneath the upper pipe ram.
- d. Open HCR
- e. Shut-in utilizing upper VBRs
- f. Close choke
- g. Confirm shut-in
- h. Notify rig manager and Centennial company representative.
- i. Call Centennial drilling engineer
- j. Read and record:
 - i. SIDPP and SICP
 - ii. Pit gain
 - iii. Time
- II. Regroup and identify forward plan

3. With BHA in the BOP stack and no compatible ram preventer and pipe combo immediately availiable:

- I. Sound alarm, alert crew.
- II. If possible to pick up high enough, pull string clear of the stack and follow Open Hole (III) scenario.
- III. If impossible to pick up high enough to pull the string clear of the stack:
 - a. Stab crossover, make up one joint/stand of drill pipe and full opening safety valve and close.
 - b. Space out drillstring with tool joint just beneath the upper pipe ram.
 - c. Open HCR
 - d. Shut-in utilizing upper VBRs.
 - e. Close choke
 - f. Confirm shut-in
 - g. Notify rig manager and Centennial company representative.
 - h. Call Centennial drilling engineer
 - i. Read and record:
 - i. SIDPP and SICP
 - ii. Pit gain
 - iii. Time
- IV. Regroup and identify forward plan.

** If annular is used to shut-in well and pressure builds to OR is expected to get to 50% of RWP, confirm space-out and swap to upper VBRs for shut-in.



ContiTech

CONTITECH RUBBER	No:QC-DB- 210/ 2014			
Industrial Kft.	Page:	9 / 113		

Pressure test with water at ambient temperature See attachment. (1 page) 10 mm = 10 Min. → 10 mm = 20 MPa COUPLINGS Type Serial N° Quality Heat N° 3" coupling with 9251 9254 AISI 4130 A0579N 4 1/16" 10K API b.w. Flange end AISI 4130 A0579N At 1/16" 10K API b.w. Flange end AISI 4130 A0579N Mot Designed For Well Testing API Spec 16 C Temperature rate:" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER NSPECTED AND PRESSURE TESTED AS ABOVE with at the above lems/equipment supplied by us are in conformity with the ter STATEMENT OF CONFORMITY: We hereby certify that the above lems/equipment supplied by us are in conformity with the ter COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	QUALITY CONTROL INSPECTION AND TEST CERTIFICATE					N°:	504	
HOSE SERIAL N°: 67255 NOMINAL / ACTUAL LENGTH: 10,67 m / 10,77 m W.P. 68,9 MPa 10000 psi T.P. 103,4 MPa 15000 psi Duration: 60 n Pressure test with water at ambient temperature See attachment. (1 page) See attachment. (1 page) 60 n 10 mm = 10 min. > 10 mm = 20 MPa Quality Heat N° COUPLINGS Type Serial N° Quality Heat N° 3° coupling with 9251 9254 AISI 4130 A0579N 4 1/16° 10K API b.w. Flange end AISI 4130 035608 API Spec 16 C Temperature rate: ¹⁷ All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER STATEMENT OF CONFORMITY: We hereby certify that the above hems/equipment supplied by us are in conformily with the for conforming with the for conforming with the for conforming with the terms/equipment supplied by us are in conformily with the for conforming wi	PURCHASER:	ContiTech	Oil & Marine C	orp.	P.O. N°:	P.O. N°: 4500409659		
W.P. 68,9 MPa 10000 psi T.P. 103,4 MPa 15000 psi Duration: 60 pressure test with water at ambient temperature Image: Comparison of the imperature See attachment. (1 page) See attachment. (1 page) 10 mm = 10 mm = 10 mm. → 10 mm = 10 mm.	CONTITECH RUBBER order N	•: 538236	HOSE TYPE:	3" ID	-1	Choke and	l Kill Hose	
Pressure test with water at ambient temperature See attachment. (1 page) ↑ 10 mm = 10 Min. → 10 mm = 20 MPa COUPLINGS Type Serial N° Quality Heat N° 3" coupling with 9251 9254 AISI 4130 AISI 4130 035608 Not Designed For Well Testing API Spec 16 C Temperature rate:" AII metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER NSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above lems/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance citerie and design requirement country OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	HOSE SERIAL N°:	67255	NOMINAL / ACT	UAL LENGTH	:	10,67 m	l / 10,77 m	
ambient temperature See attachment. (1 page) ↑ 10 mm = 10 Min. → 10 mm = 20 MPa COUPLINGS Type Serial N° Quality Heat N° 3" coupling with 9251 9254 AISI 4130 A0579N 4 1/16" 10K API b.w. Flange end AISI 4130 035608 Not Designed For Well Testing API Spec 16 C Temperature rate:" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance citeria and design requirement country OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	W.P. 68,9 MPa 10	0000 psi	T.P. 103,4	MPa 150	00 psi	Duration:	60	min.
COUPLINGS Type Serial N° Quality Heat N° 3" coupling with 9251 9254 AISI 4130 A0579N 4 1/16" 10K API b.w. Flange end AISI 4130 035608 Not Designed For Well Testing API Spec 16 C Temperature rate:" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER INSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	ambient temperature See attachment. (1 page)							
4 1/16" 10K API b.w. Flange end AISI 4130 035608 Not Designed For Well Testing API Spec 16 C Temperature rate:" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER NSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	, , , , , , , , , , , , , , , , , , , ,	-	Serial	Nº	Q	uality	Heat N°	
Not Designed For Well Testing API Spec 16 C Image: All metal parts are flawless Temperature rate:" WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER Image: Comperative rested as ABOVE with SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tested accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements: COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector	3" coupling with	<u>ו</u>	9251	9254	AIS	SI 4130	A0579N	
All metal parts are flawless ME CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER INSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the terr conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector	4 1/16" 10K API b.w. Fla	ange end			AIS	SI 4130	035608	
All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER INSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the terr conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tester accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector	Not Designed F	Not Designed For Well Testing API Spec 16 C						
WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER INSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the terr conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tested accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector	Temperature rate:"B"					"B"		
STATEMENT OF CONFORMITY: We hereby certify that the above items/equipment supplied by us are in conformity with the ter conditions and specifications of the above Purchaser Order and that these items/equipment were fabricated inspected and tested accordance with the referenced standards, codes and specifications and meet the relevant acceptance criteria and design requirements COUNTRY OF ORIGIN HUNGARY/EU Date: Inspector Quality Control	WE CERTIFY THAT THE ABOVE					H THE TERMS	OF THE ORDER	
Continent Rubber	STATEMENT OF CONFORMITY conditions and specifications of	: We hereby c the above Purch tandards, codes a	ertify that the aboven naser Order and th and specifications a	e items/equipme at these items/e nd meet the rele	nt supplied quipment v vant accept	were fabricated	I inspected and tes	ted in
20. March 2014.		Inspector		Quality Contr	ol V Qa or	Industria	al Kft, /	L

ContiTech Rubber Industrial Kft. | Budapesti út 10. H-6728 Szeged | H-6701 P.O.Box 152 Szeged, Hungary Phone: +36 62 566 737 | Fax: +36 62 566 738 | e-mail: info@fluid.contitech.hu | Internet: www.contitech-rubber.hu; www.contitech.hu The Court of Coograft County as Registry Court | Registry Court No: Cg.06-09-002502 | EU VAT No: HU11087209 Released topLinegrag monocont back back of 42, Buddes of 42201/8-26830003

ATTACHMENT OF QUALITY CONTROL INSPECTION AND TEST CERTIFICATE

No: 501, 504, 505 Page: 1/1

	Contract Rabber
GN +21.22 90	01 20 01 20 01 20 01 20
RD +21,95 90 BL +1053, bar CN +21,15 90 RD +21,91 90 BL +1055, bar	01:20 01:10 01:10 01:10
CN 421, 19 00	
RD +21.30 96 BLT +1056	01 00 00:50 00:50 00:50
RD +21-54 90 BL +1059. bdr GN +21-36 90	00:40 00:40 00:40 00:30 00:30 00:30
RD +21.42 90 BL +1061. bdr GN +21.35 90 RD +21.36 90	99-39 99-36 99-29 99-29 99-29 99-29
BL +1064. bar	00 2 2 P
0 10 20 30 40 19-83-2014-23+59 67252-67255-67256 23	



CONTITECH RUBBER	No:QC-DB-2	10/ 2014
Industrial Kft.	Page: 15	/ 113

ContiTech

Hose Data Sheet

CRI Order No.	538236
Customer	ContiTech Oil & Marine Corp.
Customer Order No	4500409659
Item No.	1
Hose Type	Flexible Hose
Standard	API SPEC 16 C
Inside dia in inches	3
Length	35 ft
Type of coupling one end	FLANGE 4.1/16" 10K API SPEC 6A TYPE 6BX FLANGE C/W BX155 R.GR.SOUR
Type of coupling other end	FLANGE 4.1/16" 10K API SPEC 6A TYPE 6BX FLANGE C/W BX155 R.GR.SOUR
H2S service NACE MR0175	Yes
Working Pressure	10 000 psi
Design Pressure	10 000 psi
Test Pressure	15 000 psi
Safety Factor	2,25
Marking	USUAL PHOENIX
Cover	NOT FIRE RESISTANT
Outside protection	St.steel outer wrap
Internal stripwound tube	No
Lining	OIL + GAS RESISTANT SOUR
Safety clamp	No
Lifting collar	No
Element C	No
Safety chain	No
Safety wire rope	No
Max.design temperature [°C]	100
Min.design temperature [°C]	-20
Min. Bend Radius operating [m]	0,90
Min. Bend Radius storage [m]	0,90
Electrical continuity	The Hose is electrically continuous
Type of packing	WOODEN CRATE ISPM-15

Centennial Resource Production, LLC hereby requests to use a flex hose on H&P choke manifold for the

Solomon Federal Com 105H well. The Flex Hose specifications are listed on the following pages.

Solomon Federal Com 105H


Centennial Offline Cementing Procedure

13-3/8" & 9-5/8" Casing

- 1. Drill hole to Total Depth with Rig and perform wellbore cleanup cycles.
- 2. Run and casing to Depth.
- 3. Land casing with mandrel.
- 4. Circulate 1.5 csg capacity.
- 5. Flow test Confirm well is static and floats are holding.
- 6. Set Annular packoff and pressure test. Test to 5k.
- 7. Nipple down BOP and install cap flange.
- 8. Skid rig to next well on pad
- 9. Remove cap flange (confirm well is static before removal)
 - a. If well is not static use the casing outlet valves to kill well
 - b. Drillers method will be used in well control event
 - c. High pressure return line will be rigged up to lower casing valve and run to choke manifold to control annular pressure
 - d. Kill mud will be circulated once influx is circulated out of hole
 - e. Confirm well is static and remove cap flange to start offline cement operations
- 10. Install offline cement tool.
- 11. Rig up cementers.
- 12. Circulate bottoms up with cement truck
- 13. Commence planned cement job, take returns through the annulus wellhead valve
- 14. After plug is bumped confirm floats hold and well is static
- 15. Rig down cementers and equipment
- 16. Install night cap with pressure gauge to monitor.
- 17. Will only offline surface and intermediate casing.


13 3/8" Surface job

CFL Off-Line Cementing Tool







9 5/8" Intermediate Job







Run 13-5/8" Packoff Test Upper and Lower Seals Engage Lockring Retrieve Running Tool



07/24/2023

FMSS

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Submission Date: 11/02/2022

A DATE STATE

Operator Name: CENTENNIAL RESOURCE PRODUCTION LLC

Well Name: SOLOMON FEDERAL COM

Well Type: OIL WELL

APD ID: 10400087543

Well Number: 105H Well Work Type: Drill Highlighted data reflects the most recent changes <u>Show Final Text</u>

Bond Info Data

Bond


Federal/Indian APD: FED

BLM Bond number: NMB001841

BIA Bond number:

Do you have a reclamation bond? NO

- Is the reclamation bond a rider under the BLM bond?
- Is the reclamation bond BLM or Forest Service?
- BLM reclamation bond number:
- Forest Service reclamation bond number:
- Forest Service reclamation bond
- **Reclamation bond number:**
- **Reclamation bond amount:**
- Reclamation bond rider amount:
- Additional reclamation bond information



Page 104 of 115

.

	E	inergy, Minerals a Oil Co 1220 S	te of New Mex and Natural Res onservation Di South St. Franc ata Fe, NM 87:	ources Departme vision cis Dr.	ent		Subn Via I	nit Electronically E-permitting
	N	ATURAL G	AS MANA(GEMENT PI	LAN			
This Natural Gas Manag	ement Plan m	ust be submitted w	ith each Applicat	ion for Permit to I	Drill (Al	PD) for a r	new or	recompleted well.
			<u>1 – Plan D</u> ffective May 25,					
I. Operator: PERMIAN R	ESOURCES C	PERATING, LLC	OGRID: <u>37</u> 2	2165		Date: _	06 /	12 / 2023
II. Type: ☑ Original □	Amendment	due to □ 19.15.27	.9.D(6)(a) NMA	C 🗆 19.15.27.9.D(6)(b) N	MAC 🗆 C	Other.	
If Other, please describe	:							
III. Well(s): Provide the be recompleted from a si					wells pr	oposed to	be dri	lled or proposed to
Well Name	API	ULSTR	Footages	Anticipated Oil BBL/D		cipated MCF/D	P	Anticipated roduced Water BBL/D
SHEBA FEDERAL COM 10	Ϋ́H	H-27-24S-34E	2349 FNL & 1030 FI	L 1622 BBL/D	2437	MCF/D	1	0891 BBL/D
RAIDER FEDERAL COM 10		O-21-24S-34E	355 FSL & 1730 FE			MCF/D		0818 BBL/D
SOLOMON FEDERAL COM		G-27-24S-34E	2299 FNL & 1965 F	EL 1366 BBL/D	2052	MCF/D		9171 BBL/D 7.9(D)(1) NMAC]
V. Anticipated Schedule proposed to be recomple Well Name	e: Provide the	e following informa		-			propo low	
		07/07/0000	07/00/0000	10/01/0000		40/40/0		40/40/0000
	EBA FEDERAL COM 107H 07/07/2023		07/22/2023	10/01/2023 10/04/2023		10/16/2023 10/16/2023		10/16/2023
AIDER FEDERAL COM 102H 07/24/2023 OLOMON FEDERAL COM 105H 07/29/2023			08/10/2023 08/13/2023			10/16/20		10/16/2023 10/16/2023
VI. Separation Equipm VII. Operational Pract Subsection A through F	ent: 🗹 Attac	h a complete descri ch a complete desc	ption of how Ope	erator will size sep		equipment	t to op	timize gas capture.

Page 6

<u>Section 2 – Enhanced Plan</u> EFFECTIVE APRIL 1, 2022

Beginning April 1, 2022, an operator that is not in compliance with its statewide natural gas capture requirement for the applicable reporting area must complete this section.

□ Operator certifies that it is not required to complete this section because Operator is in compliance with its statewide natural gas capture requirement for the applicable reporting area.

IX. Anticipated Natural Gas Production:

Well	API	Anticipated Average Natural Gas Rate MCF/D	Anticipated Volume of Natural Gas for the First Year MCF
SHEBA FEDERAL COM 107H		1216 MCF/D	460356 MCF
RAIDER FEDERAL COM 102H		1150 MCF/D	430429 MCF
SOLOMON FEDERAL COM 105H		1024 MCF/D	387668 MCF

X. Natural Gas Gathering System (NGGS):

Oper	rator	System	ULSTR of Tie-in	Anticipated Gathering	Available Maximum Daily Capacity
				Start Date	of System Segment Tie-in
TARGA	LUCIE	-TARGA GATHERING S	YSTEM I-21-24S-34E	10/16/2023	21 MMSCFD

XI. Map. \square Attach an accurate and legible map depicting the location of the well(s), the anticipated pipeline route(s) connecting the production operations to the existing or planned interconnect of the natural gas gathering system(s), and the maximum daily capacity of the segment or portion of the natural gas gathering system(s) to which the well(s) will be connected.

XII. Line Capacity. The natural gas gathering system \square will \square will not have capacity to gather 100% of the anticipated natural gas production volume from the well prior to the date of first production.

XIII. Line Pressure. Operator \square does \square does not anticipate that its existing well(s) connected to the same segment, or portion, of the natural gas gathering system(s) described above will continue to meet anticipated increases in line pressure caused by the new well(s).

 \square Attach Operator's plan to manage production in response to the increased line pressure.

XIV. Confidentiality: \square Operator asserts confidentiality pursuant to Section 71-2-8 NMSA 1978 for the information provided in Section 2 as provided in Paragraph (2) of Subsection D of 19.15.27.9 NMAC, and attaches a full description of the specific information for which confidentiality is asserted and the basis for such assertion.

Page 7

Section 3 - Certifications Effective May 25, 2021

Operator certifies that, after reasonable inquiry and based on the available information at the time of submittal:

 \Box Operator will be able to connect the well(s) to a natural gas gathering system in the general area with sufficient capacity to transport one hundred percent of the anticipated volume of natural gas produced from the well(s) commencing on the date of first production, taking into account the current and anticipated volumes of produced natural gas from other wells connected to the pipeline gathering system; or

 \Box Operator will not be able to connect to a natural gas gathering system in the general area with sufficient capacity to transport one hundred percent of the anticipated volume of natural gas produced from the well(s) commencing on the date of first production, taking into account the current and anticipated volumes of produced natural gas from other wells connected to the pipeline gathering system. *If Operator checks this box, Operator will select one of the following:*

Well Shut-In. \Box Operator will shut-in and not produce the well until it submits the certification required by Paragraph (4) of Subsection D of 19.15.27.9 NMAC; or

Venting and Flaring Plan. \Box Operator has attached a venting and flaring plan that evaluates and selects one or more of the potential alternative beneficial uses for the natural gas until a natural gas gathering system is available, including:

- (a) power generation on lease;
- (b) power generation for grid;
- (c) compression on lease;
- (d) liquids removal on lease;
- (e) reinjection for underground storage;
- (f) reinjection for temporary storage;
- (g) reinjection for enhanced oil recovery;
- (h) fuel cell production; and
- (i) other alternative beneficial uses approved by the division.

Section 4 - Notices

1. If, at any time after Operator submits this Natural Gas Management Plan and before the well is spud:

(a) Operator becomes aware that the natural gas gathering system it planned to connect the well(s) to has become unavailable or will not have capacity to transport one hundred percent of the production from the well(s), no later than 20 days after becoming aware of such information, Operator shall submit for OCD's approval a new or revised venting and flaring plan containing the information specified in Paragraph (5) of Subsection D of 19.15.27.9 NMAC; or

(b) Operator becomes aware that it has, cumulatively for the year, become out of compliance with its baseline natural gas capture rate or natural gas capture requirement, no later than 20 days after becoming aware of such information, Operator shall submit for OCD's approval a new or revised Natural Gas Management Plan for each well it plans to spud during the next 90 days containing the information specified in Paragraph (2) of Subsection D of 19.15.27.9 NMAC, and shall file an update for each Natural Gas Management Plan until Operator is back in compliance with its baseline natural gas capture rate or natural gas capture requirement.

2. OCD may deny or conditionally approve an APD if Operator does not make a certification, fails to submit an adequate venting and flaring plan which includes alternative beneficial uses for the anticipated volume of natural gas produced, or if OCD determines that Operator will not have adequate natural gas takeaway capacity at the time a well will be spud.

Received by OCD: 7/24/2023 8:26:52 AM

Page 8

I certify that, after reasonable inquiry, the statements in and attached to this Natural Gas Management Plan are true and correct to the best of my knowledge and acknowledge that a false statement may be subject to civil and criminal penalties under the Oil and Gas Act.

Signature:	ER:
	Clise Taunton

Printed Name: Elise Taunton

Title: Midstream & Marketing Representative

E-mail Address: elise.taunton@permianres.com

Date: 06/12/2023

Phone: (512) 567-9474

OIL CONSERVATION DIVISION

(Only applicable when submitted as a standalone form)

Approved By:

Title:

Approval Date:

Conditions of Approval:

Centennial Resource Production, LLC (372165)

Natural Gas Management Plan Descriptions

VI. Separation Equipment:

Centennial utilizes a production forecast from our Reservoir Engineering team to appropriately size each permanent, 3-phase separator and heater treater utilized for production operations. Our goal is to maintain 5 minutes of retention time in the test vessel and 20 minutes in the heater treater at peak production rates. The gas produced is routed from the separator to the gas sales line.

VII. Operational Practices:

Drilling

During Centennial's drilling operations it is uncommon for venting or flaring to occur. If flaring is needed due to safety concerns, gas will be routed to a flare and volumes will be estimated.

Flowback

During completion/recompletion flowback operations, after separation flowback begins and as soon as it is technically feasible, Centennial routes gas though a permanent separator and the controlled facility where the gas is either sold or flared through a high-pressure flare if needed.

Production

Per 19.15.27.8.D, Centennial's facilities are designed to minimize waste. Our produced gas will only be vented or flared in an emergency or malfunction situation, except as allowed for normal operations noted in 19.15.27.8.D(2) & (4). All gas that is flared is metered. All gas that may be vented will be estimated.

Performance Standards

Centennial utilizes a production forecast from our Reservoir Engineering team to appropriately size each permanent, 3-phase separator and heater treater utilized for production operations.

All of Centennial's permanent storage tanks associated with production operations which are routed to a flare or control device are equipped with an automatic gauging system.

All of Centennial's flare stacks, both currently installed and for future installation, are:

- 1) Appropriately sized and designed to ensure proper combustion efficiency.
- 2) Equipped with an automatic ignitor or continuous pilot.
- 3) Anchored and located at least 100 feet from the well and storage tanks.

Centennial's field operations and HSE teams have implemented an AVO inspection schedule that adheres to the requirements of 19.15.27.8.E(5).

All of our operations and facilities are designed to minimize waste. We routinely employ the following methods and practices:

- Closed-loop systems
- Enclosed and properly sized tanks

Page 110 of 115

- Vapor recovery units to maximize recovery of low-pressure gas streams and potential unauthorized emissions
- Low-emitting or electric engines whenever practical
- Combustors and flare stacks in the event of a malfunction or emergency
- Routine facility inspections to identify leaking components, functioning control devices, such as flares and combustors, and repair / replacement of malfunctioning components where applicable

Measurement or estimation

Centennial measures or estimates the volumes of natural gas vented, flared and/or beneficially used for all of our drilling, completing and producing wells. We utilize accepted industry standards and methodology which can be independently verified. Annual GOR testing is completed on our wells and will be submitted as required by the OCD. None of our equipment is designed to allow diversion around metering elements except during inspection, maintenance and repair operations.

VIII. Best Management Practices:


Centennial utilizes the following BMPs to minimize venting during active and planned maintenance activities:


- Use a closed-loop process wherever possible during planned maintenance activities, such as blowdowns, liquid removal, and work over operations.
- Employ low-emitting or electric engines for equipment, such as compressors
- Adhere to a strict preventative maintenance program which includes routine facility inspections, identification of component malfunctions, and repairing or replacing components such as hatches, seals, valves, etc. where applicable
- Utilize vapor recovery units (VRU's) to maximize recovery of volumes of low-pressure gas streams and potential unauthorized emissions
- Route low pressure gas and emissions streams to a combustion device to prevent venting where necessary


Enhanced Natural Gas Management Plan

Operator's Plan to Manage Production in Response to Increased Line Pressure

Permian Resources Operating, LLC (Permian) anticipates that its existing wells connected to the same portion of the natural gas gathering system will continue to meet anticipated increases in line pressure caused by the new wells. Permian will actively monitor line pressure throughout the field and will make necessary adjustments to existing production separators' pressures to send gas to sales. Permian also plans to implement automated alarms on all flare meters to alert of flaring events as they occur. The alarms will send notifications to field operations and engineering staff via text message and email at every occurrence of flaring. In addition, Permian plans to implement automated alarms on all flare meters to alert of any continuous flaring event that has continued for at least 4 hours. The alarms will send notifications to field operations and engineering management. Permian personnel will promptly respond to these alarms, communicate with midstream partners, and take the appropriate action to reduce flaring caused by high line pressure from new well production.







District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Permian Resources Operating, LLC	372165
1001 17th Street, Suite 1800	Action Number:
Denver, CO 80202	243526
	Action Type:
	[C-101] BLM - Federal/Indian Land Lease (Form 3160-3)

CONDITIONS

Created By	Condition	Condition Date
pkautz	Will require a File As Drilled C-102 and a Directional Survey with the C-104	7/27/2023
pkautz	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string	7/27/2023
pkautz	Oil base muds are not to be used until fresh water zones are cased and cemented providing isolation from the oil or diesel. This includes synthetic oils. Oil based mud, drilling fluids and solids must be contained in a steel closed loop system	7/27/2023
pkautz	Cement is required to circulate on both surface and intermediate1 strings of casing	7/27/2023

Page 115 of 115 CONDITIONS

Action 243526