Office	State of New Mexico	Form C-103 ¹
<u>District I</u> – (575) 393-6161 Energy,	Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-015-28992
811 S. First St., Artesia, NM 88210 OIL C	ONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND RE		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR PE		OSAGE BOYD 15 SWD
PROPOSALS.)		0 W 11 N 1
1. Type of Well: Oil Well Gas Well	Other SWD	I .
2. Name of Operator SPUR ENERGY PAR	TNERS LLC	9. OGRID Number 328947
3. Address of Operator	THERE EES	10. Pool name or Wildcat
9655 KATY FREEWAY, SUITE 500, H	OUSTON. TX 77024	SWD; CISCO-CANYON
4. Well Location		,,
Unit Letter F: 1980 fee	et from the <u>NORTH</u> line and	1980feet from theWESTline
	ownship 19S Range 25E	NMPM EDDY County
11. Elevatio	n (Show whether DR, RKB, RT, GR, etc.)
	3454' GR	
12 Check Appropriate	Box to Indicate Nature of Notice,	Papart or Other Data
12. Спеск Арргорпас	Box to indicate Nature of Notice,	Report of Other Data
NOTICE OF INTENTION		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND		—
TEMPORARILY ABANDON		ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE DOWNHOLE COMMINGLE	COMPL CASING/CEMEN	II JOB 🔲
CLOSED-LOOP SYSTEM		
OTHER: WO	RKOVER 🔀 OTHER:	
		d give pertinent dates, including estimated date
of starting any proposed work). SEE RUl proposed completion or recompletion.	LE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
We confirmed this well has pressure	on the backeide as it requires on in	amadiata warkayar
Please find procedure and WBD attac	•	iniediate workover.
r roade into procedure and 1122 and	shed for your review.	
Spud Date:	Rig Release Date:	
Spud Date.	Rig Release Date.	
I hereby certify that the information above is true a	and complete to the best of my knowledge	ge and belief.
, ,	1	
SIGNATURE South Charles		DATE: 40/04/0000
SIGNATURE Sarah Chapman	TITLE REGULATORY DIREC	CTOR DATE 12/04/2023
Type or print name SARAH CHAPMAN	E-mail address: SCHAPMAN@SPU	RENERGY.COM PHONE: 832-930-8613
For State Use Only		
ADDDOVED DV.	TITLE	DATE
APPROVED BY: Conditions of Approval (if any):	TITLE	DATE
Conditions of Approval (II any):		

Osage Boyd SWD #1 SWD

Eddy County, NM API# 30-015-28992 X23629 – \$185,000

Hole in Tubing / Packer Leak

Objective

This well has a suspected hole in tubing or packer leak due to pressure on the 7" casing. It is proposed to pull and LD all IPC tubing and replace all tubing with re-worked Polycore tubing from Western Falcon. The tubing that is in the well is from the original completion of this well in 2015.

Notes:

ONLY RUN 316 OR HIGHER-GRADE STAINLESS STEEL, PLASTIC COATED, OR NICKEL COATED ACCESSORIES DOWNHOLE – COLLARS, XOs, ON/OFF TOOLS ETC. SS IS PREFERED.

Procedure

- 1. Notification: Contact the OCD at least 24 hours prior to the commencement of any operations.
- 2. Move in rig up pulling unit and laydown machine.
- 3. Ensure well is at 0 psi, 10# brine should be enough to kill the well; make sure 11.6# is available at vendor if needed. Nipple down wellhead. Nipple up BOP.
- 4. Pull and LD 3-1/2" IPC tubing as follows:

Tubing Detail (11/20/2020)

TUBING DETAIL 13' KB 3-1/2" 9.3# IPC TUBING PACKER @ +/- 7,650'


- 5. MI new tubing from Western Falcon and backhaul old tubing.
- 6. Pick up bit and scraper and 3-1/2" Polycore tubing from Western Falcon. Run in hole to 7,650' and pull out of hole.
- 7. Run in hole hydrotesting tubing to 5,000 psi below the slips as follows:

Proposed Tubing Detail

~237 jts 3-1/2" std WF Polycore L-80 9.3# EUE tbg 3-1/2" T-2 O/O tool NP w/ profile 7" X 3 1/2" NP AS1X Packer 3-1/2" x 2-7/8" SS XO 2 7/8" NP Pup 2 7/8" SS Landing Nipple POP w/ WLREG

8. Put packer at +/- 7,650' (same depth as before).

- 9. Bull head 150 bbls of packer fluid and set packer; once set, top off the annulus with packer fluid. Consult engineer on how much compression should be set on packer.
- 10. Load and test casing to 500 psi for 30 mins.
- 11. If good test, Nipple down BOP. Nipple up wellhead.
- 12. Rig down pulling unit.
- 13. Notify NMOCD 48hrs in advance to witness MIT; run MIT in accordance to 19.15.26 NMAC.



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 290774

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	290774
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
mgebremichael	same tubing size shall be replaced and packer setting depth shall not be more than 100 ft above the top of the injection interval.	1/9/2024