

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Reports
06/07/2024

Well Name: SJU TR-B Well Location: T25S / R37E / SEC 11 / County or Parish/State: LEA /

SENW / 32.1474633 / -103.1346668

Well Number: 12 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMLC032511F Unit or CA Name: SOUTH JUSTIS UNIT Unit or CA Number:

NMNM87877X

US Well Number: 3002520547 Operator: LEGACY RESERVES

OPERATING LP

Accepted for Record Only

SUBJECT TO LIKE APPROVAL BY BLM

NMOCD 6/18/24 X ≠

Must run CBL and file into well logs file in NMOCD Permitting app

Notice of Intent

Sundry ID: 2791601

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date proposed operation will begin: 05/27/2024

Procedure Description:

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

2024_05_07_WBD_South_Justis_Unit__B12_Proposed_PA_with_WBDs_20240521063450.pdf

Page 1 of 2

eceived by OCD: 6/13/2024 12:29:11 PM Well Name: SJU TR-B

Well Location: T25S / R37E / SEC 11 /

SENW / 32.1474633 / -103.1346668

County or Parish/State: LEA/ 2 of

NM

Zip:

Well Number: 12

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMLC032511F

Unit or CA Name: SOUTH JUSTIS UNIT Unit or CA Number:

NMNM87877X

US Well Number: 3002520547

Operator: LEGACY RESERVES

OPERATING LP

Conditions of Approval

Specialist Review

SJU TR B 12 BLM Revised P A 20240529075033.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: ERIN MAZUR Signed on: MAY 21, 2024 06:34 AM

Name: LEGACY RESERVES OPERATING LP

Title: Regulatory Manager

Street Address: 2001 TIMBERLOCH PLACE SUITE 300

City: THE WOODLANDS State: TX

Phone: (713) 594-5843

Email address: EMAZUR@LEGACYRESERVES.COM

Field

Representative Name:

Street Address:

City: State:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: ZOTA M STEVENS BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345998 BLM POC Email Address: ZSTEVENS@BLM.GOV

Disposition: Approved **Disposition Date:** 05/29/2024

Signature: Zota Stevens

Form 3160-5 (June 2019)

UNITED STATES DEPARTMENT OF THE INTERIOR RU

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 202

ETT INCTIVIE IVE OF THE INVESTIGATION	ı
REAU OF LAND MANAGEMENT	5.

BURI	EAU OF LAND MANAGEMENT		5. Lease Serial No.	NMLC032511F
Do not use this f	OTICES AND REPORTS ON Worm for proposals to drill or to Use Form 3160-3 (APD) for suc	re-enter an	6. If Indian, Allottee	or Tribe Name
SUBMIT IN 1	TRIPLICATE - Other instructions on page	e 2	_	eement, Name and/or No.
1. Type of Well	_			NIT/NMNM87877X
Oil Well Gas W	_		8. Well Name and No	^{).} SJU TR-B/12
2. Name of Operator LEGACY RESE	RVES OPERATING LP		9. API Well No. 3002	2520547
3a. Address 15 SMITH ROAD SUITE	E 3000, MIDLAND, TX 79 3b. Phone No. (432) 689-520		10. Field and Pool or JUSTIS/JUSTIS	Exploratory Area
4. Location of Well (Footage, Sec., T.,R SEC 11/T25S/R37E/NMP	.,M., or Survey Description)		11. Country or Parish LEA/NM	ı, State
12. CHE	CK THE APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTI	ICE, REPORT OR OT	HER DATA
TYPE OF SUBMISSION		TYPE OF AC	TION	
Notice of Intent	Acidize Deep Alter Casing Hydr	en Prod	duction (Start/Resume)	Water Shut-Off Well Integrity
Subsequent Report			omplete	Other
Subsequent Report	Change Plans Plug	and Abandon Tem	porarily Abandon	
Final Abandonment Notice	Convert to Injection Plug	Back Wate	er Disposal	
is ready for final inspection.)	ices must be filed only after all requirements	s, including reclamation, hav	e been completed and	the operator has detennined that the site
4. I hereby certify that the foregoing is ERIN MAZUR / Ph: (713) 594-5843	true and correct. Name (Printed/Typed)	Regulatory Manage	er	
Signature (Electronic Submissio	n)	Date	05/21/2	2024
	THE SPACE FOR FEDI	ERAL OR STATE OF	ICE USE	
Approved by				
ZOTA M STEVENS / Ph: (575) 234	1-5998 / Approved	Petroleum Eng Title	gineer	05/29/2024 Date
	ned. Approval of this notice does not warrant quitable title to those rights in the subject led duct operations thereon.			
Title 18 U.S.C Section 1001 and Title 43	3 U.S.C Section 1212, make it a crime for an	y person knowingly and will	Ifully to make to any d	lepartment or agency of the United States

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve **hydraulic fracturing operations**, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

(Form 3160-5, page 2)

Additional Information

Location of Well

 $0. \ SHL: \ SENW \ / \ 1650 \ FNL \ / \ 2310 \ FWL \ / \ TWSP: \ 25S \ / \ RANGE: \ 37E \ / \ SECTION: \ 11 \ / \ LAT: \ 32.1474633 \ / \ LONG: \ -103.1346668 \ (\ TVD: \ 0 \ feet \)$ $BHL: \ SENW \ / \ 1650 \ FNL \ / \ 2310 \ FWL \ / \ TWSP: \ 25S \ / \ SECTION: \ / \ LAT: \ 0.0 \ / \ LONG: \ 0.0 \ (\ TVD: \ 0 \ feet \)$

Constitution Copy to Appropriate District 9:11 PM	State of New Mexico	Form 6-103 o
Office <u>District I</u> – (575) 393-6161 Energ	y, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-20547
811 S. First St., Artesia, NM 88210 OIL	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND F	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRII		Carrella Irratia I Irrit
DIFFERENT RESERVOIR. USE "APPLICATION FOR I PROPOSALS.)	ERMIT (FORM C-101) FOR SUCH	South Justis Unit
1. Type of Well: Oil Well Gas Well [Other	8. Well Number B12
Name of Operator Legacy Reserves Operating LP		9. OGRID Number 240974
3. Address of Operator		10. Pool name or Wildcat
1400 16th St., Ste 510 Denver, CO 802	202	Justis (Blinebry-Tubb-Drinkard)
4. Well Location		
Unit Letter F : 1650 f	Feet from the N line and	2310feet from the Wline
Section 11	Township 25S Range 37E	NMPM County Lea County
11. Elevat	ion (Show whether DR, RKB, RT, GR,	etc.)
	3128 GR	
12 Cheek Annooniet	a Day to Indianta Natura of Nati	ing Demontor Other Data
12. Check Appropriate	e Box to Indicate Nature of Noti	ice, Report or Other Data
NOTICE OF INTENTION	NTO: S	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN	D ABANDON ☑ REMEDIAL W	
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE	E COMPL	MENT JOB
DOWNHOLE COMMINGLE ☐ CLOSED-LOOP SYSTEM ☐		
OTHER:	☐ OTHER:	
		s, and give pertinent dates, including estimated date
	ULE 19.15.7.14 NMAC. For Multiple	e Completions: Attach wellbore diagram of
proposed completion or recompletion. 1. MIRU rig. Pull Rods & pump.		
2. ND prod tree & NU BOP's. 3. Release trapped pressure as necessary. Kill well with 9.0ppg mud		
4. RIH w/ tbg & tag cmt @ 4984'. PU tbg to 4980' and circ wellbore w/ 9.0ppg m 5. PU tbg to 4900'. RU e-line. RIH w/ perf gun thru tbg and perf 7" csg from 4949		
POOH w/ spent perf gun. RD e-line. RH w/ tbg to 4950 and Sqz & spot balanced cement plug at 4950'-4720' to cover DV Tool & Glorieta.		
6. PU tbg to 4250' and spot balanced 51sxs Class C cement plug at 4250'-4020' to	cover the San	
Andres. 7. PU tbg to 3100' and spot balanced 30sxs Class C cement plug at 3100-2870' to	cover the Langlie	
Mattix 7Riv Q Grayburg. 8. PU the to 1117' and spot balanced 25sxs Class C cement plug at 1117-1007'. Pl	U tbg to 700' &	
clear tbg & WOC. RIH w/ tbg & tag cmt plug @ 1007'. POOH w/ tbg. 9. RU e-line & RIH w/ 1' perf gun @ 4spf & shoot cmt sqz perfs @ 649'-650'. PO	OOH w/ spent perf	
gun & RD e-line. 10. Pump down 7" csg & establish circulation w/ 9.0ppg mud. Then pump 275sxs	Class C cmt down	
7" csg & cmt sqz cmt back to surface in the 7" x 9-5/8" annulus. 11. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to		
necessary w/ Class C cmt back to surface. Weld a steel plate over all casings and e monument. Clear off and restore well location per BLM guidelines.	rect a marker	
Spud Date:	Rig Release Date:	
III and a self of a day in formation the single		1. 1 11. 1' . 6
I hereby certify that the information above is true	and complete to the best of my know.	ledge and belief.
Enin. Magus		
SIGNATURE Fin Mazur	_{TITLE} Regulatory Mana	ager _{DATE} 5/8/2024
Type or print name Erin Mazur	E mail add emazur@	revenirenergy.com _{HONE:} 713-594-5843
For State Use Only	E-mail address:	PHONE: 1.10 00 1 00 10
101 batte ost omy		
APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		


P&A Procedure for the South Justis Unit #B12

- 1. MIRU rig. Pull Rods & pump.
- 2. ND prod tree & NU BOP's.
- 3. Release trapped pressure as necessary. Kill well with 9.0ppg mud
- 4. RIH w/ tbg & tag cmt @ 4984'. PU tbg to 4980' and circ wellbore w/ 9.0ppg mud.
- 5. PU tbg to 4900'. RU e-line. RIH w/ perf gun thru tbg and perf 7" csg from 4949-4950 w/ 4spf, POOH w/ spent perf gun. RD e-line. RIH w/ tbg to 4950 and Sqz & spot balanced 91sxs Class C cement plug at 4950'-4720' to cover DV Tool & Glorieta.
- 6. PU tbg to 4250' and spot balanced 51sxs Class C cement plug at 4250'-4020' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 30sxs Class C cement plug at 3100-2870' to cover the Langlie Mattix 7Riv Q Grayburg.
- 8. PU tbg to 1117' and spot balanced 25sxs Class C cement plug at 1117-1007'. PU tbg to 700' & clear tbg & WOC. RIH w/ tbg & tag cmt plug @ 1007'. POOH w/ tbg.
- 9. RU e-line & RIH w/ 1' perf gun @ 4spf & shoot cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 10. Pump down 7" csg & establish circulation w/ 9.0ppg mud. Then pump 275sxs Class C cmt down 7" csg & cmt sqz cmt back to surface in the 7" x 9-5/8" annulus.
- 11. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 16.4ppg & mud will be 9.0ppg.














BLM Revised P&A Procedure for the South Justis Unit #B12

- 1. MIRU rig. Pull Rods & pump.
- 2. ND prod tree & NU BOP's.
- 3. Release trapped pressure as necessary. Kill well with 9.0ppg mud
- 4. RIH w/ tbg & tag cmt @ 4984'. PU tbg to 4980' and circ wellbore w/ 9.0ppg mud.
- 5. PU tbg to 4900'. RU e-line. RIH w/ perf gun thru tbg and perf 7" csg from 4949-4950 w/ 4spf, POOH w/ spent perf gun. RD e-line. RIH w/ tbg to 4950 and Sqz & spot balanced 91sxs Class C cement plug at 4950'-4720' to cover DV Tool & Glorieta. **WOC and Tag**
- 6. PU tbg to 4250' and spot balanced 51sxs Class C cement plug at 4250'-4020' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 30sxs Class C cement plug at 3100-2870' to cover the Langlie Mattix 7Riv Q Grayburg.
- 8. PU tbg to 1117' and spot balanced 25sxs Class C cement plug at 1117-1007'. PU tbg to 700' & clear tbg & WOC. RIH w/ tbg & tag cmt plug @ 1007'. POOH w/ tbg. **WOC and Tag**
- 9. RU e-line & RIH w/ 1' perf gun @ 4spf & shoot cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 10. Pump down 7" csg & establish circulation w/ 9.0ppg mud. Then pump 275sxs Class C cmt down 7" csg & cmt sqz cmt back to surface in the 7" x 9-5/8" annulus.
- 11. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 16.4ppg & mud will be 9.0ppg.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **fresh** water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours for Class C or accelerated cement (calcium chloride) and 6 hours for Class H. Tagging the plug means running in the hole with a string of tubing or drill pipe and placing sufficient weight on the plug to ensure its integrity. Other methods of tagging the plug may be approved by the BLM authorized officer or BLM field representative.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

Fluid used to mix the cement in R111Q shall be saturated with the salts common to the section penetrated, and in suitable proportions but not less than 1% and not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified *BY PHONE* (numbers listed in 2. Notifications) a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds). A weep hole shall be left if a metal plate is welded in place.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or

concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos

Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713

Robert Duenas Environmental Protection Specialist 575-234-2229


Doris Lauger Martinez
Environmental Protection Specialist
575-234-5926

Jaden Johnston Environmental Protection Asst. (Intern) 575-234-6252

Released to Imaging: 6/18/2024 4:04:09 PM















P&A Procedure for the South Justis Unit #B12

- 1. MIRU rig. Pull Rods & pump.
- 2. ND prod tree & NU BOP's.
- 3. Release trapped pressure as necessary. Kill well with 9.0ppg mud
- 4. RIH w/ tbg & tag cmt @ 4984'. PU tbg to 4980' and circ wellbore w/ 9.0ppg mud.
- 5. PU tbg to 4900'. RU e-line. RIH w/ perf gun thru tbg and perf 7" csg from 4949-4950 w/ 4spf, POOH w/ spent perf gun. RD e-line. RIH w/ tbg to 4950 and Sqz & spot balanced 91sxs Class C cement plug at 4950'-4720' to cover DV Tool & Glorieta.
- 6. PU tbg to 4250' and spot balanced 51sxs Class C cement plug at 4250'-4020' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 30sxs Class C cement plug at 3100-2870' to cover the Langlie Mattix 7Riv Q Grayburg.
- 8. PU tbg to 1117' and spot balanced 25sxs Class C cement plug at 1117-1007'. PU tbg to 700' & clear tbg & WOC. RIH w/ tbg & tag cmt plug @ 1007'. POOH w/ tbg.
- 9. RU e-line & RIH w/ 1' perf gun @ 4spf & shoot cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 10. Pump down 7" csg & establish circulation w/ 9.0ppg mud. Then pump 275sxs Class C cmt down 7" csg & cmt sqz cmt back to surface in the 7" x 9-5/8" annulus.
- 11. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 16.4ppg & mud will be 9.0ppg.















P&A Procedure for the South Justis Unit #B12

- 1. MIRU rig. Pull Rods & pump.
- 2. ND prod tree & NU BOP's.
- 3. Release trapped pressure as necessary. Kill well with 9.0ppg mud
- 4. RIH w/ tbg & tag cmt @ 4984'. PU tbg to 4980' and circ wellbore w/ 9.0ppg mud.
- 5. PU tbg to 4900'. RU e-line. RIH w/ perf gun thru tbg and perf 7" csg from 4949-4950 w/ 4spf, POOH w/ spent perf gun. RD e-line. RIH w/ tbg to 4950 and Sqz & spot balanced 91sxs Class C cement plug at 4950'-4720' to cover DV Tool & Glorieta.
- 6. PU tbg to 4250' and spot balanced 51sxs Class C cement plug at 4250'-4020' to cover the San Andres.
- 7. PU tbg to 3100' and spot balanced 30sxs Class C cement plug at 3100-2870' to cover the Langlie Mattix 7Riv Q Grayburg.
- 8. PU tbg to 1117' and spot balanced 25sxs Class C cement plug at 1117-1007'. PU tbg to 700' & clear tbg & WOC. RIH w/ tbg & tag cmt plug @ 1007'. POOH w/ tbg.
- 9. RU e-line & RIH w/ 1' perf gun @ 4spf & shoot cmt sqz perfs @ 649'-650'. POOH w/ spent perf gun & RD e-line.
- 10. Pump down 7" csg & establish circulation w/ 9.0ppg mud. Then pump 275sxs Class C cmt down 7" csg & cmt sqz cmt back to surface in the 7" x 9-5/8" annulus.
- 11. Cut off wellhead/all casings 3' below ground level, check all annuli for cmt to surface & top fill as necessary w/ Class C cmt back to surface. Weld a steel plate over all casings and erect a marker monument. Clear off and restore well location per BLM guidelines.

NOTE: Class C cement will be 16.4ppg & mud will be 9.0ppg.














District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 353850

COMMENTS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
1400 16th Street, Suite 510	Action Number:
Denver, CO 80202	353850
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartine	z DATA ENTRY PM.	6/18/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 353850

CONDITIONS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
1400 16th Street, Suite 510	Action Number:
Denver, CO 80202	353850
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	Like approval from BLM Run CBL	6/18/2024