eceived by QCP i 8 Appropriate 2:33:41 Office	State of field files			Form C-103 of C
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natura	al Resources	WELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OW CONCERNATIONAL	DH HGION	30-045-11502	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION		5. Indicate Type of Lea	ase
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franc		STATE	FEE 🖂
District IV – (505) 476-3460	Santa Fe, NM 875	505	6. State Oil & Gas Lea	se No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			FEE	
	TICES AND REPORTS ON WELLS		7. Lease Name or Unit	Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLU		SAN JUAN 3	
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR	R SUCH	8. Well Number	
1. Type of Well: Oil Well	Gas Well X Other		37	
2. Name of Operator			9. OGRID Number	
HILCORP ENERGY COMPA	NY		3721	-
3. Address of Operator	410		10. Pool name or Wild	
382 Road 3100, Aztec, NM 874	410		Blanco Mesaverde/Bas	ın Dakota
4. Well Location				
Unit Letter L :_	790 feet from the North	line and	300 feet from the _	West line
Section 09	Township 32N Range		MPM San Juan	County
	11. Elevation (Show whether DR,			
	6336	Ď		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco	CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT OTHER: tinent details, and g For Multiple Comp	LING OPNS. P AN JOB D give pertinent dates, included letions: Attach wellbord	ERING CASING
Hilcorp Energy is requesting	approval to repair the packer for the	ne subject well pe	r the attached procedu	re.
Spud Date:	Rig Release Date:			
		L		
I hereby certify that the information a	above is true and complete to the best	of my knowledge a	nd belief.	
	TITLE_Operations/			3/14/2024
	TITLE_Operations/ Shorty E-mail address:psl			



Prepared by:	Christian Zuvich
Preparation Date:	April 15, 2024

WELL INFORMATION				
Well Name:	SAN JUAN 32-7 UNIT 37	State:	NM	
API #:	3004511502	County:	SAN JUAN	
Area:	5	Location:	790' FNL & 300' FWL - Unit L - Section 9 - T 032N - R 007W	
Route:	0504	Latitude:	36.99781 N	
Spud Date:	7/25/1962	Longitude:	-107.57911 W	


Pull packer and both production strings, run in with bit and scraper to clean wellbore, clean out wellbore, set CIBP 50' above the Dakota perfs, witnessed MIT test with packer from bottom of MV to CIBP, run in hole with production tubing and set in Mesa Verde perfs, return well to production.

CONTACTS				
Title	Name	Office Phone #	Cell Phone #	
Engineer	Christian Zuvich		832-671-8256	
Area Foreman	Cameron Garrett		947-5683	
Lead	Scott Wagner		419-2516	
Artificial Lift Tech	Jamie Reynolds		787-7712	
Operator	Brandon Noble		486-6632	




NMOCD Please notify NMOCD (505-334-6178) and BLM (505-564-7750) at least 24 hrs before the rig arrives to prep the well. BLM Please log all phone calls in daily rig reports. Comply with all NMOCD, BLM, and HEC safety and environmental 1. Hold pre-job safety meeting. Comply with all NMOCD/BLM and HEC safety and environmental regulations. Scope location for base beam. If base beam can not be used, test rig anchors prior to moving in rig. Verify there is no H2S present prior to beginning operations. Verify cathodic is offline. 2. MIRU service rig and associated equipment; NU and test BOP per HEC, State, and Federal guidelines. Inspect wellhead for possible leak 3. TOOH with the 1.66" small string from 5,582', TOOH with 2-1/16" long string with packer from 7,748'. 4. Run in hole with a bit and scraper to 7,730', pull out, run in hole with CIBP and set 50' above Dakota perforations (+/-7,766), set packer 50' below Mesa Verde perforations (+/- 5,591'), load hole with fresh water, pressure test to ensure casing integrity. 5. If successful, perform a witnessed MIT. If unsuccessful, perform remediation as necessary after proper notification to OCD has been approved. 6. POOH packer and TIH with production BHA and string. Land at 5,582' and produce the Mesa Verde through the tubing. 7. ND BOPE, NU Wellhead. RDMO workover rig. Bring prodution online. * Per email chain between Hilcorp engineer and OCD - This is not a temporary abandon, this is a temporary plug. A CIBP will be set within 50' of the top Dakota perforation and a witnessed MIT will need to be performed between the bottom of MV perforations and CIBP.









District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 373948

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	373948
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Cre	eated By	Condition	Condition Date
m	nkuehling	Notify NMOCD 24 hours prior to moving on - attach email chain to subsequent	8/26/2024