
Constitute Copy to Appropriate bistact: 38 AM	State of New Mexico		Form C-103 <sup>1</sup>	
Office District I – (575) 393-6161  Energy, Minerals and Natural Resources			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	<u> </u>		NO.	
District II – (575) 748-1283	ONSERVATION DIVI	SION 30-025-0492		
511 5. 1 list 5t., Altesia, NW 66216	220 South St. Francis Di	5. Indicate 1	Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		SIAI		
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil	& Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND RI	EPORTS ON WELLS	7. Lease Na	me or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Grayburg Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Nun	nber 142	
1. Type of Well: Oil Well Gas Well	Other			
2. Name of Operator		9. OGRID N	Number 330679	
Empire Petroleum Corporation – New Mexico				
3. Address of Operator		10. Pool nar	ne or Wildcat	
2200 S. Utica Place Suite 150, Tulsa, Oklahoma	74114	Arrowhead;	Grayburg	
4. Well Location				
Unit Letter N : 660 fee	t from the South lin	ne and1980feet t	from theWestline	
	ownship 21S Range	36E NMPM		
	on (Show whether DR, RKB, I			
111 2.0 ( 111.1	, (Sive ii, iii, iii, iii, iii, iii, iii, ii	11, 51, 610.7		
12 Check Appropriate	Box to Indicate Nature	of Notice Report or O	ther Data	
12. Check Appropriate	Box to maleute Puttine (	or record or o	iner Data	
NOTICE OF INTENTION	TO:	SUBSEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK ⊠ PLUG AND	ABANDON ☐ REME	EDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON   CHANGE P	LANS 🗌 COMI	MENCE DRILLING OPNS.	□ P AND A □	
PULL OR ALTER CASING   MULTIPLE	COMPL CASII	NG/CEMENT JOB		
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:	OTHE			
13. Describe proposed or completed operation				
of starting any proposed work). SEE RU proposed completion or recompletion.	LE 19.13.7.14 NMAC. FOR I	viulupie Completions: Att	ach wendore diagram of	
proposed completion of recompletion.				
1. MIRU WOR.				
2. POOH to rod part.				
3. MU and PU fishing tools.				
4. RIH and latch onto fish.				
5. Unseat pump and POOH with remain	ning rod string configuration.			
6. Redress pump.				
7. RIH with pump and rod string design	and seat pump.			
8. Load and test tubing.				
9. Notify NMOCD.				
10. RTP.				
	] Г			
Spud Date:	Rig Release Date:			
I hereby certify that the information above is true	and complete to the best of m	y knowledge and belief.		
SIGNATURE Nathan Sandel	TITLE Production I	Engineer	DATE 03/03/2025	
SIGNATURE				
Type or print name Nathan Sandel	E-mail address: nsar	ndel@empirepetrocorp.com	PHONE: 918-404-4202	
For State Use Only				
A DDD OVED DV			D 4 mm	
	TITLE	<del></del>	_DATE	
Conditions of Approval (if any):				

## **Current and Proposed WBD**



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 438183

## **CONDITIONS**

Operator:	OGRID:
Empire New Mexico LLC	330679
2200 S. Utica Place	Action Number:
Tulsa, OK 74114	438183
	Action Type:
	[C-103] NOI Workover (C-103G)

## CONDITIONS

Created By		Condition Date
ward.rikala	Notify the OCD inspection supervisor 24 hours prior to beginning Plug & Abandon (P&A) operations.	4/8/2025
ward.rikala	Subsequent report of operations to be submitted upon completion of work.	4/8/2025