
Office	Butte of field			Form C-103 <sup>1</sup>
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and N	latural Resources	WELL API NO.	Revised July 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	ON DIVISION	30-025-10094	
<u>District III</u> – (505) 334-6178	1220 South St. I	Francis Dr.	5. Indicate Type of L	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM		STATE	FEE 🛛
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa PC, INIV.	1 87303	6. State Oil & Gas Lo	ease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Ur Arrowhead Grayburg	
PROPOSALS.)	_ `	1) FOR SUCH	8. Well Number 184	
2. Name of Operator	Gas Well Other		9. OGRID Number 3	30679
Empire Petroleum Corporation – Ne 3. Address of Operator	w Mexico		10. Pool name or Wi	ldeat
2200 S. Utica Place Suite 150, Tulsa	, Oklahoma 74114		Arrowhead; Grayburg	
4. Well Location				
Unit Letter <u>D</u> :			feet from the	Westline
Section 7	Township 212S	Range 37E	NMPM	County Lea
	11. Elevation (Show whether 3460' GE	DR, RKB, RT, GR, etc.	.)	
12 Cl1- A		- NI-4	Deve et en Otten De	4
•	ppropriate Box to Indicate		-	
NOTICE OF INT			SSEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		_	AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	iT JOB ∐	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:		OTHER:	<del> </del>	
13. Describe proposed or comple				
	k). SEE RULE 19.15.7.14 NN	AAC. For Multiple Co	impletions: Attach welli	ore diagram of
proposed completion or reco	inpletion.			
1. MIRU WOR.				
	string and POOH to rod part.			
3. MU fishing tool and RIF				
4. Unset pump and POOH				
5. ND WH and NU BOP.	with rod string and same.			
6. Unset TAC and scan tub	ing OOH			
7. RIH with tbg and set TA				
8. ND BOP and NU WH.				
	string design and seat pump.			
10. Load and test tubing.	string design and seat pump.			
11. Notify NMOCD.				
12. RDMO.				
13. RTP.				
Spud Date:	Rig Release	e Date:		
hereby certify that the information al	bove is true and complete to the	ne best of my knowledg	ge and belief.	
.,,/ - 21		advatice 5		02/06/0005
SIGNATURE Nathan Sandel		oduction Enginee		03/06/2025
Type or print name Nathan Sand	el E-mail add	Iress:nsandel@empirep	petrocorp.com PHON	E: 918-404-4202
For State Use Only				
APPROVED BY:	TITLE		DATE	

## **Current and Proposed WBD**



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 439931

## **CONDITIONS**

Operator:	OGRID:
Empire New Mexico LLC	330679
2200 S. Utica Place	Action Number:
Tulsa, OK 74114	439931
	Action Type:
	[C-103] NOI Workover (C-103G)

## CONDITIONS

Created By		Condition Date
ward.rikala	Notify the OCD inspection supervisor 24 hours prior to beginning Plug & Abandon (P&A) operations.	4/8/2025
ward.rikala	Subsequent report of operations to be submitted upon completion of work.	4/8/2025