

(DO NOT USE THIS FORM FOR PROPO	State of New Mexic Energy, Minerals and Natura OIL CONSERVATION II 1220 South St. France Santa Fe, NM 875 ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG CATION FOR PERMIT" (FORM C-101) FOR Gas Well Other INJECTION	1 Resources V 3 DIVISION is Dr. 05 6 BACK TO A SUCH 8	Form C-103 Revised July 18, 2013 VELL API NO. 0-025-31489 Indicate Type of Lease STATE X FEE State Oil & Gas Lease No. Lease Name or Unit Agreement Name Vest Dollarhide Drinkard Unit Well Number 122 OGRID Number
Scout Energy Management, LLC.		3	30949
3. Address of Operator 13800 Montfort Dr., STE 100 Dallas Tx 75240			0. Pool name or Wildcat ollarhide; TUBB Drinkard
Unit Letter: K; 2055f Section 32		NMPM (KB, RT, GR, etc.)	neWESTline County Lea
	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLI CASING/CEMENT JO OTHER: Re- Trinent details, and go	OB
Scout Energy's plan of action: is to MIT.	set CIBP to test the casing and reseat t	he packer @6375', o	circulate well with packer fluid and Run
Spud Date:	Rig Release Date	:	
I hereby certify that the information	above is true and complete to the best	of my knowledge a	nd belief.
SIGNATURE DORNANKI	TITLE: SR. Reg Sp	pecialistDATE:	03/19/2024
Type or print name <u>Dorian K. Fuent</u> For State Use Only	es E-mail address: dfuentes@scoutep.	com PHONE: <u>972-3</u>	325-1005
APPROVED BY:Conditions of Approval (if any):	TITLE		DATE

PROCEDURE WDDU 122: 03-19-2025

- 1. MIRU ND WH and NU BOP
- 2. RIH and set CIBP @ 6378'
- 3. Test casing.
- 4. RIH with injection tbg @ EOT 6380'
- 5. ND BOP, Set packer @ 6370' and NU WH
- 6. Circ well with packer fluid
- 7. Run MIT test





Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 443934

CONDITIONS

Operator:	OGRID:
SCOUT ENERGY MANAGEMENT LLC	330949
13800 Montfort Road	Action Number:
Dallas, TX 75240	443934
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
anthony.harris	After completing well work, MIT and Bradenhead test to be performed with OCD as witness. Failure of either test shall require the well to be shut-in and a forward plan submitted to OCD.	4/22/2025