

<b>Well Name:</b> HANCOCK	<b>Well Location:</b> T27N / R12W / SEC 10 / NENW / 36.594223 / -108.101746	<b>County or Parish/State:</b> SAN JUAN / NM
<b>Well Number:</b> 12	<b>Type of Well:</b> CONVENTIONAL GAS WELL	<b>Allottee or Tribe Name:</b>
<b>Lease Number:</b> NMSF079116	<b>Unit or CA Name:</b>	<b>Unit or CA Number:</b>
<b>US Well Number:</b> 3004506633	<b>Operator:</b> HILCORP ENERGY COMPANY	

### Notice of Intent

*Released to Imaging: 5/7/2025 3:30:38 PM*

**Sundry ID:** 2851044

**Type of Submission:** Notice of Intent

**Type of Action:** Variance

**Date Sundry Submitted:** 05/05/2025

**Time Sundry Submitted:** 02:55

**Date proposed operation will begin:** 05/05/2025

**Procedure Description:** Hilcorp Energy requests a variance to 43 CFR 3162.6(d) permanent P&A monument and NMOCD 19.15.25.10 dry hole marker requirements. The standard above grade P&A marker was set upon P&A on 4/3/2025. It has been brought to Hilcorp's attention by Navajo Agricultural Products Industry (NAPI) representative, Alysse Pablo, Land Development Coordinator, that the current P&A marker has potential to cause issues with the irrigation pivot and farm equipment as it is located partially inside the field/pivot tracks. To avoid future damage to the farm equipment, it is requested to install a below grade marker.

### NOI Attachments

#### Procedure Description

Hancock\_12\_P\_A\_Marker\_Correspondence\_20250505145428.pdf

**Well Name:** HANCOCK

**Well Location:** T27N / R12W / SEC 10 /  
NENW / 36.594223 / -108.101746

**County or Parish/State:** SAN  
JUAN / NM

**Well Number:** 12

**Type of Well:** CONVENTIONAL GAS  
WELL

**Allottee or Tribe Name:**

**Lease Number:** NMSF079116

**Unit or CA Name:**

**Unit or CA Number:**

**US Well Number:** 3004506633

**Operator:** HILCORP ENERGY  
COMPANY

### Operator

*I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a*

**Operator Electronic Signature:** CHERYLENE WESTON

**Signed on:** MAY 05, 2025 02:46 PM

**Name:** HILCORP ENERGY COMPANY

**Title:** Operations/Regulatory Tech - Sr

**Street Address:** 1111 TRAVIS STREET

**City:** HOUSTON

**State:** TX

**Phone:** (713) 289-2615

**Email address:** CWESTON@HILCORP.COM

*Released to Imaging: 5/7/2025 3:30:38 PM*

### Field

**Representative Name:**

**Street Address:**

**City:**

**State:**

**Zip:**

**Phone:**

**Email address:**

### BLM Point of Contact

**BLM POC Name:** JEFFREY J TAFOYA

**BLM POC Title:** Assistant Field Manager

**BLM POC Phone:** 5055647672

**BLM POC Email Address:** JTAFOYA@BLM.GOV

**Disposition:** Approved

**Disposition Date:** 05/06/2025

**Signature:** s/ Jeff Tafoya

Form 3160-5 (June 2019)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2021
<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <i>Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.</i>		5. Lease Serial No. NMSF079116
		6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. HANCOCK/12
2. Name of Operator HILCORP ENERGY COMPANY		9. API Well No. 3004506633
3a. Address 1111 TRAVIS STREET, HOUSTON, TX 77002	3b. Phone No. (include area code) (713) 209-2400	10. Field and Pool or Exploratory Area KUTZ PICTURED CLIFFS/KUTZ PICTURED CLIFFS
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SEC 10/T27N/R12W/NMP		11. Country or Parish, State SAN JUAN/NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off	
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other	
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon		
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

Hilcorp Energy requests a variance to 43 CFR 3162.6(d) permanent P&A monument and NMOCD 19.15.25.10 dry hole marker requirements. The standard above grade P&A marker was set upon P&A on 4/3/2025. It has been brought to Hilcorp's attention by Navajo Agricultural Products Industry (NAPI) represenative, Alysse Pablo, Land Development Coordinator, that the current P&A marker has potential to cause issues with the irrigation pivot and farm equipment as it is located partially inside the field/pivot tracks. To avoid future damage to the farm equipment, it is requested to install a below grade marker.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) CHERYLENE WESTON / Ph: (713) 289-2615	Title Operations/Regulatory Tech - Sr
Signature (Electronic Submission)	Date 05/05/2025

THE SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved by JEFFREY J TAFOYA / Ph: (505) 564-7672 / Approved	Assistant Field Manager	05/06/2025
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Title	Date
	Office FARMINGTON	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**Cheryl Weston**

---

**From:** Alysse Pablo <apablo@navajopride.com>  
**Sent:** Wednesday, April 30, 2025 5:25 PM  
**To:** Cheryl Weston; Bryan Hall  
**Cc:** Richard R. Gilbreath  
**Subject:** [EXTERNAL] Hilcorp - P&A Issue  
**Attachments:** Pole Marker inside field.jpg; Hancock 12 open pit.jpg; Hancock 12.jpg; IMG\_8588.jpeg

**CAUTION:** External sender. DO NOT open links or attachments from UNKNOWN senders.

Hello Cheryl and Bryan,

Good afternoon, hope all is well. I wasn't sure who to contact for wellsite Hancock 12, then I remembered we visit this site last year. Last week on April 21<sup>st</sup>, contractors came and demolished the site but left some items and I noticed that the Pole marker is inside NAPI field. The pole marker will be an issue to NAPI operations whereas later down the road the pivot might run into the pole and cause damage to the pivot, or a farm equipment might run into the pole. On the onsite visit notes I mentioned to seed and cut below ground, and for gravel to put on road. Could we have the pole taken out and be replaced by a different kind of marker?

See attached photos of the area.

If you have any questions, please contact me.

Thanks,



*Alysse Pablo*, Land Development Coordinator  
Navajo Agricultural Products Industry  
Direct: 505-566-2653  
Main: 505-566-2600 • Fax: 505-960-9458  
PO Drawer 1318, Farmington, NM 87499  
[www.navajopride.com](http://www.navajopride.com)

---

**From:** Cheryl Weston <cweston@hilcorp.com>  
**Sent:** Wednesday, May 15, 2024 11:38 AM  
**To:** Alysse Pablo <apablo@navajopride.com>; Belinda Chee <belindachee@navajo-nsn.gov>; Spencer, Bertha <Bertha.Spencer@bia.gov>  
**Cc:** Herrera, Roger D <RHerrera@blm.gov>; Bryan Hall <bhall@hilcorp.com>  
**Subject:** RE: [EXTERNAL] Hilcorp - P&A Onsite Request

**ATTENTION:** This email was sent from someone outside of NAPI.  
You are advised to not open attachments and to not click on links from emails that originated outside of NAPI, unless you first verify that the email is safe.









Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 459626

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 459626
	Action Type: [C-103] NOI General Sundry (C-103X)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	Approval is given for the below grade marker - submit gps reading and photo of plate in place prior to backfill - along with google earth picture of area	5/7/2025