District 1 1625 N French Dr., Hobbs, NM 83240 Phone: (575) 393-6151 Fax. (575) 393-6720

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office



OBSERVED DATA

anna an Sanaan an Sanaan am Sanaan Sanaa	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			0	850
Flow Characteristics					
Puff	Y / R	YIN	Y / N	(Y) N	CO2 WTR
Steady Flow	Y / N	Y N	Y /N	Y / (R)	GAS
Surges	Y/Q	YIN	Y/ N	Y/N	T) pe of Flaid
Down to nothing	N N	Y/N	Y / N	(V) N	Lajected for Waterflord if
Gas or Oil	Y/Q	Y / N	Y / N	Y / N	applies.
Water	Y / N	Y / N	Y / N	Y /N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down	or continuous build up if applies.
Signature:	OIL CONSERVATION DIVISION
Printed name: Lee Ellison	Entered into RBDMS
Title SP Prop Foremaal	Re-test
E-mail Address: / ellisonescoutep.com	

INSTRUCTIONS ON BACK OF THIS FORM

806-891-0020

3-12-25

Date:

Phone:

Winness.

PERFORMING BRADENHEAD TEST

General Procedure for Bradenhead Test

- Identify: All valves prior to testing
- Gauges: Install on each casing string to record pressure.

Assure: That all valves are in good working condition and <u>closed at least 24 hours prior</u> to testing.

Open: Each valve (Bradenhead, intermediate and casing valves) is to be opened

Check Gauges: Record pressure on each gauge and casing string on BHT form. Open valves to atmosphere and record results on BHT form.

Designate what applies to the result of opening the valves for each string:

5 a () a	Blow or Puff Bled down to Nothing Steady Flow Dil or Gas Water	Yes or No Yes or No Yes or No Yes or No Yes or No
-------------	--	---

Start: Injection or SWD pump so tubing pressure can be read.

Instructions below apply to the District 1 Hobbs office since this must be reported on a form.

In case of pressure:

- 1. Record pressure reading on gauge.
- 2. Bleed and note time elapsed to bleed down.
- 3. Leave valve open for additional observation.
- 4. Note any fluids expelled.

In absence of Pressure:

- 1. Leave valve open for additional observation.
- 2 Note types of fluids expelled.
- 3. Note if fluids persist throughout test.

Note. Tubing pressure on injection or SWD wells.

Test will be signed by person performing test with a contact phone number.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
SCOUT ENERGY MANAGEMENT LLC	330949
13800 Montfort Road	Action Number:
Dallas, TX 75240	443616
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
blydick	None	6/18/2025

Page 3 of 3

Action 443616