Received by 0 cD. S/1/2025 3:36:03 PM		Sundry Print Report
U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		07/01/2025
Well Name: BLANCO WASH	Well Location: T24N / R9W / SEC 1 / NWSW / 36.340134 / -107.745117	County or Parish/State: SAN JUAN / NM
Well Number: 5	Type of Well: OIL WELL	Allottee or Tribe Name: EASTERN NAVAJO
Lease Number: 142006031402	Unit or CA Name:	Unit or CA Number:
US Well Number: 300452293700S1	Operator: DUGAN PRODUCTION CORPORATION	

Subsequent Report

Received by MCD.Sy1/2025 3:36:03 PM

Sundry ID: 2860783 Type of Submission: Subsequent Report Date Sundry Submitted: 06/30/2025 Date Operation Actually Began: 02/25/2025

Type of Action: Plug and Abandonment Time Sundry Submitted: 02:19

Actual Procedure: Dugan Production P&A'd the well on 02/25/2025 - 03/05/2025 per the attached procedure.

SR Attachments

Actual Procedure

Blanco_Wash_5_BLM_apvd_plug_changes_20250630141904.pdf Blanco_Wash_5_SR_PA_formation_tops_20250630141018.pdf Blanco_Wash_5_SR_PA_completed_wellbore_schematic_20250630141009.pdf Blanco_Wash_5_SR_PA_work_completed_20250630140953.pdf

Received by OCD: 7/1/2025 3:36:03 PM Well Name: BLANCO WASH	Well Location: T24N / R9W / SEC 1 / NWSW / 36.340134 / -107.745117	County or Parish/State: SAN
Well Number: 5	Type of Well: OIL WELL	Allottee or Tribe Name: EASTERN NAVAJO
Lease Number: 142006031402	Unit or CA Name:	Unit or CA Number:
US Well Number: 300452293700S1	Operator: DUGAN PRODUCTION CORPORATION	

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TYRA FEIL

Signed on: JUN 30, 2025 02:19 PM

Name: DUGAN PRODUCTION CORPORATION

Title: Authorized Representative

Street Address: PO BOX 420

City: FARMINGTON

State: NM

Phone: (505) 325-1821

Email address: TYRAFEIL@DUGANPRODUCTION.COM

Field

Representative Name: Aliph ReenaStreet Address: PO Box 420City: FarmingtonState: NMPhone: (505)360-9192Email address: Aliph.Reena@duganproduction.com

BLM Point of Contact

BLM POC Name: MATTHEW H KADE BLM POC Phone: 5055647736

Disposition: Accepted

Signature: Matthew Kade

BLM POC Title: Petroleum Engineer BLM POC Email Address: MKADE@BLM.GOV Disposition Date: 07/01/2025

Zip: 87499-0420

Dugan Production Corp. P&A'd the well on 02/25/2025 - 03/5/2025 per the following procedure:

- 2/5/2025 por the following pr
- MI & RU Aztec Rig 481 and cement equipment.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 2 psi.
- LD rods & 2-3/8" production tubing.
- PU & tally 2-3/8" workstring. Run 4½" string mill tagged obstruction at 6082'. RU power swivel, work tubing and go through fill to 6180'. Circulate bottoms up until returns cleared out.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 2 psi.
- RIH & attempt to get 4 ¹/₂" cement retainer at 6140'. Couldn't get a set. Cannot get the CR set at 6150' & 6117'. Got Cement retainer set at 6117'.
- **Plug I**: Spot Plug I, inside 4½" casing w/18 sks, 20.7 cu ft Class G neat cement to cover the Graneros perforations. Displaced w/22.7 bbls. Tagged TOC at 5896', good tag. **Plug I, inside 4½**" casing, 18 sks, 20.7 cu ft Class G, Graneros perforations, 5896'-6117'.
- Check pressures: Tbg 0 psi, Casing 0 psi, BH 0 psi.
- RIH w/4½" cement retainer to 5160'. Set cement retainer at 5160'. Load and circulate hole clean w/20 bbls water. **Attempt to pressure test casing to 650 psi, casing won't test.** RU wireline and run CBL from 5160' to surface. Sent copy of CBL & revised procedure to BLM/NMOCD. Copy of the communications attached.
- Plug II: Spot Plug II inside 4½" casing from 5106' w/30 sks, 34.5 cu ft Class G neat cement to cover Gallup perforations & Gallup top. Displaced w/18.4 bbls. WOC overnight. Tagged TOC at 4773', good tag. Plug II, inside 4½" casing, 30 sks, 34.5 cu ft, Gallup top & perforations, 4773'-5160'.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 2 psi.
- Plug III:. Spot Plug III, inside 4½" casing from 4628' w/28 sks, 32.2 cu ft Class G neat cement to cover the Mancos top & DV tool. Displaced w/16.5 bbls. Circulated 0.3 bbls cement to surface. WOC 4 hrs. Tagged TOC at 4285'. Good tag. Plug III, inside 4½" casing, 28 sks, 32.2 cu ft, Mancos-DV, 4285'-4628'.
- Attempt to pressure test casing, casing won't test.
- Plug IV: Spot inside Plug IV w/75 sks, 86.25 cu ft Class G neat cement to cover Mesaverde & Lower Chacra tops. Displaced w/ 9.6 bbls water. Circulated 0.3 bbls to surface. WOC overnight. Tagged TOC at 2452'. Good tag.. Plug IV, Inside 4½" casing, 75 sks, 86.25 cu ft, Mesaverde-Lower Chacra, 2452'-3455'.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 4 psi.
- Plug V: Spot Plug V inside 4½" casing from 2401' w/60 sks, 69 cu ft Class G cement to cover the Upper Chacra & Pictured Cliffs top. Displaced w/6.2 bbls water. WOC 4 hrs. Tagged TOC at 1638'. Good tag. Plug V, Inside 4½" casing, 60 sks, 69 cu ft, Upper Chacra-Pictured Cliffs, 1638'-2401'.
- **Plug VI:** Spot Plug VI inside 4¹/₂" casing from 1619' w/ 40 sks, 46 cu ft Class G cement to cover the Fruitland & Kirtland tops. Displaced w/4.2 bbls. WOC overnight. Check pressures, Tubing 0 psi, Casing 0 psi, BH 0 psi. Tagged TOC at 1261', tagged lower. Kirtland top at 1280'. **Attempt to pressure test casing at 650 psi, casing tested for 30 minutes. Casing tested good.** Probable hole in the casing across the Kirtland/Fruitland. Spot cement on top of the Kirtland plug on top of the tag 15 sks, 17.3 cu ft Class G neat cement to cover till 1072'. **Plug VI, Inside 41**/₂" **casing, 55 sks, 63.3 cu ft, Kirtland-Fruitland, 1072'-1619'.**

- TOOH w/tubing and SB. RU wireline and TIH to shoot squeeze holes at 895'. TIH w/4½" cement retainer at 857'. Sting in and establish rate through the perforations, 1 bpm at 650 psi. Swapped to cement.
- **Plug VII:** Spot inside Plug VII w/58 sks, 66.7 cu ft Class G neat cement to cover the Ojo Alamo top, 40 sks, 46 cu ft outside casing, 3 sks below retainer, 15 sks, 17.3 cu ft above retainer inside 4½" casing. Displaced w/1.5 bbls. WOC 4 hrs. Tagged TOC at 650'. Good tag. **Plug VII, Inside/Outside 4½**" casing, **Perforations at 895', Cement retainer 857', 58 sks, 66.7 cu ft, Ojo Alamo, 650'-895'.**
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 0 psi.
- Plug VIII: TOOH w/tubing and SB. RU Wireline and shoot squeeze holes at 267'. Establish circulation to surface through BH, 2 bpm at 50 psi. Swapped to cement. Circulate cement to surface w/106 sks, 121.9 cu.ft Class G neat cement to cover the surface casing shoe. Circulated 1 bbl cement to surface. Plug VIII Inside/Outside 4½" casing, perforations 267', 106 sks, 121.9 cu ft, Surface, 0-267'.
- Cut wellhead off. Tagged TOC at 0' inside annulus & 10' inside 4¹/₂" casing. Good tag.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 0 psi.
- Install dryhole marker & fill up cellar w/18 sks, 20.7 cu ft Class G neat cement. Clean location & RD Aztec 481. Joseph Maestas w/BLM witnessed job.
- Well P&A'd 03/05/2025.

Completed P & A Schematic

Page 5 of 9

Blanco Wash # 5 API: 30-045-22937 Sec 1 T24N R09W 1550' FSL & 1190' FWL San Juan County, NM Lat: 36.339920, Long: -107.745645

8-5/8" J-55 24# casing @ 217'. Cemented with 140 sks Cement.

Plug VIII Inside/Outside 4½" casing, perforations 267', 106 sks, 121.9 cu ft, Surface, 0-267'

Plug VII, Inside/Outside 4½" casing, Perforations at 895', Cement retainer 857', 58 sks, 66.7 cu ft, Ojo Alamo, 650'-895'.

Plug VI, Inside $4\frac{1}{2}$ " casing, 55 sks, 63.3 cu ft, Kirtland-Fruitland, 1072'-1619'

Plug V, Inside 4½" casing, 60 sks, 69 cu ft, Upper Chacra-Pictured Cliffs, 1638'-2401'

Plug IV, Inside 4½" casing, 75 sks, 86.25 cu ft, Mesaverde-Lower Chacra, 2452'-3455'

Plug III, inside $4\frac{1}{2}$ " casing, 28 sks, 32.2 cu ft, Mancos-DV, 4285'-4628'.

Cemented Stage I w/ 350 sks, Class B. **DV tool @ 4447**'. Stage II w/ 465 sks 65-35-12 cement. Will run CBL to determine TOC behind casing

CIBP @ 5160'. Plug II, inside $4\frac{1}{2}$ " casing, 30 sks, 34.5 cu ft, Gallup top & perforations, 4773'-5160'

Gallup Perforations @ 5210'-5836'

CR @ 6117'. Plug I, inside 4½" casing, 18 sks, 20.7 cu ft Class G, Graneros perforations, 5896'-6117'

Graneros Perforated @ 6190'-6240'

4 ¹/₂" 10.5 # casing @ 6485', Hole size 7-7/8"



Blanco Wash # 5

API: 30-045-22937 Sec 1 T24N R09W 1550' FSL & 1190' FWL San Juan County, NM Lat: 36.339920, Long: -107.745645

Elevation ASL: 6707' KB

Formation Tops

- Surface Casing 217'
- Ojo Alamo 845'
- Kirtland 1280'
- Fruitland 1569'
- Pictured Cliffs 1830'
- Lewis 1995'
- Chacra Upper-2351'
- Chacra Lower 2693'
- Mesaverde 3405'
- Mancos 4446'
- DV tool 4447'
- Gallup 4961'
- Gallup perforations 5210'-5836'
- Greenhorn 6159'
- Greenhorn Perforations 6190'-6240'
- Graneros 6242'
- Dakota 6332'

Tyra Feil

From: Sent:	Rennick, Kenneth G <krennick@blm.gov> Friday, February 28, 2025 7:09 PM</krennick@blm.gov>
To:	Aliph Reena; Maestas, Joseph I; Omar Ramirez; Porch, Dustin T; Kade, Matthew H; Lucero, Virgil S
Cc:	Tyra Feil; Alex Prieto-Robles
Subject:	Re: [EXTERNAL] RE: Dugan Blanco Wash #5

CAUTION: This email originated from outside your organization. Exercise caution when opening attachments or clicking links, especially from unknown senders. The BLM finds the updated procedure appropriate.

Kenneth (Kenny) Rennick

Petroleum Engineer

Bureau of Land Management Farmington Field Office 6251 College Blvd Farmington, NM 87402

Email: <u>krennick@blm.gov</u> Mobile & Text: 505.497.0019

From: Aliph Reena <Aliph.Reena@duganproduction.com>
Sent: Friday, February 28, 2025 3:41 PM
To: Maestas, Joseph I <jimaestas@blm.gov>; Omar Ramirez <oramirez@aztecwell.com>; Porch, Dustin T <dporch@blm.gov>; Rennick, Kenneth G <krennick@blm.gov>; Kade, Matthew H <mkade@blm.gov>; Lucero, Virgil S <vlucero@blm.gov>
Cc: Tyra Feil <Tyra.Feil@duganproduction.com>; Alex Prieto-Robles <arobles@aztecwell.com>
Subject: [EXTERNAL] RE: Dugan Blanco Wash #5

This email has been received from outside of DOI - Use caution before clicking on links, opening attachments, or responding.

RE: Dugan Production Corp. API: 30-045-22937 Blanco Wash # 005

From the CBL, the TOC appear to be at 4900' from Stage I & around 1000' from Stage II. There is some bonding, but do not appear to be good cement. Based on that assessment, we request the following changes to the original approved NOI to P & A procedure.

- 1. **Plug VI Fruitland-Kirtland-Ojo Alamo** -: Change from inside plug for Fruitland-Kirtland-Ojo Alamo to Inside plug for Fruitland & Kirtland. Will do Ojo Alamo Plug as a separate plug. Perforate at 895' to cover the Ojo Alamo top. And attempt to do an inside outside plug. If a rate cannot be established, we will further request permission to do an inside plug at that time.
- 2. **Plug VII Surface** -: Change to inside/outside plug. Will perforate at 267' and attempt to circulate cement to surface through BH. If a rate cannot be established, will perforate 50' higher and will re-attempt.

Also, a disparity was discovered in the DV tool depth. CBL verified the DV tool depth to be 4578' and have changed the Mancos-DV plug depth has been changed accordingly.

Please let us know if the following changes are acceptable to BLM & we will proceed accordingly. If any other changes are required, please let us know.

Regards, Aliph Reena 505-360-9192

Aliph Reena P.E Engineering Supervisor Dugan Production Corp. Cell: 505-360-9192

From: Alex Prieto-Robles <arobles@aztecwell.com>
Sent: Thursday, February 27, 2025 2:34 PM
To: Aliph Reena <Aliph.Reena@duganproduction.com>
Cc: Tyra Feil <Tyra.Feil@duganproduction.com>; jimaestas@blm.gov; Omar Ramirez <oramirez@aztecwell.com>; DUSTIN
<dporch@blm.gov>; KENNETH <krennick@blm.gov>; MATHEW <mkade@blm.gov>; MONICA
<monica.kuehling@emnrd.nm.gov>; VIRGIL <vlucero@blm.gov>
Subject: Dugan Blanco Wash #5

CAUTION: This email originated from outside your organization. Exercise caution when opening attachments or clicking links, especially from unknown senders.

Alex Prieto Rig Manager – San Juan Basin Aztec Well Servicing Co. P.O. Box 100 Aztec, New Mexico 87410 Cell: 505-419-9882 Office: 505-334-6191 <u>Arobles@aztecwell.com</u>



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DUGAN PRODUCTION CORP	6515
PO Box 420	Action Number:
Farmington, NM 87499	480851
	Action Type:
	[C-103] Sub. Plugging (C-103P)
CONDITIONS	

	Created By		Condition Date
	loren.diede	Accepted for record	7/3/2025

Page 9 of 9

Action 480851