Office	State of New Mexic	0	Form C
District 1 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural	Resources	Revised November 3 /ELL API NO.
District II	OIL CONSERVATION D		0-021-20588
811 S. First St., Artesia, NM 88210 District III	1220 South St. Francis		Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8750	<i>~</i>	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa 1 0, 1991 0750	5	State Oil & Gas Lease No. 40190
	S AND REPORTS ON WELLS		Lease Name or Unit Agreement
DIFFERENT RESERVOIR. USE "APPLICA"			HAZEN 1928 24
PROPOSALS.) 1. Type of Well: Oil Well 🕅 G	as Well Other	δ.	Well Number 01
2. Name of Operator WHITING OIL AND GAS CO	-	9.	OGRID Number
3. Address of Operator	KFOKATION		25078 D. Pool name or Wildcat
400 W ILLINOIS STE 1300 M	IDLAND, TEXAS 79701		RAVO DOME CARBON DIOXIDE GAS 64
4. Well Location		E	·····
	rom the <u>SOUTH</u> line and <u>1930</u> feet <u>N</u> Range <u>28E</u> NMPM Co	t from the WEST _	ine
	1. Elevation (Show whether DR, RK		
1	344' GR		
12. Check Appropriate Box to In	idicate Nature of Notice, Repo	ort or Other Data	
NOTICE OF INT	ENTION TO:	SUBSE	QUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON · 🔲 👘 🦷 RE	EMEDIAL WORK	
	_ /	OMMENCE DRILLI	
PULL OR ALTER CASING		ASING/CEMENT JO)B
OTHER:		Looption is read	for OCD increation offer DPA
		Location is read	y for OCD inspection after P&A
All pits have been remediated in c Rat hole and cellar have been fille	ompliance with OCD rules and the te	erms of the Operato	r's pit permit and closure plan.
🕅 Rat hole and cellar have been fille	ompliance with OCD rules and the te	erms of the Operato toles have been pro	r's pit permit and closure plan. perly abandoned.
 Rat hole and cellar have been fille A steel marker at least 4" in diame 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve	erms of the Operato toles have been pro I has been set in co	r's pit permit and closure plan. perly abandoned. ncrete. It shows the
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve E NAME, WELL NUMBER, API	erms of the Operato toles have been pro- l has been set in con NUMBER, QUAR	r's pit permit and closure plan. perly abandoned. ncrete. It shows the
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> INFORMATION	r's pit permit and closure plan. perly abandoned. ncrete. It shows the
 Rat hole and cellar have been fille A steel marker at least 4" in diame <u>OPERATOR NAME, LEAS</u> <u>UNIT LETTER, SECTION,</u> <u>PERMANENTLY STAMPE</u> 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> INFORMATION CE.	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> HAS BEEN WELDED OR
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as n 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve E NAME, WELL NUMBER, API TOWNSHIP, AND RANGE. All 1	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> INFORMATION CE.	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> HAS BEEN WELDED OR
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS <u>UNIT LETTER, SECTION,</u> <u>PERMANENTLY STAMPE</u> The location has been leveled as nother production equipment. Anchors, dead men, tie downs and 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All 1</u> <u>D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> <u>INFORMATION</u> <u>CE.</u> contour and has been feet below ground l	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> HAS BEEN WELDED OR n cleared of all junk, trash, flow lines evel.
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as n other production equipment. Anchors, dead men, tie downs and I f this is a one-well lease or last re 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery an-	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> <u>INFORMATION</u> <u>CE.</u> contour and has been feet below ground l d pit location(s) has	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. ye been remediated in compliance wi
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as n other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operator 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery an-	erms of the Operato toles have been pro- l has been set in con <u>NUMBER, QUAR</u> <u>INFORMATION</u> <u>CE.</u> contour and has been feet below ground l d pit location(s) has	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. ye been remediated in compliance wi
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as n other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operator rom lease and well location. 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery and or's pit permit and closure plan. All t	erms of the Operato toles have been pro- l has been set in con- <u>NUMBER, QUAR</u> <u>INFORMATION</u> <u>CE.</u> contour and has been feet below ground l d pit location(s) hav flow lines, producti	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> HAS BEEN WELDED OR n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS <u>UNIT LETTER, SECTION,</u> <u>PERMANENTLY STAMPE</u> The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I</u> <u>D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery and r's pit permit and closure plan. All the have been removed. Portable bases I	erms of the Operato toles have been pro- l has been set in con- NUMBER, QUAR INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> HAS BEEN WELDED OR n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS <u>UNIT LETTER, SECTION,</u> <u>PERMANENTLY STAMPE</u> The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery and r's pit permit and closure plan. All is have been removed. Portable bases I have been addressed as per OCD rule	erms of the Operato toles have been pro- l has been set in con- <u>NUMBER, QUAR</u> <u>INFORMATION 1</u> <u>CE.</u> contour and has been feet below ground 1 d pit location(s) have flow lines, producti have been removed es.	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns Pipelines and flow lines have been 	ompliance with OCD rules and the te d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery and r's pit permit and closure plan. All is have been removed. Portable bases I have been addressed as per OCD rule	erms of the Operato toles have been pro- l has been set in con- <u>NUMBER, QUAR</u> <u>INFORMATION 1</u> <u>CE.</u> contour and has been feet below ground 1 d pit location(s) have flow lines, producti have been removed es.	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/QUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS <u>UNIT LETTER, SECTION,</u> <u>PERMANENTLY STAMPE</u> The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns 	bompliance with OCD rules and the ter d and leveled. Cathodic protection h ter and at least 4' above ground leve E NAME, WELL NUMBER, API TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC early as possible to original ground c risers have been cut off at least two maining well on lease, the battery an- or's pit permit and closure plan. All is have been removed. Portable bases I have been addressed as per OCD rule abandoned in accordance with 19.15	erms of the Operato toles have been pro- l has been set in con- <u>NUMBER, QUAR</u> <u>INFORMATION 1</u> <u>CE.</u> contour and has been feet below ground 1 d pit location(s) hav flow lines, producti have been removed es. 5.35.10 NMAC. Al	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/OUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re . (Poured onsite concrete bases do no l fluids have been removed from nor
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns Pipetines and flow lines have been etrieved flow lines and pipelines. 	bompliance with OCD rules and the ter d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I</u> <u>D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two maining well on lease, the battery an- or's pit permit and closure plan. All is have been removed. Portable bases I have been addressed as per OCD rule abandoned in accordance with 19.15 maining well on lease: all electrical s	erms of the Operato toles have been pro- l has been set in con- <u>NUMBER, QUAR</u> <u>INFORMATION 1</u> <u>CE.</u> contour and has been feet below ground 1 d pit location(s) hav flow lines, producti have been removed es. 5.35.10 NMAC. Al	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/OUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow lines evel. we been remediated in compliance we on equipment and junk have been re . (Poured onsite concrete bases do no l fluids have been removed from nor
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns Pipelines and flow lines have been etrieved flow lines and pipelines. If this is a one-well lease or last re 	bompliance with OCD rules and the ter d and leveled. Cathodic protection h ter and at least 4' above ground leve E NAME, WELL NUMBER, API TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC early as possible to original ground c risers have been cut off at least two maining well on lease, the battery an- bor's pit permit and closure plan. All is have been removed. Portable bases I have been addressed as per OCD rule abandoned in accordance with 19.15 maining well on lease: all electrical s infrastructure.	erms of the Operato toles have been pro- l has been set in con- NUMBER, QUAR INFORMATION <u>INFORMATION</u> <u>CE.</u> contour and has been feet below ground l d pit location(s) hav flow lines, production have been removed es. 5.35.10 NMAC. All service poles and lin	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/OUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow line: evel. ve been remediated in compliance wi on equipment and junk have been re . (Poured onsite concrete bases do no l fluids have been removed from non tes have been removed from lease an
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re DCD rules and the terms of the Operatorion lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns Pipelines and flow lines have been etrieved flow lines and pipelines. If this is a one-well lease or last resonant of the location is a one-well lease or last resonant pipelines. 	bompliance with OCD rules and the ter d and leveled. Cathodic protection h ter and at least 4' above ground leve <u>E NAME, WELL NUMBER, API</u> <u>TOWNSHIP, AND RANGE. All I</u> <u>D ON THE MARKER'S SURFAC</u> early as possible to original ground c risers have been cut off at least two naining well on lease, the battery an- or's pit permit and closure plan. All the have been removed. Portable bases I have been addressed as per OCD rule abandoned in accordance with 19.15 maining well on lease: all electrical s infrastructure.	erms of the Operato toles have been pro- l has been set in con- NUMBER, QUAR INFORMATION <u>CE.</u> contour and has been feet below ground l d pit location(s) have flow lines, production have been removed es. 5.35.10 NMAC. All rervice poles and lire ict office to schedul	r's pit permit and closure plan. perly abandoned. ncrete. It shows the <u>TER/OUARTER LOCATION OI</u> <u>HAS BEEN WELDED OR</u> n cleared of all junk, trash, flow line: evel. ve been remediated in compliance wi on equipment and junk have been re . (Poured onsite concrete bases do no l fluids have been removed from non tes have been removed from lease an
 Rat hole and cellar have been fille A steel marker at least 4" in diame OPERATOR NAME, LEAS UNIT LETTER, SECTION, PERMANENTLY STAMPE The location has been leveled as nother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re Corrules and the terms of the Operatoriom lease and well location. All metal bolts and other materials o be removed.) All other environmental concerns Pipelines and flow lines have been etrieved flow lines and pipelines. If this is a one-well lease or last resocation, except for utility's distribution When all work has been completed, retuined GIGNATURE 	bompliance with OCD rules and the ter d and leveled. Cathodic protection h ter and at least 4' above ground leve E NAME, WELL NUMBER, API TOWNSHIP, AND RANGE. All I D ON THE MARKER'S SURFAC early as possible to original ground c risers have been cut off at least two maining well on lease, the battery an- or's pit permit and closure plan. All i have been removed. Portable bases I have been addressed as per OCD rule abandoned in accordance with 19.15 maining well on lease: all electrical s infrastructure. Im this form to the appropriate Distri-	erms of the Operato toles have been pro- l has been set in con- NUMBER, QUAR INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION INFORMATION S. 5.35.10 NMAC. All service poles and lim- ict office to schedul JLATORY SUPER	r's pit permit and closure plan. perly abandoned. Increte. It shows the ETER/OUARTER LOCATION OF HAS BEEN WELDED OR In cleared of all junk, trash, flow lines evel. We been remediated in compliance we on equipment and junk have been re on equipment and junk have been re (Poured onsite concrete bases do not fluids have been removed from not set have been removed from lease an le an inspection.

•

.

.

,

C_____)

•

on Heimann (North/South) road * (A)*

LOCATION, GOOL Lontour; god ANT; Connect PiA: Stundy