Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION	30-007-20681 SD-06-01
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Dia Danna Dd. Anton MA 67410	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 2008 JUL 25 PM 2 01	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM (UU) JUL 25 FII & UL 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	VPR D
1. Type of Well: Oil Well Gas Well Other Horizontal Multi Lateral	8. Well Number 303
2. Name of Operator	9. OGRID Number 180514
EL Paso E & P Company, L.P.	
3. Address of Operator	10. Pool name or Wildcat
PO BOX 190, RATON, NM 87740	
4. Well Location	
Unit Letter N: 405 feet from the South line and 1541 feet fr	rom theWestline
Section 35 Township 30N Range 17E NMPM Col	
	tax County
Lateral Bottom Hole Location: 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	v 1995 22, 1996 23.50, 23.50, 1997 23.50
Pit or Below-grade Tank Application □ or Closure □	
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	tance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUE	Report or Other Data SEQUENT REPORT OF:
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOF	Report or Other Data SEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORTH TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	Report or Other Data SEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	Report or Other Data SSEQUENT REPORT OF: RK
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTH COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: HO	Report or Other Data SEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: Ho 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTH COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: HO	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: Ho 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted operations. (See Rule 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted operations. (See Rule 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted operations. (See Rule 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted operations. (See Rule 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted operations.)	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface.	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or rec 06/04/06 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well.	Report or Other Data SSEQUENT REPORT OF: K
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 bbls of cement to surface. O6/04/06 Spud well. Drill 12 ¼" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. O6/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. O8/2006 Shut well in. Clean location. Close pit.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or rec 06/04/06 Spud well. Drill 12 ¼" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. 1 hereby certify that the information above is true and complete to the best of my knowledge.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: Obscribe proposed or completed operations. (Clearly state all pertinent details, and give pertinent date SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 bbls of cement to surface. O6/04/06 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. O6/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. O8/2006 Shut well in. Clean location. Close pit.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent data SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or rec 06/04/06 Spud well. Drill 12 ¼" hole to 303". Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. 08/2006 Shut well in. Clean location. Close pit.	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: Ho 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent data SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or rec 06/04/06 Spud well. Drill 12 ¼" hole to 303". Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. 08/2006 Shut well in. Clean location. Close pit. I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE Shully Multiple TITLE Regulatory A	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: Ho 1. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent data SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or rec 06/04/06 Spud well. Drill 12 ¼" hole to 303". Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. 06/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. 08/2006 Shut well in. Clean location. Close pit. I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE Shully Multiple TITLE Regulatory A	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFTEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: OTHER: How the second of the second	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFTEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompleted 8 bbls of cement to surface. Of/04/06 Spud well. Drill 12 1/4" hole to 303'. Run 9 5/8" casing. Mix and pump 140 sks Surface Blend cement. Circulated 8 bbls of cement to surface. Of/2006 Released Layne Western Rig and cancel project until further notice. Await Administrative decision on program and status of well. O8/2006 Shut well in. Clean location. Close pit. I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	Report or Other Data SSEQUENT REPORT OF: K
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFTEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENTOTHER: OTHER: How the second of the second	Report or Other Data SSEQUENT REPORT OF: K