

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 29404

QUESTIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	29404
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.		
Was or is this venting or flaring caused by an emergency or malfunction	Yes	
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.	
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under		
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes	
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	

Unregistered Facility Site	
Please provide the facility details, if the venting or flaring occurred or is occuring at a facility that does not have an Facility ID (f#) yet.	
Facility or Site Name	BELGIAN SHIRE CTB
Facility Type	Flare Stack - (FS)

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Facilities starting flaring due to compressor station ESD and batteries starting to flare. Once field tech got ESD valve reset and open batteries starting selling gas.

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	75	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	0	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Date(s) and Time(s)		
Date venting or flaring was discovered or commenced	05/30/2021	
Time venting or flaring was discovered or commenced	02:33 PM	
Is the venting or flaring event complete	Yes	
Date venting or flaring was terminated	05/30/2021	
Time venting or flaring was terminated	04:48 PM	
Total duration of venting or flaring in hours, if venting or flaring has terminated	2	
Longest duration of cumulative hours within any 24-hour period during this event	2	

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Gas Compressor Station Natural Gas Flared Spilled: 63 Mcf Recovered: 0 Mcf Lost: 63 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity		
Was or is this venting or flaring a result of downstream activity	Yes	
Date notified of downstream activity requiring this venting or flaring	Not answered.	
Time notified of downstream activity requiring this venting or flaring	Not answered.	

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	Big sinks compressor station ESD causing few facilities high line psi and flare. Date/time notified of downstream activity requiring this venting or flaring: was not notified
Steps taken to limit the duration and magnitude of venting or flaring	Field tech was called out to go and troubleshoot ESD event and possibly alarms at the compressor station.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Field tech had found an alarm on their end that caused the ESD event, clear alarm and facilities quit flaring.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 29404

CONDITIONS

Op	erator:	OGRID:
	DEVON ENERGY PRODUCTION COMPANY, LP	6137
	333 West Sheridan Ave.	Action Number:
	Oklahoma City, OK 73102	29404
		Action Type:
		[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	6/3/2021