



www.permianls.com  
575.397.3713 2609 W Marland Hobbs NM 88240

## C6+ Gas Analysis Report

|                     |                            |                            |                                          |
|---------------------|----------------------------|----------------------------|------------------------------------------|
| 11019G              | South Hobbs Unit CTB Inlet | South Hobbs Unit CTB Inlet |                                          |
| Sample Point Code   | Sample Point Name          | Sample Point Location      |                                          |
| Laboratory Services | 2020036993                 | 1719                       | D Armstrong - Spot                       |
| Source Laboratory   | Lab File No                | Container Identity         | Sampler                                  |
| USA                 | USA                        | USA                        | New Mexico                               |
| District            | Area Name                  | Field Name                 | Facility Name                            |
| Nov 24, 2020 09:58  | Nov 24, 2020 09:58         | Nov 24, 2020 11:59         | Nov 24, 2020                             |
| Date Sampled        | Date Effective             | Date Received              | Date Reported                            |
| 60.00               | Torrance                   | 38 @ 70                    |                                          |
| Ambient Temp (°F)   | Flow Rate (Mcf)            | Analyst                    | Press PSI @ Temp °F<br>Source Conditions |
| Oxy                 |                            | NG                         |                                          |
| Operator            |                            | Lab Source Description     |                                          |

| Component          | Normalized Mol % | Un-Normalized Mol % | GPM    |
|--------------------|------------------|---------------------|--------|
| H2S (H2S)          | 0.0000           | 0                   |        |
| Nitrogen (N2)      | 0.1080           | 0.10806             |        |
| CO2 (CO2)          | 85.2310          | 85.23111            |        |
| Methane (C1)       | 0.6730           | 0.67276             |        |
| Ethane (C2)        | 0.6140           | 0.61395             | 0.1640 |
| Propane (C3)       | 3.9190           | 3.91938             | 1.0790 |
| I-Butane (IC4)     | 1.7080           | 1.70793             | 0.5590 |
| N-Butane (NC4)     | 4.2350           | 4.23453             | 1.3350 |
| I-Pentane (IC5)    | 1.4540           | 1.45438             | 0.5320 |
| N-Pentane (NC5)    | 0.9800           | 0.98005             | 0.3550 |
| Hexanes Plus (C6+) | 1.0780           | 1.07784             | 0.4680 |
| TOTAL              | 100.0000         | 100.0000            | 4.4920 |

Method(s): Gas C6+ - GPA 2261, Extended Gas - GPA 2286, Calculations - GPA 2172

| Analyzer Information |                   |                |              |
|----------------------|-------------------|----------------|--------------|
| Device Type:         | Gas Chromatograph | Device Make:   | Shimadzu     |
| Device Model:        | GC-2014           | Last Cal Date: | Nov 24, 2020 |

| Gross Heating Values (Real, BTU/ft³) |           |                      |           |
|--------------------------------------|-----------|----------------------|-----------|
| 14.696 PSI @ 60.00 °F                |           | 14.73 PSI @ 60.00 °F |           |
| Dry                                  | Saturated | Dry                  | Saturated |
| 464.3                                | 457.3     | 465.4                | 458.4     |

| Calculated Total Sample Properties            |                        |
|-----------------------------------------------|------------------------|
| GPA2145-16 *Calculated at Contract Conditions |                        |
| Relative Density Real                         | Relative Density Ideal |
| 1.5926                                        | 1.5805                 |
| Molecular Weight                              |                        |
| 45.7756                                       |                        |

| C6+ Group Properties |              |              |
|----------------------|--------------|--------------|
| Assumed Composition  |              |              |
| C6 - 60.000%         | C7 - 30.000% | C8 - 10.000% |

|           |
|-----------|
| Field H2S |
| 0 PPM     |

## PROTREND STATUS:

Passed By Validator on Nov 24, 2020

## DATA SOURCE:

Imported

## PASSED BY VALIDATOR REASON:

First sample taken @ this point, composition looks reasonable

## VALIDATOR:

Torrance Galvan

## VALIDATOR COMMENTS:

OK

**UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM****Facility:** South Hobbs CTB**Flare Date:** 03/20/2022**Duration of event:** 44 Minutes**MCF Flared:** 186**Start Time:** 11:46 AM**End Time:** 12:30 PM**Cause:** Compression Equipment Shut down > Vibration Switch Tripped**Method of Flared Gas Measurement:** Gas Flare Meter**Comments:** This upset event was not caused by any wells associated with the facility

- 
- Reason why this event was beyond Operator's control:** The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements. Internal OXY compression equipment failure procedures ensure that upon a compressor unit shutdown, a production tech is promptly notified and is instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Upon arrival, production tech must assess whether compressor shutdown is due to damage and repair is needed, or whether there are other reasons.

.In this case, this emissions event was caused by compressor unit LP 4500 malfunctioning due to the compressor unit having false alarm readings, caused by a faulty transmitter and therefore, automatically shutting the unit down. Automation tech called out to troubleshoot and make necessary adjustments and/or repairs. Automation tech arrived on-site and troubleshooted the unit. Restarted the unit and the unit was placed back on-line and returned to normal working service. This event was completely out of OXY's control to prevent from occurring but OXY made every effort to control and minimize excess emissions while OXY production techs resolved the issues. Notwithstanding compressor design and operation, compressors are inherently dynamic and alarm triggers, whether true or false, can cause compressors to malfunction and shutdown with warning or advance notice.
  - Steps Taken to limit duration and magnitude of venting or flaring:** It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. In this case, the steps taken to limit duration and magnitude of flaring was for Oxy production techs to quickly respond to the compressor alarm, diagnose the issue, and make the necessary calls to seek additional assistance. By working together, Oxy technicians were able to troubleshoot the issue and restart the unit back to normal working service.

3. **Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:** The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. The only actions that Oxy can take and handle that is within its control, is to continue with its compression equipment preventative maintenance program for this facility's compression equipment. In this particular event a New Employee is being trained on this Unit and was not aware of the condition of the oil level. Oxy trains employee on how to Monitor the oil levels and prevent these types of shut down

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS  
  
Action 92143

DEFINITIONS

|                                                                               |                                                        |
|-------------------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                       |
|                                                                               | Action Number:<br>92143                                |
|                                                                               | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none"><li>• this application's operator, hereinafter "this operator";</li><li>• venting and/or flaring, hereinafter "vent or flare";</li><li>• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";</li><li>• the statements in (and/or attached to) this, hereinafter "the statements in this";</li><li>• and the past tense will be used in lieu of mixed past/present tense questions and statements.</li></ul> |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 92143

**QUESTIONS**

|                                                                               |                                                        |
|-------------------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                       |
|                                                                               | Action Number:<br>92143                                |
|                                                                               | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

**QUESTIONS**

|                                                                                                                                                                           |                                       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|
| <b>Prerequisites</b>                                                                                                                                                      |                                       |
| <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i> |                                       |
| Incident Well                                                                                                                                                             | Not answered.                         |
| Incident Facility                                                                                                                                                         | [fJXK1520829861] South Hobbs Unit CTB |

|                                                                                                                                                                                                                                                                                            |                                                   |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|
| <b>Determination of Reporting Requirements</b>                                                                                                                                                                                                                                             |                                                   |
| <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>                                                                                                                                                 |                                                   |
| Was this vent or flare caused by an emergency or malfunction                                                                                                                                                                                                                               | Yes                                               |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event                                                                                                                                                                                 | No                                                |
| Is this considered a submission for a vent or flare event                                                                                                                                                                                                                                  | Yes, minor venting and/or flaring of natural gas. |
| <i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i>                                                                                     |                                                   |
| Was there <b>at least 50 MCF</b> of natural gas vented and/or flared during this event                                                                                                                                                                                                     | Yes                                               |
| Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No                                                |
| Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence                                                                                                             | No                                                |

|                                                           |                                                            |
|-----------------------------------------------------------|------------------------------------------------------------|
| <b>Equipment Involved</b>                                 |                                                            |
| Primary Equipment Involved                                | Other (Specify)                                            |
| Additional details for Equipment Involved. Please specify | Compression Equipment Shut down > Vibration Switch Tripped |

|                                                                                                                                      |               |
|--------------------------------------------------------------------------------------------------------------------------------------|---------------|
| <b>Representative Compositional Analysis of Vented or Flared Natural Gas</b>                                                         |               |
| <i>Please provide the mole percent for the percentage questions in this group.</i>                                                   |               |
| Methane (CH4) percentage                                                                                                             | 1             |
| Nitrogen (N2) percentage, if greater than one percent                                                                                | 0             |
| Hydrogen Sulfide (H2S) PPM, rounded up                                                                                               | 0             |
| Carbon Dioxide (CO2) percentage, if greater than one percent                                                                         | 85            |
| Oxygen (O2) percentage, if greater than one percent                                                                                  | 0             |
| <i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i> |               |
| Methane (CH4) percentage quality requirement                                                                                         | Not answered. |
| Nitrogen (N2) percentage quality requirement                                                                                         | Not answered. |
| Hydrogen Sulfide (H2S) PPM quality requirement                                                                                       | Not answered. |
| Carbon Dioxide (CO2) percentage quality requirement                                                                                  | Not answered. |
| Oxygen (O2) percentage quality requirement                                                                                           | Not answered. |

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 92143

QUESTIONS (continued)

|                                                                               |                                                        |
|-------------------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                       |
|                                                                               | Action Number:<br>92143                                |
|                                                                               | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| Date(s) and Time(s)                            |            |
|------------------------------------------------|------------|
| Date vent or flare was discovered or commenced | 03/20/2022 |
| Time vent or flare was discovered or commenced | 11:46 AM   |
| Time vent or flare was terminated              | 12:30 PM   |
| Cumulative hours during this event             | 1          |

| Measured or Estimated Volume of Vented or Flared Natural Gas              |                                                                                                              |
|---------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
| Natural Gas Vented (Mcf) Details                                          | Not answered.                                                                                                |
| Natural Gas Flared (Mcf) Details                                          | Cause: Other   Other (Specify)   Natural Gas Flared   Released: 186 Mcf   Recovered: 0 Mcf   Lost: 186 Mcf ] |
| Other Released Details                                                    | Not answered.                                                                                                |
| Additional details for Measured or Estimated Volume(s). Please specify    | Not answered.                                                                                                |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report.                                   |

| Venting or Flaring Resulting from Downstream Activity             |               |
|-------------------------------------------------------------------|---------------|
| Was this vent or flare a result of downstream activity            | No            |
| Was notification of downstream activity received by this operator | Not answered. |
| Downstream OGRID that should have notified this operator          | Not answered. |
| Date notified of downstream activity requiring this vent or flare | Not answered. |
| Time notified of downstream activity requiring this vent or flare | Not answered. |

| Steps and Actions to Prevent Waste                                                                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| Please explain reason for why this event was beyond this operator's control                                                      | The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. The flare is regularly monitored to the ensure flame is lit and meeting opacity requirements. Internal OXY compression equipment failure procedures ensure that upon a compressor unit shutdown, a production tech is promptly notified and is instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Upon arrival, production tech must assess whether compressor shutdown is due to damage and repair is needed, or whether there are other reasons. .In this case, this emissions event was caused by compressor unit LP 4500 malfunctioning due to the compressor unit having false alarm readings, caused by a faulty transmitter and therefore, automatically shutting the unit down. Automation tech called out to troubleshoot and make necessary adjustments and/or repairs. Automation tech arrived on-site and troubleshot the unit. Restarted the unit and the unit was placed back on-line and returned to normal working service. This event was completely out of OXY's control to prevent from occurring but OXY made every effort to control and minimize excess emissions while OXY production techs resolved the issues. Notwithstanding compressor design and operation, compressors are inherently dynamic and alarm triggers, whether true or false, can cause compressors to malfunction and shutdown with warning or advance notice. |
| Steps taken to limit the duration and magnitude of vent or flare                                                                 | It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. In this case, the steps taken to limit duration and magnitude of flaring was for Oxy production techs to quickly respond to the compressor alarm, diagnose the issue, and make the necessary calls to seek additional assistance. By working together, Oxy technicians were able to troubleshoot the issue and restart the unit back to normal working service                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| Corrective actions taken to eliminate the cause and reoccurrence of vent or flare                                                | The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. It is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, in order to minimize emissions as much as possible. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. The only actions that Oxy can take and handle that is within its control, is to continue with its compression equipment preventative maintenance program for this facility's compression equipment. In this particular event a New Employee is being trained on this Unit and was not aware of the condition of the oil level. Oxy trains employee on how to Monitor the oil levels and prevent these types of shut down                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |

**District I**

1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 92143

**ACKNOWLEDGMENTS**

|                                                                               |                                                        |
|-------------------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                       |
|                                                                               | Action Number:<br>92143                                |
|                                                                               | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

**ACKNOWLEDGMENTS**

|                                     |                                                                                                                                                                                                                                                                                                                           |
|-------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> | I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.                                                                                      |
| <input checked="" type="checkbox"/> | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| <input checked="" type="checkbox"/> | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.                                                                                                        |
| <input checked="" type="checkbox"/> | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.                       |
| <input checked="" type="checkbox"/> | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.                                                                                                                          |

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 92143

CONDITIONS

|                                                                               |                                                        |
|-------------------------------------------------------------------------------|--------------------------------------------------------|
| Operator:<br>OCCIDENTAL PERMIAN LTD<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>157984                                       |
|                                                                               | Action Number:<br>92143                                |
|                                                                               | Action Type:<br>[C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition                                                                                                                                                                          | Condition Date |
|------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| srojas     | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 3/22/2022      |