TRANSACTION REPORT

MAY-21-2004 FRI 04:13 PM

FOR:

¥									
* * *	DATE	START	RECE I VER	TX TIME	PAGES	TYPE	NOTE		M# DP
* *	MAY-21	04:13 P	M 915055648656	33"	2	SEND	OK		374
*— *					ΤΩΤΔ	T .	22C DACEC:	2	
*					TOTA	լ :	33S PAGES:	2	



TRANSMITTAL COVER SHEET

OIL CONSERVATION DIVISION 1220 S. ST. FRANCIS DRIVE SANTA FE, NM 87505 (505) 476-3440 (505)476-3462 (Fax)

PLEASE	DRY	TV/IZD	TUTO	EAV.
TUENDE		AV DR	1 1112	HAX


TO:

FROM:

Mike Pippin Michael Stogner

DATE:

5-21-2004



TRANSMITTAL COVER SHEET

OIL CONSERVATION DIVISION 1220 S. ST. FRANCIS DRIVE (505) 476-3440 (505)476-3462 (Fax)

PLEASE DE	LIVER THIS FAX:
го:	Mike Pippin
FROM:	Michael Stogner
DATE:	5-21-2004
PAGES:	
SUBJECT:	Montoya 25 #3

Stogner, Michael

From:

Stogner, Michael

Sent:

Friday, May 21, 2004 3:48 PM

To: Cc: Mike Pippin (E-mail) Hayden, Steven

Subject:

Proposed Montoya 25 Well No. 3

I am reviewing your application for an unorthodox infill coal gas well location in the SE/4 of Sec. 25-T32N-R13W, San Juan County, and I have a few questions.

- (1) How much surface in the SE/4 of Sec. 25 does Mr. Montoya own?
- (2) From my review of the information provided in your application and aerial photos of the area, there appears to be numerous locations considered to be standard within the E/2 SE/4 of Sec. 25 to relocate this well?
- (3) Why can't this well be twined on one of the existing well pads located within the SE/4 of Sec. 25:
 - (a) XTO Energy, Inc.'s Montoya Com. Well No. 1A (API No. 30-045-24994), located 1190' FSL & 990' FEL (Unit P) of Sec. 25; or
 - (b) XTO Energy, Inc.'s Montoya Com. Well No. 1C (API No. 30-045-30374), located 1805' FSL & 1950' FEL (Unit J) of Sec. 25?

Stogner, Michael

From:

MAILER-DAEMON@messagelabs.com

Sent:

Friday, May 21, 2004 3:49 PM MSTOGNER@state.nm.us

Subject:

failure notice

This is the mail delivery agent at messagelabs.com.

I was not able to deliver your message to the following addresses.

<mpippin@ddroadband.net>:

Sorry, I couldn't find any host named ddroadband.net. (#5.1.2)

--- Below this line is a copy of the message.

Return-Path: <MSTOGNER@state.nm.us>

X-VirusChecked: Checked

X-Env-Sender: MSTOGNER@state.nm.us

X-Msg-Ref: server-14.tower-64.messagelabs.com!1085176109!4736375

X-StarScan-Version: 5.2.11; banners=state.nm.us,-,-

X-Originating-IP: [164.64.5.6]

Received: (qmail 6624 invoked from network); 21 May 2004 21:48:29 -0000 Received: from xconnect.state.nm.us (HELO xconnect.gsd.nm.gov) (164.64.5.6) by server-14.tower-64.messagelabs.com with SMTP; 21 May 2004 21:48:29 -0000

Received: by xconnect.gsd.nm.gov with Internet Mail Service (5.5.2653.19)

id <L2K7X2Y3>; Fri, 21 May 2004 15:48:29 -0600

Message-ID: <DB33FA3F0FC6584E882D0CE6297AF0F94F7BD2@nmemnrddept.prod.emnrd.nm.gov>

From: "Stogner, Michael" <MSTOGNER@state.nm.us>

To: "Mike Pippin (E-mail)" <mpippin@ddroadband.net>

Cc: "Hayden, Steven" <SHAYDEN@state.nm.us>

Subject: Proposed Montoya 25 Well No. 3

Date: Fri, 21 May 2004 15:48:28 -0600

MIME-Version: 1.0

X-Mailer: Internet Mail Service (5.5.2653.19)

I am reviewing your application for an unorthodox infill coal gas well location in the SE/4 of Sec. 25-T32N-R13W, San Juan County, and I have a few questions.

- (1) How much surface in the SE/4 of Sec. 25 does Mr. Montoya own?
- (2) From my review of the information provided in your application and aerial photos of the area, there appears to be numerous locations considered to be standard within the E/2 SE/4 of Sec. 25 to relocate this well?
- (3) Why can't this well be twined on one of the existing well pads located within the SE/4 of Sec. 25:
- (a) XTO Energy, Inc.'s Montoya Com. Well No. 1A (API No. 30-045-24994), located 1190' FSL & 990' FEL (Unit P) of Sec. 25; or (b) XTO Energy, Inc.'s Montoya Com. Well No. 1C (API No. 30-045-30374), located 1805' FSL & 1950' FEL (Unit J) of Sec. 25?

Confidentiality Notice: This e-mail, including all attachments is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited unless specifically provided under the New Mexico Inspection of Public Records Act. If you are not the intended recipient, please contact the sender and destroy all copies of this message. -- This email has been scanned by the MessageLabs Email Security System.